

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 31 Jan 2019

Preliminary Advice

Insured Vehicle No	: SFH9090S	Accident Date	: 26/01/2019
TP Vehicle No	: SHC8919L	Assignment Date	: 30/01/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 12.00
Date of Inspection	: 29/01/2019		
Inspection At	: SOON HOCK AUTOMOTIVE (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AUTOPOINT #01-06 S(568047) SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	39,976.42
Revised Amount	:S\$	23,924.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	23,924.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.