

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19001981/R1TD3S2**Date:** 12/02/2019REFERENCE

Insured/Claimant:	YEO CHING SOON	Policy No:	PNPV2018-00015521	
Date of Loss:	25/01/2019	Nature of Claim:	OD	Claim No: 1201900003449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ1431C		
Make & Model:	TOYOTA PREMIO, 1.8 (A)	Engine No:	2ZR4169655
Reg. Date:	25/11/2008 (Man. Year: 2008)	Chassis No:	ZRT2603040612
Colour:	Silver	Odometer:	0 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	S\$45,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Poor	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	30,000.00	0.00	30,000.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	30,000.00	0.00	30,000.00	100.00
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	29,400.00	-600.00	30,000.00	102.04
+ GST 7.00/7.00% (\$\$)	2,058.00	-42.00	2,100.00	102.04
Nett Amount (\$\$)	31,458.00	-642.00	32,100.00	102.04

INSPECTION

Date of Assignment: 29/01/2019

Date Inspected: 31/01/2019 Inspected At:

Automotive Repair Centre Pte Ltd (HQ)
38 Woodlands Industrial Park E1, #05-18
Singapore 757700

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$45,000.00
OMV :	\$22,336.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$32,121.00
COE Rebate (2) :	\$31,523.00
Total Rebate (1) + (2) = :	\$31,523.00

The total amount incurred will be Market Value \$45,000.00 minus Total Rebate \$31,523.00 = \$13,477.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2019)
Parts:	143	TOYOTA PREMIO 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ1431C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	30,000.00	0.00
Gross Labour Cost (\$\$)			30,000.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >