



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

III Insured's Veh No : SHC8935P
Date of Accident : 28 January 2019

Miss Khoo Mei Hua

Date : 29 January 2019

Estimate To Repair SLB8103G - Honda VEZEL 1.5X CVT
Chassis No : L15B4029624

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper DIS/Toa ✓	\$ 0.00
02	1 pc	front bumper reinforcement 11 X	\$ 0.00
03	1 pc	n/s front bumper side retainer sel ✓	\$ 0.00
04	10 ps	front bumper clip @ \$.00 rer ✓	\$ 0.00
05	1 pc	n/s front bumper fog lamp garnish good ✓	\$ 0.00
06	1 pc	front bumper lower lip good ✓	\$ 0.00
07	1 pc	front bumper lower splashield 11 X	\$ 0.00
08	1 pc	n/s headlamp	\$ 0.00
09	1 pc	n/s headlamp lower bracket 11 X	\$ 0.00
10	1 pc	n/s front fender 11/2uc ✓	\$ 0.00
11	1 pc	n/s front fender wheel arch garnish Toa ✓	\$ 0.00
12	1 pc	n/s front fender inner cowling 11 X	\$ 0.00
13	6 ps	n/s front fender inner cowling clip @ \$.00 rer ✓	\$ 0.00
14	1 pc	n/s front shock absorber Bul ✓	\$ 0.00
15	1 pc	n/s front lower arm Buc ✓	\$ 0.00
16	1 pc	n/s front stabilier link Buc X	\$ 0.00
17	1 pc	n/s front knuckle arm Bul ✓	\$ 0.00
18	1 pc	n/s front wheel hub with bearing 11 ✓	\$ 0.00
Less 20 %			\$ 0.00
			\$ 0.00
<u>SPECIAL NETT ITEMS</u>			
19	1 pc	n/s front tyre 8vc X	\$ 0.00
			\$ 0.00
<u>LABOUR & MISC. CHARGES</u>			
01		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 180.00
02		To check electrical lighting concerned.	\$ 50.00
03		To rust-proofing of the affected areas.	\$ 80.00
04		To check steering geometry and computer wheel alignment.	\$ 80.00
05		To transfer of tyre, rim and on wheel balancing.	\$ 80.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00

not added
Lian
2/5/19
3-4 day.

to the ph. of the paper
30/1/19

Rev: LKK - Marcus
30/1/19 0950

50
20
30
60
X
300



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

III Insured's Veh No : SHC8935P

Date of Accident : 28 January 2019

Miss Khoo Mei Hua

Date : 29 January 2019

Estimate To Repair SLB8103G - Honda VEZEL 1.5X CVT

Chassis No : L15B4029624

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u> Putty and spray painting of the affected portion.	\$ 900.00
			\$ 2,170.00
		Total	\$ 2,170.00

600

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: