

INS. CASE OWNER:

CC3 / AXA1600

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Nature of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time: 26/06/16

Sent By: JB

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

4,543.92

(3 days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

2A

If NO or B 28, Ass. Lia:

Repair Cost:

SS

(OLD REJECTED OUT)

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(5

x

days)

Loss of Income (LOI):

SS

(5

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

WP REPORT

4260.00

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF: AAKenneth**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1-A. 1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8140 999613 Yr Regn: 061 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995Colour: n. white 1st A/C: Insured / Std / NI / NASp. Reading: 188454 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL 15AUC 278150Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken

Front

Rear

R/Bal. 9 mm R/Bal. 7 mmL/Bal. 9 mm L/Bal. 7 mmD.O.A. 20/5/16 D.O.I. 23/5/16

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/5 84543-92 Panelin 1st pass to Cotinine

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC3/AXA16009524/Khg3		
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 24-05-2016		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKR 7686A	Veh. Inspected	SHD 9996B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	24/05/2016	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/05/2016	Inspection Date	23/05/2016	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 26 May 2016

Preliminary Advice

Insured Vehicle No	: SKR7686A	Accident Date	: 20/05/2016
TP Vehicle No	: SHD9996B	Assignment Date	: 25/05/2016
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 3 /Days
Date of Inspection	: 23/05/2016		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S Rear Body... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,093.45
Revised Amount	:S\$	4,543.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,543.92

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

TRANS-CAB AUTO SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6281 1400

Co./GST Reg. No. 201019686G

Not Authorised
1-B-1
B4543-92
Resuming B4 paint

Vehicle No.:	SHD 9996B
Chassis No.:	VF1ABL15AUC278150
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	20.5.2016
Third Party Insurer :	AXA

PART		LIST	
1	1	BUMPER COVER REAR	\$ 852.66
2	1	BUMPER LOWER REAR	\$ 591.41
3	1	BUMPER BRACKET CTR REAR	\$ 87.29
4	1	BUMEPB BRACKET SIDE LH REAR	\$ 104.59
5	1	BUMEPB RETAINER LH REAR	\$ 34.61
6	1	BUMPER REFLECTOR LH	\$ 33.55
7	1	FENDER PANEL REAR LH	\$ 2,537.80
8	1	FENDER WHEELARCH REAR LH	\$ 418.06
9	1	TAILLAMP LH	\$ 425.04
10	1	ROCKER PANEL OUTER LH	\$ 759.61
11	1	DOOR REAR LH	\$ 2,188.20
12	1	DOOR WEATHERSTRIP REAR LH L70Y	\$ 304.23
13	1	DOOR PANEL FRT RH L70Y	\$ 1,823.50
14	1	DOOR WEATHERSTRIP FRT LH L70Y	\$ 304.23
15	1	DOOR MIRROR RH L70Y	\$ 950.90
16	1	DOOR MIRROR GLASS RH L70Y	\$ 155.34
17	1	DOOR MIRROR BACK COVER RH L70Y	\$ 140.04
18	1	DOOR MIRROR COVER INNER FRT RH L70Y	\$ 60.97
19	1	DOOR MIRROR LAMP RH L70Y	\$ 124.48

TOTAL	\$	11,896.50
10%	\$	1,189.65
	\$	10,706.85

Special Nett

1	1SET	PARKING AID	\$ 600.00
2	1SET	REAR BUMPER CLIP	\$ 66.00
3	1	RIM (ROUE 7J 16H 2547)RH RR	\$ 385.00
4	1	TYRE RH RR	\$ 330.00
5	1	CAP HUB RH REAR	\$ 35.60
6	1	DOOR STICKER "6555-3333"	\$ 80.00
7	1	DOOR STICKER "TRANS-CAB"	\$ 120.00

TOTAL	\$	1,616.60
-------	----	----------

TOTAL PARTS	\$	12,323.45
-------------	----	-----------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	3,600.00	<i>5001</i>
----	----------	-------------

Putty And Spray Painting Of The Affected Portion.

\$	3,600.00	<i>8801</i>
----	----------	-------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>301</i>
----	--------	------------

TRANS-CAB AUTO SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6281 1400

Co./GST Reg. No. 201019686G

To reinstall rear bumper parking sensor.	\$	170.00	601
To remove and replace corporate sticker	\$	nn 330.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	✓
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	340.00	601
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	601
TOTAL	\$	8,770.00	
Grand Total	\$	21,093.45	

Repair Days

3 days - 10 Days
(PARTS BY PARTS)**LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

20 JULY 2016

**RACHHPAL SINGH
61 JALAN LIMAU KASTURI
SINGAPORE 468447**

Dear Sir/Madam,

**OUR REF : CC3/AXA16009524/Khg3
YOUR REF : SKR 7686A
ACCIDENT INVOLVING SKR 7686A AND SHD 9996B ALONG JALAN LIMAU
KASTURI ON 20.05.2016**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s TRANS-CAB AUTO SERVICES PTE LTD, acting on behalf of the owner of SHD 9996B against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SHD 9996B. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Syaf
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Singapore Pte Ltd (AXA)
(Motor Claims Dept)

Print Sent Message

This mail is associated with :

***SHD9996B (C0384994)**
[SKR7686A]
 TP
 TRANS-CAB SERVICES PTE LTD
 May 20 2016 1:00PM
 [RACHHPAL SINGH S/O NOOP SINGH]
 Trans-cab Auto Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 02/01/2018 09:41 AM.
To AXA_CynthiaLoh
CC AXA_SG; vicalpeh@lkkauto.com; admin-a@lkkauto.com
Subject Re: TP settlement - C0384994/GA089526

Dear Cynthia,

We refer to the subject of this e-mail. We have inspected TP vehicle on 23.05.2016

TP claim file has been dormant for more than one(1) year.

Third-party claimant is inactive in this particular case file.

There is no follow-up, response or further action from them since inspection date.

In view of no further development from TP's side, we will temporarily close file and will submit our WP report to your good-office.

In future, if TP will pursue their claim, we will notify you for our further handling.

Thank you.

Regards,
 Joy Irene
 Case Handler
 LKK Auto Consultants Pte Ltd
 DID: 6749 5792

<-- Original Message -->

From: AXA_SG
To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com
Sent On: 21/07/2017 04:28 PM
Subject: Re: TP settlement - C0384994/GA089526



AXA INSURANCE PTE LTD
 4 Shenton Way, #24-01 AXA Tower
 Singapore 068811
 Customer Service 400-01
 100 0000 0000
 100 0000 0000
 www.axa.com.sg
 GST Reg No: L000000000
 U.S. Reg No: L000000000

Dear LKK,

Please expedite D/S.

Thanks & Regards,
 Cynthia Loh
 <-- Original Message -->
From: AXA_SG
To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com
CC: AXA_SG

Sent On: 07/06/2016 11:12 AM

Subject: TP settlement - C0384994/GA089526

Dear KENNETH KONG,

Please proceed for direct settlement if damages consistent.

Regards,
Ong Li Li

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2016		25 May 2016 11:39 Edit Adj Rpt	S\$4,543.92 Edit Estimates	S\$4,543.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	RACHHPAL SINGH S/O NOOP SINGH, ID: S1767307F, Tel: +6597332439		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD9996B	Date of Loss:	20/05/2016 13:00 - :59
Claim Type:	TP / C0384994	Policy/Cover Note No.:	GA089526 (Comprehensive)
Vehicle Reg. No. (Insured):	SKR7686A	Policy No. (Claimant):	VPX/P1680520
		Excess:	S\$0.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/06/2016]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AXA_SG (21/07/2017): Re: TP settlement - C0384994/GA089526
- AXA_SG (07/06/2016): Re: Direct Settlement - Accident Involving SKR7686A (OI : AXA - C0384994) and SH...
- AXA_SG (07/06/2016): TP settlement - C0384994/GA089526
- AXA_SG (25/05/2016): WP / New TP Assignment - C0384994/GA089526

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD9996B (C0384994)**
[SKR7686A]
TP
TRANS-CAB SERVICES PTE LTD
May 20 2016 1:00PM
[RACHHPAL SINGH S/O NOOP SINGH]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser	
Assessment Reports		1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail Print
1	07/06/16 11:09	Accident Statement <small>From: SC - Reg. No: SKR7686A, Claimant: RACHHPAL SINGH</small>	 Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	26/05/16 09:43	Adjuster Immediate Advice	 Load HTM
Photos/Images		3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	26/05/16 09:44	LKKPhotosInspection	 Load PDF
2	02/01/18 16:59	LKK REINSPECTION PHOTOS	 Load PDF
Documentation		1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail Print
1	25/05/16 10:32	EMAIL_ABS	 Load PDF
2	25/05/16 10:32	ESTIMATE_ABS	 Load PDF
3	25/05/16 10:32	TP GIA REPORT_ABS	 Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	19/07/16 15:50	LETTER TO OI	 Load PDF
2	02/01/18 09:43	EMAIL TO WP REPORT	 Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid #ccc; height: 40px; margin-top: 5px;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AXA16009524/KHB3Q2

Date: 10/01/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA089526

Claimant Vehicle No: SHD9996B

Insured Vehicle No:

SKR7686A

Date of Loss: 20/05/2016

Nature of Claim:

TP

Claim No: C0384994

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD9996B

Make & Model:

RENAULT LATITUDE, 2.0 CVT ABS (A)

Engine No:

M9R8839C001430

Reg. Date:

13/06/2014 (Man. Year: 2014)

Chassis No:

VF1ABL15AUC278150

Colour:

Metallic White/Red

Odometer:

188454 km

Engine Capacity:

1995 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side:

Falken 9 mm

Rear Left Side:

Falken 7 mm

Front Right Side:

Falken 9 mm

Rear Right Side:

Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,323.46	2,953.92	9,369.54	76.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,770.00	1,590.00	7,180.00	81.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,093.46	4,543.92	16,549.54	78.46
+ GST 7.00/7.00% (S\$)	1,476.54	318.07	1,158.47	78.46
Nett Amount (S\$)	22,570.00	4,861.99	17,708.01	78.46

INSPECTION

Date of Assignment: 25/05/2016

Date Inspected: 23/05/2016 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2018)
Parts: 143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9996B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR (CONSISTENT)	Buckled	852.66 FL	*852.66 FL
2	1		*BUMPER LOWER REAR (CONSISTENT)	Serviceable	591.41 FL	*- FL
3	1		*BUMPER BRACKET CTR REAR (CONSISTENT)	Serviceable	87.29 FL	*- FL
4	1		*BUMPER BRACKET SIDE LH REAR (CONSISTENT)	Serviceable	104.59 FL	*- FL
5	1		*BUMPER RETAINER LH REAR (CONSISTENT)	Distorted	34.61 FL	*34.61 FL
6	1		*BUMPER REFLECTOR LH (CONSISTENT)	Serviceable	33.55 FL	*- FL
7	1		*FENDER PANEL REAR LH (CONSISTENT)	Repair	2,537.80 FL	*- FL
8	1		*FENDER WHEELARCH REAR LH (CONSISTENT)	Serviceable	418.06 FL	*- FL
9	1		*TAILLAMP LH (CONSISTENT)	Serviceable	425.04 FL	*- FL
10	1		*ROCKER PANEL OUTER LH (CONSISTENT)	Repair	759.61 FL	*- FL
11	1		*DOOR REAR LH (CONSISTENT)	Bent / Warped	2,188.20 FL	*2,188.20 FL
12	1		*DOOR WEATHERSTRIP REAR LH L70Y (CONSISTENT)	Serviceable	304.23 FL	*- FL
13	1		*DOOR PANEL FRT RH L70Y (CONSISTENT)	Repair	1,823.50 FL	*- FL
14	1		*DOOR WEATHERSTRIP FRT LH L70Y (CONSISTENT)	Serviceable	304.23 FL	*- FL
15	1		*DOOR MIRROR RH L70Y (CONSISTENT)	Serviceable	950.90 FL	*- FL
16	1		*DOOR MIRROR GLASS RH L70Y (CONSISTENT)	Serviceable	155.34 FL	*- FL
17	1		*DOOR MIRROR BACK COVER RH L70Y (CONSISTENT)	Serviceable	140.04 FL	*- FL
18	1		*DOOR MIRROR COVER INNER FRT RH L70Y (CONSISTENT)	Serviceable	60.97 FL	*- FL
19	1		*DOOR MIRROR LAMP RH L70Y (CONSISTENT)	Serviceable	124.48 FL	*- FL
20	1		*SET PARKING AID (CONSISTENT)	Serviceable	600.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
22	1		*RIM (ROUE 7J 16H 2547) RH RR (CONSISTENT)	Serviceable	385.00 FS	*- FS
23	1		*TYRE RH RR (CONSISTENT)	Serviceable	330.00 FS	*- FS
24	1		*CAP HUB RH REAR (CONSISTENT)	Serviceable	35.60 FS	*- FS
25	1		*DOOR STICKER 6555-3333 (CONSISTENT)	Necessary	80.00 FS	*60.00 FS
26	1		*DOOR STICKER TRANS-CAB (CONSISTENT)	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 13,513.11 3,261.47

- List Item Discount on L Items 10.00/10.00% (S\$) 1,189.65 307.55

Total Parts (S\$) 12,323.46 2,953.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,600.00	500.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,600.00	880.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPE PARKING SENSOR	New	170.00	60.00
5	TO REMOVE AND REPLACE CORPORATE STICKER	New	330.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	340.00	60.00
9	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
Gross Labour Cost (\$\$)			8,770.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >