

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528
63190533/530
Fax. 64796601
64796624

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

29 JAN 2019

GST REG. NO : M2 - 0020081

E S T I M A T E

Estimate No. : b1 49950
Date Estimated : 29/01/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ideal Electric (Singapore) Pte Ltd
1090 Lower Delta Road
#06-08/16 Tiong Bahru Industri
Singapore 169201

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR66K	J777505	26/06/2013	M135i	0

DESCRIPTION

Replacing rear bumper panel and attachments, etc to knock out dents caused by the accident

VALUE
880 1,700.00

Spray rear bumper panel

934.20 1,038.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

? 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries

? 150.00

To supply rear emboss number plate.

83.00

Total Labour 1: 3,679.00

DESCRIPTION

TAILPIPE TIP BLACK CHROME X

QTY PRIC VALUE

Rear silenc. X

2 118.65 237.30

REAR BUMPER CARRIER ?

1 1,297.20 1,297.20

RR BUMPER CENTER GUIDE ?

1 416.45 416.45

GUIDE FOR BUMPER SIDE LH (M) ?

1 66.30 66.30

GUIDE FOR BUMPER SIDE RH (M) ?

1 58.80 58.80

INSERT FOR BUMPER REAR (M) ?

1 58.80 58.80

REAR BUMPER PANEL PRIMED (M) 00

1 240.35 240.35

DECOUPLING RING PDC TORQUE CONVERTE nec

1 961.25 961.25

4 5.05 20.20

Total Parts : 3,356.65

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49950**
Date Estimated : **29/01/2019**
Prepared By : **Joseph Yaguel**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR66K	J777505	26/06/2013	M135i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____



Labour 1	:	3,679.00
Parts	:	3,356.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	492.50
Grand Total	:	7,528.15

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **