

ASS. REC. BY:

REF:

CS3/ALG19001998/ACD307

Special Instruction

Surveyor  
Menmen

Adrian

## ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time:

30/1/19 @ 2.24pm

Estimated Cost:

Bill to:

OD / ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 3543T

Insured:

SLN 5859R

at Workshop in/s

MS Car Auto

Tel:

9725 4442

of

No. 8 Kaki Bkf Ave 4 #01-07 Premier

Policy No:

0999994786

Claim No:

8254289525SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/01/2019

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

2.37pm @ 30/1/19

Person Contacted:

Desmond

Vehicle ☒ IN / ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	FBL 3543T-X
	SLN 5859R-X
27/08/19	@ 16:47 pm checked with Desmond (owner), no estimate.
	Demandtlt: 28/2/2019
	After repair: 27/2/2019

REF: AIG

## ASSIGNMENT

From: Date: 31/01/19  
 Estimated Cost:  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: FBL 3543T  
 at Workshop n/s: MS-Car Auto  
 of: 8 koki Bkt Ave 4 # 01-07 premier  
 Insured:  
 Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS<sup>up</sup>

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBL3543T. Yr Regn: 2016 Make: *Mash*  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CRF1000A. C.C. 998

Colour: white. A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JH2SD04B6GK001216

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90/90 R-21

R: 150/70 R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Enduro*

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 206 mm L/Bal. mm

D.O.A.

D.O.I.

Survey held at

MS Car Auto.

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format: DAR

Lump Sum / I.B.L. (\$)

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

TOTAL

180

11

191

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2019 <a href="#">Edit Reg</a>		30 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K			
Main Claimant:	-			
Vehicle Reg. No.:	FBL3543T	Date of Loss:	24/01/2019 00:00 - :59	
Claim Type:	TP / 8254289525SG	Policy/Cover Note No.:	0999994786 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLN5859R	Policy No. (Claimant):		
		Excess:		
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Yong, Ivy-AV</b> ] Ivy-VA.Yong@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 12/02/2019]			
Claimant's Solicitor:	ROY & PARTNERS - Tel: 65368466			

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG\_SG (31/01/2019): Request to upload TP GIA Report

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your password will expire in 12 days. [Click here to change it.](#)

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 30/1/2019 2:24:32 PM  
Attachments:  29012019165216.pdf

---

Hi LKK,

Kindly assist to survey, bike in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** William Lee [mailto:[william@roypartners.com.sg](mailto:william@roypartners.com.sg)]  
**Sent:** Tuesday, January 29, 2019 3:55 AM  
**To:** Gan, Angiegeokling; Abu Kassim, Noor Mariesa; Fong, Andy-SY; Ng, Hai-Chuan  
**Cc:** 'Ashley'; 'MS Car Auto'; msgroupoffice@gmail.com  
**Subject:** Our Ref: MKR/307/8619/2019/as.wl; Your Ref: Your insured vehicle no. SLN 5859R;  
**Importance:** High

Our Ref: MKR/307/8619/2019/as.wl;  
Your Ref: Your insured vehicle no. SLN 5859R;

Dear Sirs,

**Attn: Motor claims department**

**CLAIMANT:** CHIA SHEH CHEONG (OWNER OF FBL 3543T)  
**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. FBL 3543T AND SLN 5859R ALONG BRADDELL ROAD TOWARDS CTE ON 24.01.2019 AT ABOUT 1115 HOURS.**

We refer to the above matter.

We act for Chia Sheh Cheong, the owner of motorcycle No. **FBL 3543T**.

We are instructed by our client to notify you of a road traffic accident on 24.01.2019 at about 11.15 am along Braddell Road towards CTE involving our client's motorcycle

registration number **FBL 3543T** and motor car registration number **SLN 5859R** driven by your insured at the material time. A copy of the traffic police report is attached.

As a result of the accident, our client's motorcycle **FBL 3543T** has been damaged. Before our client proceed to repair the damaged motorcycle, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a after repair photo of our client's motorcycle **FBL 3543T** at our client's repairer workshop, M/s MS Car Auto Pte Ltd at No. 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875. Your said surveyor may contact Mr. Desmond at 9725 4442. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motorcycle without further reference to you.

Thanks & regards,

**William Lee**

M/s Roy & Partners

101 Cecil Street

#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	724J
<b>Vehicle Details</b>	
Vehicle No.:	FBL3543T
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	CRF1000A
Primary Colour:	Multi-Colour
Manufacturing Year:	2015
Engine No.:	SD04E5001484
Chassis No.:	JH2SD04B6GK001216
Maximum Power Output:	-
Open Market Value:	\$15,384.00
Original Registration Date:	03 Mar 2016
First Registration Date:	03 Mar 2016
Transfer Count:	6
Actual ARF Paid:	\$2,308.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Mar 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,600.00
COE Rebate Amount:	\$4,295.00
<b>Total Rebate Amount:</b>	<b>\$4,295.00</b>

The information contained herein is correct as at 27 Aug 2019

OK

Email: [sm@idac.com.sg](mailto:sm@idac.com.sg)  
Tel no: 6555 6888 Fax no: 6454 3279

### Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 24 / 01 / 2019 (dd/mm/yy) Time of Accident: 11 : 15 (24-HR-FORMAT)  
Vehicle No.: FBL35437 Vehicle Make & Model: Honda CRF 1000L  
Exact location of Accident: \_\_\_\_\_  
Policyholder's Name / IC No.: Chia Sheh Cheong 37701724J (As Above) ☒  
Driver's Name / IC No.: \_\_\_\_\_  
Driver's Contact No.: 98291664 Company Contact No.: \_\_\_\_\_  
Driver's Address: \_\_\_\_\_  
Insurance Company: Direct Asia Email address (if any): \_\_\_\_\_

**Relationship between Owner & Driver:** (Please **CIRCLE** one only)  
Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: \_\_\_\_\_

**What do you wish to claim?** (Please **TICK** one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

**Exact purpose for which the vehicle was being used at time of accident?**

☒ Private use / ☐ Work purpose

**Occupation (nature of job)** ☒ Indoor / ☐ Outdoor

**No. of Passengers (Including Driver):** 01

**Weather condition & Road conditions?** (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: \_\_\_\_\_

**Was there any video captured by your Car Camera?** ☐ Yes / ☐ No

**Any Injuries:** ☒ Yes / ☐ No (If YES) Injured Person's Name: \_\_\_\_\_

Injuries Sustain: \_\_\_\_\_ Injured Person in Which Vehicle: \_\_\_\_\_


**Police Report filed:** ☒ Yes / ☐ No (If YES) Which Police Station: \_\_\_\_\_

### The Other Party(s) Details:

1. Driver's Name / IC No.: \_\_\_\_\_ Vehicle No: SLN 5859R  
Driver's Contact No.: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_  
2. Driver's Name / IC No.: \_\_\_\_\_ Vehicle No: \_\_\_\_\_  
Driver's Contact No.: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_  
\*Independent Witness (If Any): \_\_\_\_\_ Contact No: \_\_\_\_\_  
Preferred Workshop Name: \_\_\_\_\_ Contact No: \_\_\_\_\_

\* If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

# SKETCH PLAN




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


As a police Report T/20190124/2135

A: FBL 3543 T  
B: SIN 5859 R

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

x   
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

Report No. T/20190124/2135

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 24/01/2019 17:55		Vide Report No.:		Station Diary No.: 71	
<b>Informant's Particulars</b>					
Name of Informant: CHIA SHEH CHEONG			Address: 96 PUNGGOL DRIVE #04-15 SINGAPORE 828797		
ID Type / ID No.: NRIC NO / S7701724J			Contact No.: Home/Office: Mobile: 98291664		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 41	Date of Birth: 25/01/1977	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: SELF-EMPLOYED			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/01/2019 11:15	Type of Location: Slip Road
Location: Along Road 1 BRADDELL ROAD  SLIP ROAD TOWARDS CTE(CITY)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL3543T	Motorcycle	HONDA	CRF1000A	Multi-Colored	Slightly Damaged	0
SLN5859R	Car	MAZDA	3	Silver	Slightly Damaged	1

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBL3543T	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/00536147	22/09/2018	21/09/2019



Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	CHIA SHEH CHEONG	ID No.	S7701724J
Related Vehicle	FBL3543T (Motorcycle)	Contact No.	98291664
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Serious
<b>Rider</b>			
Name	ABDUL RASHID BIN HUSSAIN	ID No.	NIL
Related Vehicle	NIL	Contact No.	83129855
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 24/01/2018 at 1115hrs, I was riding my motorcycle bearing registration number FBL3543T along Braddell Road. I then made a right turn once I reached the intersection towards CTE(PIE). As I was travelling on the slip road, a vehicle bearing registration number SLN5859R failed to keep a proper lookout and entered the slip road from my left. The vehicle failed to give way even though there were dotted lines indicating he should have given way to me. I could not brake in time and hit the rear right portion of the vehicle. This caused me to fell off my motorcycle. A fellow rider who almost got hit by the same vehicle stopped to render assistance to me. He was also the witness to the accident. Subsequently I was conveyed to Tan Tock Seng Hospital where I was given treatment and discharged on the same day. As I am self-employed, I told the doctor that no MC was needed. I sustained a fracture on left arm.



**SINGAPORE  
POLICE FORCE**



T/20190124/2135

Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

3 of 3

Report No. T/20190124/2135

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
F /  
Staff Sgt MUHAMMAD AQIB BIN MOHAMMAD  
AKHTAR

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
24/01/2019 17:55

Officer In Charge Of Case:  
TP / GIT /  
SI THABAGESH JEYATHESH  
Contact No.: 65476232

Classification Of Case:

SN 005

Authentication Stamp  
NP168



Signature

Singapore Police Force

FBL3543T.

Honda CRF1000A.

JH2SD04B66K001216.

Front Number Plate Sticker.	Nec	✓
Front Windshield.	Cut	✓
Front Windshield Slider.	Nec	✓
Headlamp Cowling LH.	Cut	✓
Clutch Lever Protector	Cut	✓
Front LH Wing Mirror.	Cut	✓
Front LH Signal Lamp.	cut	✓
Front LH Utility Bag	Cut	✓
Crash Bar - LH.	Bed	✓
Front Wheel Fender.	Repair	x
Rear LH Storage Box	Cut	✓
Rear LH Foot Rest	Cut	✓
Rear LH Foot Rest Bracket	Cut	✓
Engine Under Tray	xxm	x.
Fog Lamp LH	Cut	✓
Fog Lamp Bracket LH.	Cut	✓

FBL3543T.

Front Fork x 02	xHm	x
Front Fork Carbon Fiber Stickers.	Mer	✓
Steering Stem.	} xHm	x
Steering Cone and Bearing.		
Decorative Stickers	Mer	✓

OS Pups

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2019 <a href="#">Edit Reg</a>		30 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>LCRF PTE LTD, Co. Reg. No.: 201624597K</b>									
Main Claimant: -									
Vehicle Reg. No.: <b>FBL3543T</b>		Date of Loss: 24/01/2019 00:00 - :59 [34 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 8254289525SG</b>		Policy/Cover Note No.: 0999994786 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SLN5859R</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838</b>									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Ivy-AV] Ivy-VA.Yong@aig.com</b>									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/02/2019]</b>									
Claimant's Solicitor: <b>ROY &amp; PARTNERS - Tel: 65368466</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (31/01/2019): Request to upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBL3543T (8254289525SG)

[SLN5859R]




































TP



















































-

Jan 24 2019 12:00AM


























[LCRF PTE LTD]

Ms Car Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
2	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
3	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
4	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
5	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
6	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
7	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
8	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
9	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
10	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
11	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
12	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
13	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
14	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
15	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
16	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
17	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
18	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
19	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
20	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
21	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
22	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
23	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
24	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
25	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
26	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
27	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
28	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
29	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
30	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
31	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
32	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
33	27/08/19 17:30	General View									 Load JPG	<input checked="" type="checkbox"/>		
34	27/08/19 17:34	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>		
35	27/08/19 17:34	Photographs of Damaged Parts									 Load JPG	<input checked="" type="checkbox"/>		
36	27/08/19 17:34	Photographs of Damaged Parts									Load JPG	<input checked="" type="checkbox"/>		
37	27/08/19 17:34	Photographs of Damaged Parts									Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	27/08/19 17:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	27/08/19 17:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/01/19 09:50	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001998/ACD3E2

Date: 29/08/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994786  
**Claimant Vehicle No :** FBL3543T **Insured Vehicle No :** SLN5859R  
 Date of Loss: 24/01/2019 Nature of Claim: TP Claim No: 8254289525SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL3543T**  
 Make & Model: HONDA CRF1000A, 998cc Engine No: SD04E5001484  
 Reg. Date: 03/03/2016 (Man. Year: 2015) Chassis No: JH2SD04B6GK001216  
 Colour: White Odometer: 0 km  
 Engine Capacity: 998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 90/90 R21 Rear Tyre Size: 150/70 R18  
 Front Left Side: Enduro 6 mm Rear Left Side: Enduro 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 30/01/2019  
 Date Inspected: 31/01/2019 Inspected At: Ms Car Auto Pte Ltd (HQ)  
 8 KAKI BUKIT AVE 4 #01-07 PREMIER @  
 KAKI BUKIT  
 Singapore 415875  
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSHIELD	Cut	0.00 F	*- F
2	1		*FRONT WINDSHIELD STICKER	Necessary	0.00 F	*- F
3	1		*HEADLAMP COWLING LH	Cut	0.00 F	*- F
4	1		*CLUTCH LEVER PROTECTOR	Cut	0.00 F	*- F
5	1		*FRONT LH WING MIRROR	Cut	0.00 F	*- F
6	1		*FRONT LH SIGNAL LAMP	Cracked	0.00 F	*- F
7	1		*FRONT LH UTILITY BAG	Cut	0.00 F	*- F
8	1		*CRASH BAR LH	Bent	0.00 F	*- F
9	1		*FRONT WHEEL FENDER	Repair	0.00 F	*- F
10	1		*REAR LH STORAGE BOX	Cut	0.00 F	*- F
11	1		*REAR LH FOOT REST	Cut	0.00 F	*- F
12	1		*REAR LH FOOT REST BRACKET	Cut	0.00 F	*- F
13	1		*ENGINE UNDER TRAY	Not Necessary	0.00 F	*- F
14	1		*FOG LAMP LH	Cut	0.00 F	*- F
15	1		*FOG LAMP BRACKET LH	Cut	0.00 F	*- F
16	2		*FRONT FORK	Not Necessary	0.00 F	*- F
17	1		*FRONT FORK CARBON FIBER STICKER	Necessary	0.00 F	*- F
18	1		*STEERING STEM	Not Necessary	0.00 F	*- F
19	1		*STEERING CONE AND BEARING	Not Necessary	0.00 F	*- F
20	1		*DECORATIVE STICKERS	Necessary	0.00 F	*- F
21	1		*FRONT NUMBER PLATE STICKER	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >