

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

30 JAN 2019

ESTIMATE

Estimate No. : b1 49951	Page No. : 1 of 5
Date Estimated : 29/01/2019	
Prepared By : Joseph Yaguel	

<p>- ESTIMATE REPAIR FOR - Ow Chio Kiat 40B Nassim Road Singapore 258427</p>	<p>- ACCOUNT - 40000 Cash Sales - Service Singapore</p>
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS1867S	PZ85208	30/09/2009	335i-C	0

DESCRIPTION	VALUE		
Replacing rear bumper panel and attachments, reworking front bumper panel, tail panel and to knock out dents caused by the accident	1700 2,550.00		
Spray rear bumper, tail panel, front bumper	1868 2,819.00		
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.	250 295.00		
To remove and install boot compartment carpet and garnish to facilitate repairs.	230 ? photo 271.00		
Sundries	? 150.00		
Total Labour 1:	6,085.00		
DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER LH GUIDE	1	39.30	? 39.30
RR BUMPER RH GUIDE	1	39.30	? 39.30
RR BUMPER CTR GUIDE	1	47.95	? 47.95
RR BUMPER CARRIER	1	458.55	? 458.55
RR BUMPER (M/PDC)	1	1,320.90	de 1,320.90
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	nu 20.20
Total Parts :			1,926.20

Date:

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49951	Page No. : 2 of 5
Date Estimated : 29/01/2019	
Prepared By : Joseph Yaguel	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS1867S	PZ85208	30/09/2009	335i-C	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 26/2/19 @ 1120 Excess \$S _____

Surveyor's Name Taufik Sign Taufik

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail taufik@lkkauto.com

Actual on Days Recondition 04 days.

	Labour 1	:	6,085.00
	Parts	:	1,926.20
	Labour 2	:	0.00
	Excess	:	0.00
	Total GST @ 7%	:	560.78
	Grand Total	:	8,571.98

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****