

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08

SIN MING AUTOCITY, SINGAPORE 575722.

Tel No. : 64536256/64563715 Fax No. : 64557754

E-Mail : kumchew1@singnet.com.sg

GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

Estimate : ES004534

Date : 04/03/2019

Vehicle Num. : SKZ 5781 D

Make/Model : NISSAN SYLPHY-2015

Chassis/Eng# : MNTBBAB17Z0026666

Accident Date : 28/01/2019

Claim No. :

Reference : KC/TP5781/1802-06

Policy No. :

LONPAC INSURANCE BHD
300 BEACH ROAD, #17-04/07
THE CONCOURSE, SINGAPORE 199555
PRI EMAIL : mt_claim@lonpac.com
Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62962706

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 PC	NETT ITEMS :		
2.	2 PCS	REAR BUMPER <i>de</i>		607.00
3.	8 PCS	REAR BUMPER BRACKET <i>de</i>	41.40	82.80
4.	2 PCS	REAR BUMPER CLIPS <i>de</i>	5.10	40.80
5.	2 PCS	REAR BUMPER RETAINER - SIDE <i>X su</i>	44.00	88.00 <i>X</i>
6.	1 PC	REAR BUMPER REFLECTOR <i>X su</i>	55.00	110.00 <i>X</i>
7.	1 PC	REAR BUMPER INNER SPONGE - CENTER <i>cr</i>		43.90
8.	1 PC	REAR BUMPER INNER SPONGE - R/H (SIDE) <i>cr</i>		85.90
9.	1 PC	REAR BUMPER INNER SPONGE - L/H (SIDE) <i>cr</i>		127.80
10.	2 PCS	REAR LAMP <i>X su</i>	371.90	743.80 <i>X</i>
11.	4 PCS	REAR LAMP CLIP <i>X su</i>	5.70	22.80 <i>X</i>
12.	2 PCS	REAR LAMP PANEL <i>X su</i>	277.50	555.00 <i>X</i>
13.	1 PC	REAR END PANEL <i>repair</i>		428.40 <i>R+</i>
14.	1 PC	REAR END PANEL INNER GARNISH <i>de</i>		109.10
15.	4 PCS	REAR END PANEL INNER GARNISH CLIPS <i>de</i>	5.10	20.40
16.	1 PC	REAR SPARE TYRE PANEL SPONGE - TOP <i>X su</i>		159.40 <i>X</i>
17.	2 PCS	REAR FENDER INNER GARNISH <i>X su</i>	417.80	835.60 <i>X</i>
18.	8 PCS	REAR FENDER INNER GARNISH CLIP <i>X su</i>	5.10	40.80 <i>X</i>
19.	1 PC	REAR LID <i>bt</i>		1,163.80
20.	1 PC	REAR LID LOCK <i>X su</i>		115.00 <i>X</i>
21.	1 PC	REAR LID RUBBER <i>de</i>		101.50
22.	2 PCS	REAR LID HINGE <i>X su</i>	87.50	175.00 <i>X</i>
23.	2 PCS	REAR LID REFLECTOR <i>X su</i>	141.60	283.20 <i>X</i>
24.	2 PCS	REAR NUMBER PLATE LAMP <i>X su</i>	78.30	156.60 <i>X</i>
25.	1 PC	REAR LID CHROME MOULDING - TOP <i>cr</i>		185.70
26.	1 PC	REAR LID CHROME MOULDING - LOWER <i>X su</i>		118.00 <i>X</i>
	1 PC	REAR LID HANDLE SWITCH <i>su</i>		78.50

Nett Total S\$:

10.00% Discount S\$:

6,478.80

647.88

5,830.92

CONTINUE / ...

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

LONPAC INSURANCE BHD
 300, BEACH ROAD, #17-04/07
 THE CONCOURSE, SINGAPORE 199555
 PRI EMAIL : mt_claim@lonpac.com

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62962706

Estimate : ES004534

Date : 04/03/2019
 Vehicle Num. : SKZ 5781 D
 Make/Model : NISSAN SYLPHY-2015
 Chassis/Eng# : MNTBBAB17Z0026666
 Accident Date : 28/01/2019
 Claim No. :
 Reference : KC/TP5781/1802-06
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 PC	SPECIAL NETT ITEMS :		
2.	1 PC	REAR NUMBER PLATE		
		REAR REVERSE SENSOR		

SPECIAL NETT ITEMS :
 REAR NUMBER PLATE
 REAR REVERSE SENSOR

Special Nett Total S\$:

LABOUR :

TO PULL, KNOCK ON ACCIDENT PORTION & REPLACE THE ABOVE PARTS.

TO SPRAY & PAINT ON REAR ACCIDENT PORTION.

TO ANTI-RUST REAR AFFECTED AREAS.

TO CHECK WIRING FUNCTION.

TO DISMANTLE & REPLACE REVERSE SENSOR.

Labour Total S\$:

60.00 X
 200 280.00
 340.00

850.00

950.00

150.00

150.00 X

150.00

2,250.00

SingDollars : Eight Thousand Four Hundred Twenty & Cents Ninety-Two Only

KUM CHEW MOTOR WORKSHOP

Total S\$: 8,420.92

2382.48

200.00

1420.00

4002.48

20%

3201.98

45-3,200

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5 days