

INS. CASE OWNER:

Peter

CC

4, Asm 1900

2011

Kf39

LKK:

IDAC:

93346

Surveyor:

fsc

DOI:

ASSIGNMENT


31/1/19

Date / Time:

30/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XD 318D

Name of Insured:

VERUA 65 (S) Indrpl

Insured Tel No.:

87000

HP:

Excess Sec II :SS

D.O.A.:

27/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SGM 01 CD 4

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:


(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLR9690L



INSRS:


WSP:

Tel:

Liability:

RMKS:

mbm




INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/12

CNC

SLR9690L - X;

XD 318D - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$ 9200.00

(6 days)

Reduction: \$15,343.20 % 63

Confirm by: Kenneth

Email

Call

FINAL SETTLEMENT

Date/Time:

25/3/2020

Confirm with:

VU

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

15

OZD

If NO or B 28, Ass. Lia:

Repair Cost:

(W/GST) S\$ 9844.00

Loss of Rental (LOR):

S\$ 1497.20

(14 days)

x \$149.80 (W/GST) change

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 11,948.65

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 11,948.65

Name 1:

mbm wheelpower Pte Ltd

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

✓ GIA

REF: ASM(AXA)

ASSIGNMENT

From: Date: 31-01-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLR 9690L

at Workshop m/s: M&M Wheelpower

of: 160 Sin Ming Drive

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$130k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lump Sum: 1B1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLR 9690L Yr Regn: 09 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mer C350 C.C. 1991

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 53757 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2050 4721-423647

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 245/35 ZRR

R: 275/30 ZRR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 29/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L/S 9200/- (Red = \$15,343.20 / 63%)

* 6 repair day + 2 PRs + 2 sunday + 2 saturday + 5 PH = 15 days.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + PS \$

) Photos

) Others

) .

TOTAL

Report Format:


Lump Sum / I.B.I. (\$)

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

KP

SHD 02632



MBM WHEELPOWER PTE LTD

Your Ref: XD318D
Our Ref: SLR9690L

To: AXA

CC

Fax

*Not whashed
Purmy B4 paint*

6 days

Date: 30/1/2019
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: MERCEDES BENZ C350E
Chassis No.: WDD2050472F423647
Engine No.: 27492030757926
Year of Make: 2016
Accident Date: 29 January 2019

ESTIMATE FOR VEHICLE NO.: SLR9690L

DESCRIPTION	QTY	List Price
REAR WINDSCREEN MOULDING	1	\$ 110.00
REAR RH FENDER <i>2265</i>	1	\$ 2,616.00
REAR RH FUEL CAP	1	\$ 106.00
*REAR RH FUEL RECESS FILLER	1	\$ 267.00
REAR RH FUEL ACTUATOR LOCK	1	\$ 150.00
REAR RH TAIL LAMP PANEL	1	\$ 272.00
*REAR RH AIR VENT PANEL	1	\$ 316.00
*REAR RH AIR VENT	1	\$ 98.00
REAR RH FENDER INNER SHIELD	1	\$ 229.00
*REAR RH FENDER INNER SHIELD CLIPS @ \$90 EACH	10	\$ 90.00
REAR RH DOOR	1	\$ 2,789.00
REAR RH DOOR WEATHERSTRIP	1	\$ 332.00
REAR BUMPER <i>1845</i>	1	\$ 2,362.00
RIVET @ \$9 EACH	10	\$ 90.00
*REAR BUMPER RH SIDE GUIDE	1	\$ 82.00
REAR BUMPER RH SIDE MOUNTING	1	\$ 65.00
REAR BUMPER RH BRACKET	1	\$ 144.00
DISTANCE SENSOR @ \$250 EACH	2	\$ 500.00
DECOUPLING RING @ \$12 EACH	2	\$ 24.00
REAR BUMPER LOWER COVER	1	\$ 570.00
TAIL LAMP RH <i>795</i>	1	\$ 874.00
REAR RH RIM	1	\$ 1,262.00
*REAR RH SHOCK ABSORBER <i>1070</i>	1	\$ 1,747.00
REAR RH TIE ROD	1	\$ 288.00
REAR RH STRUT	1	\$ 242.00

REAR RH CAMBER ARM
 REAR RH LOWER ARM
 X REAR RH WHEELHUB WITH BEARING 1035
 REAR RH BALL JOINT

1	\$	Rh	293.00	X
1	\$	Rh	183.00	X
1	\$	DAM. Rh	2,169.00	X
1	\$	Rh	198.00	X
Total: \$			18,468.00	
LESS 10% \$			(1,846.80)	
Parts Total: \$			16,621.20	

SPECIAL NETT

BODY SEALANT
 WINDSCREEN SELANT

1	\$	mc 30sn	80.00	
1	\$	na 40sn	60.00	


LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.
 TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)
 TO REMOVE AND REPLACE FUEL TANK FIXTURE AND TO UPHOLSTERY TO FACILITATE REPAIRS
 TO REMOVE AND RE-FIT ROOF LINING
 TO REMOVE AND RE-FIT REAR WINDSCREEN
 TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR
 TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR
 TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS
 TO REMOVE & REPLACE BUMPER SENSORS
 TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT
 TO REMOVE & REPLACE REAR RH UNDERCARRIAGE
 TO REMOVE & REFIT REAR RH TYRE
 TO CHECK & RECONNECT ALL NECESSARY WIRING
 TO CONDUCT CHASSIS ALIGNMENT ON (CAR-O-LINER)
 TO SPRAY PAINT ON THE AFFECTED AREAS

	\$	700l	1,800.00	
	\$	120l	200.00	
	\$		80.00	✓
	\$	100l	150.00	
	\$	120l	150.00	
	\$	nn	80.00	X
	\$	nn	100.00	X
	\$		150.00	X
	\$		40.00	✓
	\$	60l	80.00	
	\$	200	250.00	✓
	\$	20	60.00	✓
	\$	20l	80.00	
	\$	nn	400.00	X
	\$	600l	1,500.00	
Total: \$			21,881.20	
7% GST: \$			1,531.68	
Grand Total: \$			23,412.88	

24593.20

MBM WHEELPOWER PTE LTD



Your Ref: XD318D
Our Ref: SLR9690L

To: AXA

CC

Fax

Date: 18/2/2019
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: MERCEDES BENZ C350E
Chassis No.: WDD2050472F423647
Engine No.: 27492030757926
Year of Make: 2016
Accident Date: 29 January 2019

SUPPLEMENTARY ESTIMATE FOR VEHICLE NO. : SLR9690L

DESCRIPTION

REAR WINDSCREEN WITH MOULDING

REAR RH AIRMANTIC SPRING 1216

QTY		List Price	
1	\$	<i>my m</i>	1,238.00 ✓
1	\$	<i>A7</i>	1,474.00 ✓
Total:		\$	2,712.00
LESS 10%		\$	(271.20)
Parts Total:		\$	2,440.80

Mbm wheelpowerpte ltd
180 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
162828888 64525333
Company Registration Number : 200204110W