

MBM WHEELPOWER PTE LTD

Your Ref: XD318D

Our Ref: SLR9690L

To: AXA

CC

Fax

*Not Withheld
Penny B4 pain
6 days*

Date: 30/1/2019
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: MERCEDES BENZ C350E
Chassis No.: WDD2050472F423647
Engine No.: 27492030757926
Year of Make: 2016
Accident Date: 29 January 2019

mbm wheelpower

ESTIMATE FOR VEHICLE NO. : SLR9690L

DESCRIPTION

QTY

List Price

REAR WINDSCREEN MOULDING	1	\$	<i>me</i> ✓	110.00
REAR RH FENDER	1	\$	<i>me</i> ✓	2,616.00
REAR RH FUEL CAP	1	\$	?	106.00
REAR RH FUEL RECESS FILLER	1	\$	?	267.00
REAR RH FUEL ACTUATOR LOCK	1	\$	?	150.00
REAR RH TAIL LAMP PANEL	1	\$	<i>me</i> X	272.00
REAR RH AIR VENT PANEL	1	\$	?	316.00
REAR RH AIR VENT	1	\$	<i>me</i> X	98.00
REAR RH FENDER INNER SHIELD	1	\$	<i>me</i> X	229.00
REAR RH FENDER INNER SHIELD CLIPS @ \$90 EACH	10	\$	<i>me</i> X	90.00
REAR RH DOOR	1	\$	<i>me</i> X	2,789.00
REAR RH DOOR WEATHERSTRIP	1	\$	<i>me</i> X	332.00
REAR BUMPER	1	\$	<i>cm</i> ✓	2,362.00
RIVET @ \$9 EACH	10	\$	<i>me</i> ✓	90.00
REAR BUMPER RH SIDE GUIDE	1	\$	?	82.00
REAR BUMPER RH SIDE MOUNTING	1	\$	?	65.00
REAR BUMPER RH BRACKET	1	\$	<i>me</i> X	144.00
DISTANCE SENSOR @ \$250 EACH	2	\$	<i>me</i> X	500.00
DECOUPLING RING @ \$12 EACH		\$	?	24.00
REAR BUMPER LOWER COVER	1	\$	<i>me</i> X	570.00
TAIL LAMP RH	1	\$	<i>Bo</i> ✓	874.00
REAR RH RIM	1	\$	<i>me</i> X	1,262.00
REAR RH SHOCK ABOSRBER	1	\$	<i>me</i> X	1,747.00
REAR RH TIE ROD	1	\$	<i>me</i> X	288.00
REAR RH STRUT	1	\$	<i>me</i> X	242.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REAR RH CAMBER ARM	1	\$	293.00	X
REAR RH LOWER ARM	1	\$	183.00	X
REAR RH WHEELHUB WITH BEARING	1	\$	2,169.00	X
REAR RH BALL JOINT	1	\$	198.00	X
Total:	\$		18,468.00	
LESS 10%	\$		(1,846.80)	
Parts Total:	\$		16,621.20	

SPECIAL NETT

BODY SEALANT	1	\$	80.00	
WINDSCREEN SELANT	1	\$	60.00	

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	1,800.00	
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	200.00	
TO REMOVE AND REPLACE FUEL TANK FIXTURE AND TO UPHOLSTERY TO FACILITATE REPAIRS	\$	80.00	
TO REMOVE AND RE-FIT ROOF LINING	\$	150.00	
TO REMOVE AND RE-FIT REAR WINDSCREEN	\$	150.00	
TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR	\$	80.00	X
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	100.00	X
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	150.00	X
TO REMOVE & REPLACE BUMPER SENSORS	\$	40.00	
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	80.00	
TO REMOVE & REPLACE REAR RH UNDERCARRIAGE	\$	250.00	
TO REMOVE & REFIT REAR RH TYRE	\$	60.00	X
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	80.00	
TO CONDUCT CHASSIS ALIGNMENT ON (CAR-O-LINER)	\$	400.00	X
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	1,500.00	
Total:	\$	21,881.20	
7% GST:	\$	1,531.68	
Grand Total:	\$	23,412.88	