

✓
in 220419

Steve
83228813

With Repair 22/4/19 2:30pm
P/P 4 days
Ry before spray

SERVICE ESTIMATE

99039 - C00001 SL: SERVICE SALES - PC

Mr Wong Kian Chong
Blk 117 Bedok North Road
#05-237

Singapore 460117

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 29/01/2019

WIP No. : 51240

Veh.In/Out: 28/01/2019

*Tel.No. : Home: 91135380

Reg.No. : SMF4458B

Reg.date : 12/11/2018

Mileage : 0

Chassis No: YV1FS40LDJ2470561

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Wong Kian Chong

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR RH FENDER, ETC ⁸⁰⁰	0		6400.00	0		6,400.00	S 7000 1200
800	TO PUTTY SPRAY PAINT ON REAR RH FENDER, REAR END PANEL, RH ⁷⁰⁰	0		2800.00	0		2,800.00	S 2100 700
	ROCKER PANEL, ETC							
802	TO REPLACE REAR WINDSCREEN	0		800.00	0		800.00	S X
802	TO REMOVE & INSTALL REAR BOOT	0		2400.00	0		2,400.00	S 1700 X
	COMPARTMENT PARTS							
802	TO REMOVE & INSTALL INTERIOR P ⁸⁰⁰	0		3200.00	0		3,200.00	S 4600 800
89994	TO INSTALL REAR WINDSCREEN FIL	0		280.00	0		280.00	S X
280	TO CHECK WIRING INCLUDE	0		450.00	0		450.00	S /
	RESETTING OF ALL ELECTRICAL MODULES							
	FENDER REAR RH S60 1 X 200	1.0	EA	2032.70			2,032.70	S X R
	D WINDSCREEN SEALA X 120	2.0	EA	122.10			244.20	S X M
	D PRIMER GLASS & P X 100	1.0	EA	37.40			37.40	S X M
	V001161436/*D* GLASS X 100	1.0	EA	55.40			55.40	S X M
	WINDSCREEN REAR S60 X 1200	1.0	EA	1288.90			1,288.90	S X M

SERVICE ESTIMATE

99039 - C00001 SL: SERVICE SALES - PC

Mr Wong Kian Chong
Blk 117 Bedok North Road
#05-237

Singapore 460117

GST Reg. No: M28920628X

Inv. No. : B&P 0. Page 2

Inv. date. : 29/01/2019

WIP No. : 51240

Veh. In/Out: 28/01/2019

*Tel. No. : Home: 91135380

Reg. No. : SMF4458B

Reg. date. : 12/11/2018

Mileage : 0

Chassis No: YV1FS40LDJ2470561

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Wong Kian Chong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	SOUND DEADENING PAD X MM	1.0 EA	250.00			250.00	S/Vm
--	--------------------------	--------	--------	--	--	--------	------

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Gross Total. 20,238.60

Labour Total	16,330.00
Parts Total	3,908.60
Package Total	0.00

Net..... 20,238.60

GST @ 7.0% 1,416.70

Total..... 21,655.30

Paid..... 0.00

Please Pay.. 21,655.30

GST: S=StdRated; O=OutOfScope; Z=ZeroRated