

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19002018/JKA3Q2

Date: 28/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800113539
Claimant
Vehicle No : SMB1346G **Insured Vehicle No :** EL202L
Date of Loss: 25/01/2019 Nature of Claim: TP Claim No: 1312072308SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB1346G**
Make & Model: MAN NL320F (A22), 10.5 D (M) Engine No: 50333721133365
Reg. Date: 15/04/2013 (Man. Year: 2012) Chassis No: WMAA22ZZ4D7001793
Colour: Multi-colour Odometer: 513225 km
Engine Capacity: 10518 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5
Front Left Side: Firenza 7 mm Rear Left Side: Firenza 7 mm
Front Right Side: Firenza 7 mm Rear Right Side: Firenza 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 974.70 | 0.00 | 974.70 | 100.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 976.00 | 589.00 | 387.00 | 39.65 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 1,950.70 | 589.00 | 1,361.70 | 69.81 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 29/01/2019
Date Inspected: 29/01/2019 Inspected At: SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 1.0 days

Adjuster: ONG HWEE JIE

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|--------------------------|--------------------|
| 1 | 1 | | *COVER HEADLAMP:FRT LH ,FOR MAN A22 BUS | Not Necessary | 974.70 F | *- F |
| | | | | | Total Parts (S\$) | 974.70 0.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | TO REMOVE & INSTAL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS | New | 530.00 | 265.00 |
| 2 | PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | New | 446.00 | 324.00 |
| Gross Labour Cost (\$\$) | | | 976.00 | 589.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >