



Case Details

Case Reference Number : TAX/01/19/2124
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1036K

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5536-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 25/01/2019 03:28 PM
 Vehicle Age(In Months) : 62

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	<input type="text" value="1"/>	<input type="text" value="361.50"/>	<input type="text" value="Replace"/>	DEF
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	<input type="text" value="Check"/>	
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	<input type="text" value="Check"/>	
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	<input type="text" value="Check"/>	
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	<input type="text" value="Check"/>	
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	<input type="text" value="1"/>	<input type="text" value="13.88"/>	<input type="text" value="Replace"/>	CUT
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	<input type="text" value="1"/>	<input type="text" value="233.33"/>	<input type="text" value="Replace"/>	CRA
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	<input type="text" value="Not Give"/>	
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	<input type="text" value="1"/>	<input type="text" value="0"/>	<input type="text" value="Repair"/>	
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	<input type="text" value="Check"/>	

Total Spare Part Cost 2,339.56

Surveyor Total 608.71

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 1,871.65

Final Sur Total 486.97

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BRACKET, FR TURN UPPER RH	1	24.40	24.40	25.00	18.30	Replace	0	0	Check	
One Time Key In	Main			BRACKET, FR TURN	1	58.20	58.20	25.00	43.65	Replace	0	0	Check	
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check	
Total Spare Part Cost									2,339.56	Surveyor Total		608.71		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									1,871.65	Final Sur Total		486.97		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	676.00	250	
Total:			676.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO WASH AND VACUUM	60.00	0	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			340.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,871.65	486.97
Total Labour Cost	676.00	250.00
Total Spray Painting	558.00	200.00
Other	340.00	20.00
Overall Total	3,445.65	956.97
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	3,450.00	950.00
Surveyor Approved Amount		950.00
No of Repair Days*	4	3
Remarks	-	L/S REPAIR, PHOTO AFTER REPAIR.
Surveyor Name		Hwee jie
Signature		
Survey Date	29/01/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: