



UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 190103.VGS(PA6290U)

23 January 2019

Vaya Garden Scene Cruiser Pte Ltd
Blk 637 Hpugang Ave 8
#10-121
Singapore 530637

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PA 6290 U

QTY DESCRIPTIONS

1 pc 1st LHS panel *repair*
1 pc Signal lamp *can*
1 pc Side lamp *can*

PRICE S\$

2,680.00 X
358.00 } 463
105.00 }

463

25%

347.25

Labour charges for remove & replace the above damaged part

800.00 *450*

Labour charges for dismantle & assemble window glass x 2

300.00 X

950

To putty & spray painting onto affected areas

600.00 *500*

Total

5,443.00
=====

(SGD: Five Thousand four hundred and forty-three only)

Price quoted above is subjected to 7% GST

Yours faithfully,
Tan Tiong Chia

Rasm

Hp 90010068

4 days

W/S

13/02/19 @ 1000h

Resy after repair

347.25

950.00

1297.25

20%

1037.80

4/5-1000

4 days

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2C Jalan Pesawat, Jurong, Singapore 619359

Tel: 6268 1281 Fax: 6268 1282

E-mail: unitedcb@singnet.com.sg