



# UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 190103.VGS(PA6290U)

23 January 2019

Vaya Garden Scene Cruiser Pte Ltd  
Blk 637 Hpugang Ave 8  
#10-121  
Singapore 530637

QUOTATION  
without Prejudice

Dear Sir,

## COST OF REPAIR FOR PA 6290 U

<u>QTY</u>	<u>DESCRIPTIONS</u>	<u>PRICE</u> S\$
1 pc	1st LHS panel <i>repair</i>	2,680.00
1 pc	Signal lamp <i>CRA</i>	358.00
1 pc	Side lamp <i>CRA</i>	105.00
	Labour charges for remove & replace the above damaged part	<del>800.00</del> <i>850</i>
	Labour charges for dismantle & assemble window glass x 2	<del>300.00</del> <i>X</i>
	To putty & spray painting onto affected areas	<del>600.00</del> <i>500</i>
Total		5,443.00 =====

(SGD: Five Thousand four hundred and forty-three only)

Price quoted above is subjected to 7% GST

Yours faithfully,  
Tan Tiong Chia

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2C Jalan Pesawat, Jurong, Singapore 619359

Tel: 6268 1281 Fax: 6268 1282

E-mail: [unitedcb@singnet.com.sg](mailto:unitedcb@singnet.com.sg)

*Rasul*  
*Hp 90010068*  
*4 days*  
*4s*  
*13/02/19 @ 1000hrs*  
*Resay after repair*