



UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: 190103.VGS(PA6290U)

23 January 2019

Vaya Garden Scene Cruiser Pte Ltd
Blk 637 Hpugang Ave 8
#10-121
Singapore 530637

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PA 6290 U

QTY DESCRIPTIONS

1 pc 1st LHS panel *repair*
1 pc Signal lamp *can*
1 pc Side lamp *can*

PRICE S\$

2,680.00 X
358.00 } 463
105.00 }

463
25%
347.25

Labour charges for remove & replace the above damaged part

800.00 *450*

Labour charges for dismantle & assemble window glass x 2

300.00 X *can*

950

To putty & spray painting onto affected areas

600.00 *500*

Total

5,443.00
=====

(SGD: Five Thousand four hundred and forty-three only)

Price quoted above is subjected to 7% GST

Yours faithfully,
Tan Tiong Chia

Resue
Hp 90010068
4 days
4/5
13/02/19 @ 1000h
Resue after repair
4 days

347.25
950.00
1297.25
20%
1037.80
4/5-1000
4 days

United City General Insurance notify
the insurer of the following:

- The survey is done after spray painting
- The survey is done after repair
- The survey is done after repair
- The survey is done after repair
- The survey is done after repair
- The survey is done after repair
- The survey is done after repair
- The survey is done after repair

Acknowledged by Repairer
Signature:
Date: