

MTM Performance Auto Pte Ltd

The Motor Claims Department
AIG Asia Pacific Pte Ltd
78 Shenton Way, #07-16
Singapore 079102

Quotation for Repair Costs

Yr Insured Vehicle Number	Vehicle Registration No	Consultants	Date
SJZ8993B	SJS2011L	Erwin - 92210404	28/01/2019

Item	Description	Quantity	Unit Price S\$	Total Price S\$
1	Rear Bumper <i>de</i>	1	859.21	859.21 -
2	Rear Exhaust <i>bt</i>	1	629.70	629.70 -
3	Rear Bumper Retainer <i>ne</i>	2	17.18	34.36 -
4	Rear Boot <i>bt</i>	1	706.20	706.20 -
5	Rear Boot Light <i>RH cut</i>	1	218.00	218.00 -
6	Rear Light Body <i>RH cut</i>	1	363.34	363.34 -
7	Rear Boot Lock <i>bt</i>	1	219.35	219.35 -
8	Rear Boot Hinge <i>bt</i>	2	52.00	104.00 -
9	Rear Bumper sensor <i>200 new</i>	1	220.00	<i>SN</i> 220.00 <i>200</i>
10	Rear Boot Rubber <i>h</i>	1	340.00	340.00 -
11	Number Plate <i>x</i>	1	40.00	40.00
12	Number plate holder <i>x</i>	1	30.00	30.00
13	Rear Boot Carpet <i>de</i>	1	470.00	470.00 -
14	Rear Boot Spoiler <i>dis</i>	1	900.00	<i>600</i> 900.00
15	To check rear compartment wiring system	1	60.00	60.00 <i>30</i>
16	To install reverse sensor	1	150.00	150.00 <i>30</i>
17	To remove inner trim, garnish for necessary checking and repair	1	250.00	250.00 <i>60</i>
18	Spare tyre compartment/floor panel	1	1014.36	1014.36 <i>Rx 200</i>
19	Panel Beating to straighten, repair, realign damaged area	1	1400.00	1400.00 <i>1200</i>
20	Spray painting on new parts & damaged areas	1	1400.00	1400.00 <i>1200</i> 1400.00 ✓
21	To apply anti-rust costing on affected area	1	120.00	<i>60</i> 120.00
22	To install damaged parts eg. Bumper, boot hinge, spoiler, reverse sensor, lights etc.	1	1800.00	1800.00 <i>2980</i>
Total				11,328.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3635.33

6815.33

11515500

Tauhik 9749549. 7324.16
wp
29/1/19 @ 445pm
Lumpsum
Rising after repair
tauhik@lkhart.com.
7 days