

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 29/01/2019

TP Veh Reg No: SMA8621X

Estimate No: ES1991127/AMK

Date: 11 Feb 2019

Policy No: 5096312225

Veh Reg No: SLU5443U

Make/Model: MAZDA 5 2.0 A

Chassis No: JM6CR10F290309378

Engine No: LF10704303

Reg. Date: 01/06/2009

Estimate Repair Cost to Vehicle No :SLU5443U

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	1,116.00	1 PC	1,116.00	✓
2 FRONT BUMPER LH SIDE RETAINER	36.00	1 PC	36.00	✓
3 FRONT BUMPER LH FOG LAMP GARNISH	55.00	1 PC	55.00	?
4 FRONT BUMPER CLIPS	10.50	5 PCS	52.50	✓
5 LH HEADLAMP	1,345.00	1 PC	1,345.00	?
6 LH HEADLAMP LOWER BRACKET	36.00	1 PC	36.00	?
7 FRONT LH FENDER	436.00	1 PC	436.00	✓
8 FRONT LH FENDER INNER SHIELD	218.00	1 PC	218.00	✓
9 FRONT LH FENDER INNER SHIELD CLIP	5.00	6 PCS	30.00	✓
10 FRONT SHOCK ABSORBER	417.00	2 PC	834.00	?
11 FRONT KNUCKLE ARM	330.00	2 PC	660.00	✓
12 FRONT KNUCKLE BEARING	147.00	2 PC	294.00	✓
13 FRONT LOWER ARM	392.00	2 PC	784.00	?
			5,896.50	
	Less 20%		1,179.30	4,717.20
Special Net				
14 FRONT RIMS	280.00	2 PC	560.00	✓
15 REMOVE & REFIX FRT BUMPER,GRILLE,HEADLAMP,FRT LH FENDER,KNOCK & REPAIR FRT LH FENDER & INNER PANEL & REALIGN THE SAME	600.00	1 LA	600.00	500
16 PUTTY & RESPRAY FRT BUMPER,FRT LH FENDER & INNER PANEL & ALL AFFECTED AREAS	700.00	1 LA	700.00	540
17 REMOVE & REFIX FRT BOTH UNDER CARRIAGE & REALIGN THE SAME	300.00	1 LA	300.00	?
18 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
19 RUSTPROOFING	60.00	1 LA	60.00	300
			2,280.00	2,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 29/01/2019
TP Veh Reg No: SMA8621X

Estimate No: ES1991127/AMK
Date: 11 Feb 2019
Policy No: 5096312225
Veh Reg No: SLU5443U
Make/Model: MAZDA 5 2.0 A
Chassis No: JM6CR10F290309378
Engine No: LF10704303
Reg. Date: 01/06/2009

Estimate Repair Cost to Vehicle No :SLU5443U

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 6,997.20
			Add GST @ 7%	489.80
			Total Amount Payable	<u>S\$ 7,487.00</u>

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE