

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 3939S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	3,800.00	-
1	REAR BUMPER STRUCTURAL FRAME ASSY	TO REPAIR SEE LABOUR	580.00	-
1	REAR LID COVER N/S REFLECTOR	CRACKED	120.00	120.00
1	REAR PANEL ASSY	CRUSHED	4,300.00	3,400.00
1	REAR PANEL STRUCTURAL FRAME ASSY	DISTORTED	1,400.00	1,000.00
1	REAR N/S TAILLAMP	CRUSHED	1,100.00	1,100.00
1	REAR N/S INSPECTION LID COVER ASSY	DISTORTED	2,300.00	2,000.00
2	REAR N/S INSPECTION LID HINGE	BENT	220.00	220.00
2	REAR N/S INSPECTION LID COVER DAMPER	BENT	360.00	360.00
1	REAR N/S INSPECTION LID COVER REFLECTOR	CRACKED	20.00	20.00
	LESS 10% DISCOUNT		-	-822.00
			14,200.00	7,398.00
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN GLASS GUM (SN)	NECESSARY	350.00	260.00
			350.00	260.00
	<u>LABOUR</u>			
	TO REMOVE REAR WINDSCREEN GLASS SO AS TO ENABLE REPAIR TO BE CARRIED OUT AND REFIT SAME.		600.00	400.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR PANEL, SIDE PANEL, REAR INSPECTION LID COVER AND ALL AFFECTED ACCIDENT PARTS.		2,800.00	2,000.00
	TO CUT OFF DAMAGED FRAMES AND WELD NEW. TO KNOCK / STRAIGHTEN ALL NECESSARY PARTS INCLUDING REPAIRING AND CHARGING OF ALL DAMAGED PARTS AND ALIGN SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER STRUCTURAL FRAME ASSY.		3,200.00	2,200.00
			6,600.00	4,600.00
	GRAND TOTAL		21,150.00	12,258.00

RECOMMENDED COST OF LUMP SUM REPAIRS		9,800.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/AXA16000259/K1vd3s2-1





Report Ref No. CS3/AXA16000259/K1vd3s2-1

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

X:2.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.