

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN CHEE HOW
23 A NALLUR ROAD
#04-01
S 456644

TPEQ
Poh Kin

Date :20.02.2019
Vehicle no :SKT 969 U
Make/Model :TOYOTA HARRIER
Accident date :28.12.2018

No	DESCRIPTION	Qty	Amount (\$S)
<u>List Items</u>			
1	Rear bumper <i>Deland</i>	1	\$ 1557.2 <i>1381.20</i>
2	Rear bumper side holder @ \$93.50 <i>nc</i>	2	\$ 187 ✓
3	Rear bumper lower lip <i>Deland</i>	1	\$ 500.5 ✓
4	Rear bumper reflector @ \$63.40 <i>nc</i>	2	\$ 126.8 X
5	Rear bumper sponge <i>cauld</i>	1	\$ 137.5 ✓
6	Rear bumper clips (1set) <i>nc</i>	1	\$ 70.30
7	Rear end panel <i>Rys</i>	1	\$ 858 X
8	Rear end panel top garnish <i>nc</i>	1	\$ 489.5 X
			\$ 3926.5
		Less 25% Disc	\$ 981.63
		Total	\$ 2944.87

Special Nett Items

1 Reverse sensor *anyd*

1 \$ 380 *200*
Total \$ 380

Labour Cost

- 1 To supply rear end panel inner sealant
- 2 Remove & reinstall reverse sensor
- 3 Remove & reinstall boot lid inner garnish
- 4 Remove, replace & repair consistent to the accident
- 5 Respray Painting
- 6 Tuff kote

\$ 200 X
\$ 150 *80*
\$ 200 X
\$ 1400 *400*
\$ 1200 *400*
\$ 150 X
Total \$ 3300

Grand Total \$ 6624.87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 2737.15
H/S: 22K.
04 days.

2.2K