

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0143/2018/GW
Date : 30-Jan-19

Kindly arrange for survey.

Your insured vehicle no. SJX 2668 R

Lonpac Insurance Bhd

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Attn: Motor Claims Dept

Fax: 6296 2706

Owner's Name : Mr. Lee Chor Heng
Address : 72 Jalan Gumilang
Singapore 668911
Telephone : 96784431
Type of Claim : Third Party Claim
Policy No. : 2100398966-04
Vehicle No : **SKR 2407 Y**
Model Code : Audi A6 C7 2.0 TFSI Mu
Model / Year : Jan-15
Engine No : CDN 411191
Chassis No : WAUZZZ4GXEN165215
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Jan-19
Place of Accident : Car Park of Blk 273 BT Batok East Ave 4

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKR 2407 Y

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓
2	To dismantle and renew rear bumper. To repair rhs rear fender. Reorganise crash management components. Reinstall all parts removed.	\$ 1,400.00 1000
3	To respray rear bumper and rhs rear fender.	\$ 1,600.00 1100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 3,552.00</u>

All charges are not inclusive of GST.

Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 2407 Y

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER <i>Repair</i>	\$ 2,343.00	*
2	REAR BUMPER SITCKY PAD	\$ 21.00	+
3	REAR BUMPER FIXING PARTS <i>3 Nm</i>	\$ 249.00	+
4	REAR BUMPER SPOILER <i>new</i>	\$ 316.00	+
5	REAR BUMPER SECURING STRIP	\$ 157.00	+
6	REAR BUMPER GUIDE PROFILE -RH UPPER	\$ 53.00	+
7	REAR BUMPER SECURING ELEMENT	\$ 6.00	+
8	REAR BUMPER GUIDE SECTION-RH	\$ 30.00	+
9	REAR BUMPER CONNECTING PIECE	\$ 11.00	+
10	REAR BUMPER LOWER GUIDE SECTION-RH	\$ 48.00	+
11	REAR BUMPER COVER FIXING PARTS	\$ 24.00	+
12	REAR BUMPER CARRIER COVER	\$ 105.00	+
13	REAR SENSOR	\$ 231.00	+
14	REAR SENSOR SEAL RING - INNER/OUTER	4 \$ 5.00	+
15	LED TAILLIGHT-RH <i>connected</i>	\$ 1,148.00	✓
16	LED TAILLIGHT COVER-RH <i>new</i>	\$ 43.00	+
17	EXHAUST TAIL PIPE TRIM <i>new</i>	\$ 517.00	+
18	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS		: \$ 5,807.00	
TOTAL LABOUR CHARGES		: \$ 3,552.00	
GRAND TOTAL		: \$ 9,359.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *14/02/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 04 Days.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant