

ASS. REC. BY:

REF: CS/FCI 19002049/Kqd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

9.27am @ 30/1/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY 7 CS

To Inspect Vehicle No:

SMA 2782D

Insured:

SHC 2248D

at Workshop m/s

Alan's United

Tel:

64538686

of

Blk 7 Sin Ming Ind. Est #01-76

Policy No:

Claim No:

D19000715MF34

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

28/01/2019

CA / REV / REP. / REV 24 HRS 'OS'

H.O.D. Endorsement:

Date/Time:

9.45am @ 31/1/19

Person Contacted:

Kenny

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SMA 2782D - X
	SHC 2248D - CS/FCI 18015194/Krbn2 D.O.A. 17/8/18
01/2/19 @ 11.18am	revised to Eileen Lee by email.
	Kenneth finalised final fig 810075.08, 10 days.
	(Red 72851.98, 22%)

ASS. REC. BY:

REF: F021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

1 B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

RECEIVED 11 MAR 2019

Date/Time, File Pass to?

11/3/2019

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

2x15=30

170+30

50

30+50

58

408

Report Format :

Lump Sum / I.B.I: (\$

TP
60075.08



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000715MFSH

Date: 01 February 2019

Our Ref: CS/FCI19002049/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMA 2782D.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/01/2019 at the premises of M/s ALAN'S UNITED, and have the following to report:-

Workshop Estimate Amount	: S\$ 12,524.50 .
Revised Estimate Amount	: S\$ 9,341.96 .
"Check" Items Amount	: S\$ 1,496.50 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	28-01-2019	Our Ref No. D19000715MFSH
Accident Date	25-01-2019	Claim Type. Third Party
Insured Vehicle	SHC2248D	Third Party Vehicle. SMA2782D
Survey Location	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76	
Contact Person.	KENNY	
Contact No.	64538686/ 64538686	Fax No. 64596550
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ALAN'S UNITED AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 1 February 2019 11:18 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000715MFSH/1
Attachments: CSFC119002049Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SMA 2782P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 31 January 2019 9:48 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000715MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 31 January 2019 9:27 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000715MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Register New Vehicle (Acknowledgement)**Vehicle Particulars**

Vehicle No.:	SMA2782D	Vehicle Scheme:	Normal
Vehicle Type:	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1:	No Attachment		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	HONDA	Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Chassis No.:	GP71211098	Engine No.:	LEB6553486
Motor No.:	H13713427	Trailer Chassis No.:	-
Propellant:	Petrol-Electric	Passenger Capacity:	4
Engine Capacity:	1496 cc	Power Rating:	22.0 kW
Maximum Power Output:	101.0 kW (135 bhp)		
Unladen Weight:	1190 kg	Maximum Laden Weight:	1465 kg
Primary Colour:	Silver	Secondary Colour:	-
First Registration Date:	31 May 2018	Original Registration Date:	31 May 2018
Manufacturing Year:	2017	Open Market Value:	\$21,593.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$2,500.00
No. of Transfers:	0	Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$1,593.00 (140%)
Actual ARF Paid:	\$5,000.00		

Owner Particulars

Owner Name: FRANCIS TRANSPORT
 Owner ID Type: Business
 Owner ID: 53336293L
 Registered Address Type: HDB / HUDC
 Registered Block/House No.: 265D
 Registered Street Name: PUNGGOL WAY
 Registered Unit No.: # 13 - 348
 Registered Building Name: -
 Registered Postal Code: 824265
 COE No. / Expiry Date: 2018060103000890G / 30 May 2028
 COE Bid Category: B - Car above 1600cc or 97kW (130bhp)
 QP Paid: \$38,501.00

10. 1128491429

Transaction Details

Business Transaction Ref. No.: 20180531110028493062
 Business Transaction Date: 31 May 2018
 Business Transaction Time: 11:00:28

Message

The above vehicle has been successfully registered.

Please note that \$34,062.00 will be deducted from your GIRO account.

OK

Save as PDF

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05918

Vehicle Insured : SHC2248D
Accident Date : 25-Jan-2019

Date : 29-Jan-2019

Our Ref : 219017 (FIRST) / CHAN

PAGE : 1

FRANCIS TRANSPORT
265D PUNGGOL WAY
#13-348
Singapore 824265

Not Authorized

Resurvey B4 paint

10 days

ESTIMATED COST OF REPAIR FOR HONDA SHUTTLE HYBRID 1.5A SMA2782D

1 pc	Tail gate		Rm	1,193.40	✓
1 pc	Tail gate inner lock		DW	207.10	✓
1 pc	Tail gate rubber		Dis/lt	188.50	✓
1 pc	Tail gate glass moulding		Mm	120.00	✓
1 pc	Tail gate outer garnish			383.10	? SNC X
1 pc	Tail gate logo			24.32	? RM X
2 pcs	Tail gate lamp	ols cm @ S\$340.80	Mm	681.60	✓
1 pc	Tail gate "SHUTTLE" emblem		Mm	55.00	✓
1 pc	Tail gate "HYBRID" emblem		Mm	80.10	✓
1 pc	Tail gate inner trim		Bm	350.10	✓
2 pcs	Taillamp	ols cm @ S\$528.50		1,057.00	✓
1 pc	O/s taillamp corner panel		Rm	240.20	✓
1 pc	End panel		Rm	590.80	✓
1 pc	End panel top garnish		DW	155.50	✓
1 pc	End panel antennal sensor(out)			115.00	? DM ✓
2 pcs	Rear fender inner trim cover	@ S\$455.40	ols	910.80	Bm ✓
1 pc	Rear bumper fascia		Rm	1,150.60	✓
2 pcs	Rear bumper side retainer	@ S\$ 37.80	Sm	75.60	X
2 pcs	Rear bumper reflector	@ S\$ 45.00		90.00	? o/s mtg cm
2 pcs	Rear bumper reflector cover	@ S\$ 66.50	ols/Rm	133.00	✓
1 pc	Rear bumper tow cover		Mm	19.50	✓
2 pcs	Rear bumper side screw	ols/Rm @ S\$ 9.50		19.00	✓
8 pcs	Rear bumper clip	@ S\$ 3.90	Mm	31.20	✓
2 pcs	Rear bumper sponge	@ S\$ 56.60		113.20	? LRA ✓
1 pc	Rear floor panel		BT/Am	956.00	✓
1 pc	Floor panel lower member			135.00	? Bt ✓
1 pc	Floor panel centre member			255.00	? X R
1 pc	O/s floor panel side extension			255.00	? Bt ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC2248D

Page : 2

1 pc Floor panel top garnish
1 pc Floor ppanel inner tray
1 pc Inner tray rear cover
1 pc O/s rear extension top cover
1 pc Rear battery cover

CM 355.00 ✓
CM 295.00 ✓
P/I 95.00 ✓
Return 125.00 ✓
R 375.00 X

10,830.62

Less 20% : 2,166.12

1 pc Rear bumper reverse sensor(set
1 pc Rear w/s glass sealant
1 pc Rear no.plate with box
1 pc Rear reverse camera

8,664.50 2001n
R 300.00 sn
R 401n 60.00 sn
R 455n 50.00 sn
SVC 300.00 sn ?X

(B/I) 100.00 ? ✓

To towing on wheel

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 1201

To remove roof lining, front and
rear seats, trim board and carpet

120.00 1001

To apply undersealing

100.00 901

To remove and refix exhaust
silencer box

80.00 601

To putty and spray replaced parts

1,200.00 11001

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,400.00 12001

Total : S\$12,524.50

=====

12927.06

Singapore Dollars Twelve Thousand Five Hundred
and Twenty Four and Cents Fifty Only

Kg

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05918

Accident Date : 25-Jan-2019

Date : 29-Jan-2019

Our Ref : 219017 (FIRST) / CHAN

PAGE : 1

FRANCIS TRANSPORT
265D PUNGGOL WAY

#13-348

Singapore 824265

Not Authorized

Preserving B4 point

10 days

===== REPAIR FOR HONDA SHUTTLE HYBRID 1.5A SMA2782D =====

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1 pc	Tail gate			
1 pc	Tail gate inner lock			
1 pc	Tail gate rubber			
1 pc	Tail gate glass moulding			
1 pc	Tail gate outer garnish			
1 pc	Tail gate logo			
2 pcs	Tail gate lamp			
1 pc	Tail gate "SHUTTLE" emblem			
1 pc	Tail gate "HYBRID" emblem			
1 pc	Tail gate inner trim			
2 pcs	Taillamp			
1 pc	O/s taillamp corner panel			
1 pc	End panel			
1 pc	End panel top garnish			
1 pc	End panel antennal sensor(out			
2 pcs	Rear fender inner trim cover			
1 pc	Rear bumper fascia			
2 pcs	Rear bumper side retainer			
2 pcs	Rear bumper reflector			
1 pc	Rear bumper reflector cover			
1 pc	Rear bumper tow cover			
2 pcs	Rear bumper side screw			
8 pcs	Rear bumper clip			
2 pcs	Rear bumper sponge			
1 pc	Rear floor panel			
1 pc	Floor panel lower member			
1 pc	Floor panel centre member			
1 pc	O/s floor panel side extension			

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC2248D

Page : 2

- 1 pc Floor panel top garnish
- 1 pc Floor ppanel inner tray
- 1 pc Inner tray rear cover
- 1 pc O/s rear extension top cover
- 1 pc Rear battery cover

CM 355.00 —
CM 295.00 —
PI 95.00 —
reform 125.00 —
R 375.00 X

Less 20% :

10,830.62
2,166.12

8271.50
1654.38
6617.52

- 1 pc Rear bumper reverse sensor(set
- 1 pc Rear w/s glass sealant
- 1 pc Rear no.plate with box
- 1 pc Rear reverse camera

8,664.50 200sn
300.00 sn
40sn 60.00 sn
45sn 50.00 sn
300.00 sn X
(Btl) 100.00 30

To towing on wheel

150.00 120

To remove & refix rear windscreen glass and conduct water leak test.

120.00 100

To remove roof lining, front and rear seats, trim board and carpet

100.00 90

To apply undersealing

80.00 60

To remove and refix exhaust silencer box

1,200.00 1100

To putty and spray replaced parts

1,400.00 1200

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

Total : S\$12,524.50
=====

Singapore Dollars Twelve Thousand Five Hundred and Twenty Four and Cents Fifty Only

P 6617.52

S.P 402.56

SN 285.00

L 2770.00

Kenward Pte
Contractors

10075.08 ✓ok

12927.06

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC2248D (FIRST)

Date : 31-01-2019

Accident Date : 25-01-2019

Our Ref : 219017 / CHAN

FRANCIS TRANSPORT

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR HONDA SHUTTLE HYBRID 1.5A SMA2782D

1 PC	REAR BATTERY AIR DUCT	<i>nd</i>	\$235.00 ✓
1 PC	TAIL GATE LOWER POCKET	<i>nd</i>	\$28.00 ✓
1 PC	REAR N/S TAILLAMP CORNER PANEL	<i>R</i>	\$240.20 ✓
			\$503.20
		LESS 20%	\$100.64
			<u>\$402.56</u>

Singapore Dollars Four Hundred Two And Cents Fifty Six Only



Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403
 Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com
 Business Reg. No: 53349344K

24 Hours Towing Services

NO. 25292

CASH SALE / JOB ORDER

Date: 28/1/2019

Messrs:

ALAN'S UNITED AUTO PTE LTD

车牌

Vehicle No. SWE5762D

车型

Model No: HONDA BURNING HIDE-ND

时间 (日/夜)

Time (day/night): Day

联络号码

Contact No: 904 7369

由

Location: To compound

到

To: B&T Towing Ltd Sector C D-76

银额

Cash \$ 100

其他

Others: accident

经手人

Authorised By: D1

Tow Truck Driver Name: Thana 307

注意: 本公司对所拖之车辆, 在進行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Recovery
- ☐ Multi-Basement
- ☐ With Load/Cargo Box
- ☒ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

E. & O. E.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19002049/Kqd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2248D	Veh. Inspected	SMA 2782D
Policy No.		Coverage (\$)	0.00
Claim No.	D19000715MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	30/01/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71211098	Colour	METALLIC SILVER
Odometer	39229	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	7 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	7 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/01/2019	Inspection Date	30/01/2019
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 2782D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE	BENT	1,193.40	1,193.40
1	TAIL GATE INNER LOCK	DENTED	207.10	207.10
1	TAIL GATE RUBBER	DISTORTED / CUT	188.50	188.50
1	TAIL GATE GLASS MOULDING	NECESSARY	120.00	120.00
1	TAIL GATE OUTER GARNISH	SERVICEABLE	383.10	-
1	TAIL GATE LOGO	NOT NECESSARY	24.32	-
2	TAIL GATE LAMP @\$340.80	O/S CRACKED	681.60	340.80
1	TAIL GATE "SHUTTLE" EMBLEM	NECESSARY	55.00	55.00
1	TAIL GATE "HYBRID" EMBLEM	NECESSARY	80.10	80.10
1	TAIL GATE INNER TRIM	BUCKLED	350.10	350.10
2	TAILLAMP @\$528.50	O/S CRACKED	1,057.00	528.50
1	O/S TAILLAMP CORNER PANEL	BENT	240.20	240.20
1	END PANEL	BENT	590.80	590.80
1	END PANEL TOP GARNISH	DENTED	155.50	155.50
1	END PANEL ANTENNA SENSOR (OUT)	DENTED	115.00	115.00
2	REAR FENDER INNER TRIM COVER @\$455.40	O/S BUCKLED	910.80	455.40
1	REAR BUMPER FASCIA	BENT	1,150.60	1,150.60
2	REAR BUMPER SIDE RETAINER @\$37.80	SERVICEABLE	75.60	-
2	REAR BUMPER REFLECTOR @\$45.00	O/S MTG CRACKED	90.00	45.00
2	REAR BUMPER REFLECTOR COVER @\$66.50	O/S DENTED	133.00	66.50
1	REAR BUMPER TOW COVER	MISSING	19.50	19.50
2	REAR BUMPER SIDE SCREW @\$9.50	O/S DENTED	19.00	9.50
8	REAR BUMPER CLIP @\$3.90	NECESSARY	31.20	31.20
2	REAR BUMPER SPONGE @\$56.60	CRACKED	113.20	113.20
1	REAR FLOOR PANEL	BENT / BUCKLED	956.00	956.00
1	FLOOR PANEL LOWER MEMBER	BENT	135.00	135.00
1	FLOOR PANEL CENTRE MEMBER	TO REPAIR SEE LABOUR	255.00	-
1	O/S FLOOR PANEL SIDE EXTENSION	BENT	255.00	255.00
1	FLOOR PANEL TOP GARNISH	CRACKED	355.00	355.00
1	FLOOR PANEL INNER TRAY	CRACKED	295.00	295.00

Report Ref No. CS/FC119002049/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	INNER TRAY REAR COVER	DISTORTED	95.00	95.00
1	O/S REAR EXTENSION TOP COVER	DEFORMED	125.00	125.00
1	REAR BATTERY COVER	TO REPAIR SEE LABOUR	375.00	-
1	REAR BATTERY AIR DUCT (ADDITIONAL)	DENTED	235.00	235.00
1	TAIL GATE LOWER POCKET (ADDITIONAL)	DENTED	28.00	28.00
1	REAR N/S TAILLAMP CORNER PANEL (ADDITIONAL)	BENT	240.20	240.20
	LESS 20% DISCOUNT		-2,266.76	-1,755.02
			9,067.06	7,020.08
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	DENTED	300.00	200.00
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR NO PLATE WITH BOX (SN)	DENTED	50.00	45.00
1	REAR REVERSE CAMERA (SN)	SERVICEABLE	300.00	-
			710.00	285.00
	LABOUR			
	TO TOWING ON WHEEL.		100.00	100.00
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET.		120.00	100.00
	TO APPLY UNDERSEALING.		100.00	90.00
	TO REMOVE AND REFIX EXHAUST SILENCER BOX.		80.00	60.00
	TO PUTTY AND SPRAY REPLACED PARTS.		1,200.00	1,100.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FLOOR PANEL CENTRE MEMBER AND REAR BATTERY COVER.		1,400.00	1,200.00
	-		-	-
	-		-	-
	-		-	-
			3,150.00	2,770.00
	GRAND TOTAL		12,927.06	10,075.08

Report Ref No. CS/FCI19002049/Kqd3n2



RECOMMENDED COST OF REPAIRS			10,075.08
-----------------------------	--	--	-----------

Report Ref No. CS/FCI19002049/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.