

ASS. REC. BY:

REF:

CS/FCI19002063/And3ⁿ²

Special Instruction:

Surveyor:
CWS

Adrian

ASSIGNMENT (Office)

From (Person):

May Chua

of

FCI

Date/Time 9:24am @ 31/1/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

9M 8898L

Insured:

SHC 8060M

at Workshop m/s

New Hock Teck

Tel:

67479241

of

1 Kaki Bukit Ave 6 # 01-43 Autobay

Policy No:

Claim No:

D19000777 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/01/2019

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

9:31am @ 31/1/19

Person Contacted:

Sukyi

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	9M 8898L - X
	SHC 8060M - NS/INC 14016228/1/14m3x3 BVA: 20/8/2014
01/02/19	@ 14:41 p.m. revert pricing estimate to May via email.
27/2/19	Adrian confirmed LS \$5500 (Red 6089.50, 5416)
27/2/19	Email preli revised to FCI

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SJM8898L Yr Regn: 2010 JulyType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 523i c.c. 2497Colour: Black A/C: Insured / Std / NI / NASp. Reading: 170384 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAFP32050C544767Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRip / STD A/Rim orTyre Size: F: 245/45R18R: 245/45R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mmD.O.A. _____ D.O.I. 31/01/19Survey held at NHTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 27 FEB 2019

Note: MV: 401C (EST)PV: 29.7kNett: 10.3k

Date/Time, File Pass to?

1) 57/3 - typist

3) _____

5) _____

Prel. Report:

Final Report:

Date/Time, File Return to?

2) _____

4) _____

6) _____

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

170 + 155025260



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000777MFSH

Our ref: CS/FC19002063/Avd3

Date : 27/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJM 8898L


We thank you for your instruction on 31/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31/1/2019 at the premises of M/s NEW HOCK TECK MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$11,289.50
Revised Estimate Amount	: S\$5,200.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-01-2019	Our Ref No. D19000777MFSH
Accident Date	29-01-2019	Claim Type. Third Party
Insured Vehicle	SHC8060M	Third Party Vehicle. SJM8898L
Survey Location	1 KAKI BUKIT AVE 6 BLK C #01-43 AUTOBAY@KAKI BUKIT	
Contact Person.	SUKYI CHONG	
Contact No.	67479241/ 0	Fax No. 67417276
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	NEW HOCK TECK MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 27 February 2019 11:31 AM
To: Shirley Hiew (LKK Auto); 'May Chua Hui Chin'; 'CWS Motor Claims'
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D19000777MFSH/1, SJM 8898L
Attachments: SJM 8898L PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJM 8898L
Date of survey: 31/1/2019
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 1 February 2019 2:41 PM
To: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000777MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SJM 8898L on 31/01/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Thursday, 31 January 2019 9:33 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19000777MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 31 January 2019 9:24 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000777MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 1 February 2019 2:41 PM
To: 'May Chua Hui Chin'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19000777MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SJM 8898L on 31/01/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 31 January 2019 9:33 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000777MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 31 January 2019 9:24 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin

<maychua@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000777MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Triple Crown Winner of the Premium Dealer Award
Save big & enjoy \$800 shopping vouchers with every purchase.

[Learn more](#)

Select
By Performance Premium Selection

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Wish 1.8A

2.88% P.A. Lowest Interest @ GV
Cars Financing \$3800
Downpayment Monthly From \$698
GV Credit Pte Ltd - StarAd

HIN LUNG AUTO
HoBee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

[Browse by Category](#)
[Save Search](#)
[Print](#)
[Sort by Date Posted](#)
[20 results/page](#)

18 vehicles

Search 5 Series 523i [Advanced Search](#) [Search](#) [View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	5 Series 523i	Any	Any	2010	Any	Any	Any	Any	Available
	BMW 5 Series 523i Highline	\$43,500	\$16,160 /yr	21-May-2010	2,497 cc	150,000 km	Luxury	Available	
Original Grey With Dark Grey Interior, Non-smoker Owner, Well Maintained Exterior And Interior By Owner, With PML Records Available, Accident-free. Highline Model, Luxurious And Spacious Cabin. For Yo...									
Car Empire Automobiles Pte Ltd									
★ Posted: 03-Jan-2019 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW									
	BMW 5 Series 523i	\$48,888	\$22,330 /yr	08-Jun-2010	2,497 cc	-	Luxury	Available	DIRECT OWNER
PML Unit, Excellent Condition, One Of The Best Maintained And Reliable 6 Cylinder Naturally Aspirated Engine 523i In The Market, Car Has Been Regularly Service.									
★ Posted: 16-Jan-2019 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW									
	BMW 5 Series 523i	\$41,800	\$15,300 /yr	25-Jun-2010	2,497 cc	-	Luxury	Available	CONSIGNMENT
Luxurious And Sporty 523i Executive Sedan, Nice Bidded Plate, Regularly Serviced, Pristine Condition. For That Responsive, Smooth, Quiet, And Powerful Drive, With Luxurious And Spacious Cabin To Ensur...									
Car Search									
★ Posted: 09-Jan-2019 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW									
	BMW 5 Series 523i	\$42,999	\$17,350 /yr	28-Jun-2010	2,497 cc	-	Luxury	Available	
No Gimmicks! Price Negotiable, Low Mileage Done, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call Now For Viewing.									
★ Posted: 25-Jan-2019 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW									
	BMW 5 Series 523i (New 10-yr COE)	\$79,900	\$7,980 /yr	29-Jun-2010	2,497 cc	90,000 km	Luxury	Available	
1 Owner Only! 100% Genuine Super Low KM Done! Fully Service By PML From Day 1 Till Current To Prove! Just Done Major Service At 88K! Car Totally In Very Good Running Condition! Engine Super Smooth & G...									
★ Posted: 11-Jan-2019 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW									
	BMW 5 Series 523i (New 10-yr COE)	\$71,500	\$7,140 /yr	30-Jun-2010	2,497 cc	92,000 km	Luxury	Available	
Only \$71.5K! Guaranteed Lowest Price BMW 523i Available. PML Agent Unit. High ARF OF \$42,678! Genuine Low Mileage Of 92K KM Only.Zero Repairs. Silky Smooth Engine. Zero Vibrations. Just Spent \$2,000+T...									
★ Posted: 19-Jan-2019 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW									
	BMW 5 Series 523i (New 10-yr COE)	\$79,900	\$7,980 /yr	30-Jun-2010	2,497 cc	100,000 km	Luxury	Available	
1 Owner Only! Company Expat Director Usage Only! 100% Genuine Super Low KM Done With Proof To Show! Interior Like New! Steering Wheel Like New! Engine Block Like New! No Oil Stain! Drive Like New! Sup...									
★ Posted: 21-Dec-2018 Tags: 2010 BMW 523i, 2010 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW									

[Compare \[4 \]](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4752I
Vehicle Details	
Vehicle No.:	SJM8898L
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jan 2019
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT D/AB 2WD 4DR GAS/D NAV SR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	05257463N52B25AF
Chassis No.:	WBAFP32050C544767
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$43,334.00
Original Registration Date:	22 Jul 2010
First Registration Date:	22 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$43,334.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jul 2020
PARF Rebate Amount:	\$23,833.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$39,911.00
COE Rebate Amount:	\$5,890.00
Total Rebate Amount:	\$29,723.00

The information contained herein is correct as at 29 Jan 2019

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

Admin - first capital

30/01/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 1st Cap.

Veron.

Accident date: 29/01/2019

Estimated repair cost for vehicle no: SJM8898L BMW 523i 2.5 A '10

CHASSIS: WBAFP32050C544767

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Door <i>Dented</i>		\$1,774.50 ✓
2	2	Front R/H Door Hinge <i>new</i>	\$116.30	\$232.60 ✗
3	1	Front R/H Door Inner Lock <i>Dented</i>		\$287.75 ✓
4	1	Front R/H Door Inner Rubber <i>new</i>		\$168.85 ✓
5	1	Front R/H Door Frame Sticker		\$62.90 ✓
6	1	Front R/H Door Outer Handle Cover With Chrome <i>Dented</i>		\$594.00 ✓
7	1	Front R/H Door Outer Handle Bracket Assy <i>new</i>		\$164.25 ✗
8	2	Front R/H Door Outer Handle Rubber Seal <i>new</i>	\$102.40	\$204.80 ✓
9	1	Front R/H Door Glass Outer Moulding <i>new</i>		\$115.95 ✓
10	1	Front R/H Door Side Mirror Assy <i>Repair</i>		\$1,831.00 ✗
11	1	Rear R/H Door <i>Dented</i>		\$1,774.50 ✓
12	1	Rear R/H Door Inner Lock <i>new</i>		\$287.75 ✗
13	1	Rear R/H Door Inner Rubber <i>new</i>		\$168.85 ✓
14	1	Rear R/H Door Frame Sticker		\$162.80 ✓
15	1	Rear R/H Door Outer Handle Cover With Chrome		\$594.00 ✗
16	1	Rear R/H Door Outer Handle Bracket Assy <i>new</i>		\$164.25 ✗
17	2	Rear R/H Door Outer Handle Rubber Seal	\$102.40	\$204.80 ✗
18	1	Rear R/H Door Glass Outer Moulding <i>new</i>		\$115.95 ✓

Subtotal :- \$8,909.50

5430.85

5159.30

Labour charges

To remove & refit front R/H door, glass, moulding, lock, rubber, trim board & frame sticker

~~\$240.00~~ 100

To remove & refit rear R/H door, glass, moulding, lock, rubber, trim board & frame sticker

~~\$240.00~~ 100

To reset computer

~~\$200.00~~ 100

To check wiring

~~\$100.00~~ 30

Panel beating

~~\$750.00~~ 500

Spray painting

~~\$850.00~~ 550

Subtotal :- \$2,380.00

Total:- \$11,289.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 6539.30
A/S: 5.2K
05 Days.

SK
5.2K
05 Days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19002063/Avd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 01-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8060M	Veh. Inspected	SJM 8898L
Policy No.		Coverage (\$)	0.00
Claim No.	D19000777MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	31/01/2019

2. Vehicle Particulars & Condition

Make & Model	BMW 523i	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBAFP32050C544767	Colour	BLACK
Odometer	170384	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R18	MICHELIN	6 mm
L/H Front Tyre	245/45 R18	MICHELIN	6 mm
R/H Rear Tyre	245/45 R18	MICHELIN	6 mm
L/H Rear Tyre	245/45 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/01/2019	Inspection Date	31/01/2019
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 8898L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT R/H DOOR	DENTED	1,774.50	1,774.50
2	FRONT R/H DOOR HINGE @\$116.30	NOT NECESSARY	232.60	-
1	FRONT R/H DOOR INNER LOCK	DAMAGED	287.75	287.75
1	FRONT R/H DOOR INNER RUBBER	NECESSARY	168.85	168.85
1	FRONT R/H DOOR FRAME STICKER	NECESSARY	62.90	62.90
1	FRONT R/H DOOR OUTER HANDLE COVER WITH CHROME	DAMAGED	594.00	594.00
1	FRONT R/H DOOR OUTER HANDLE BRACKET ASSY	NOT NECESSARY	164.25	-
2	FRONT R/H DOOR OUTER HANDLE RUBBER SEAL @\$102.40	NECESSARY	204.80	204.80
1	FRONT R/H DOOR GLASS OUTER MOULDING	NECESSARY	115.95	115.95
1	FRONT R/H DOOR SIDE MIRROR ASSY	TO REPAIR SEE LABOUR	1,831.00	-
1	REAR R/H DOOR	DENTED	1,774.50	1,774.50
1	REAR R/H DOOR INNER LOCK	NOT NECESSARY	287.75	-
1	REAR R/H DOOR INNER RUBBER	NECESSARY	168.85	168.85
1	REAR R/H DOOR FRAME STICKER	NECESSARY	162.80	162.80
1	REAR R/H DOOR OUTER HANDLE COVER WITH CHROME	NOT NECESSARY	594.00	-
1	REAR R/H DOOR OUTER HANDLE BRACKET ASSY	NOT NECESSARY	164.25	-
2	REAR R/H DOOR OUTER HANDLE RUBBER SEAL @\$102.40	NOT NECESSARY	204.80	-
1	REAR R/H DOOR GLASS OUTER MOUDLING	NECESSARY	115.95	115.95
	LESS 5% DISCOUNT		-	-271.54
			8,909.50	5,159.31
LABOUR				
	TO REMOVE & REFIT FRONT R/H DOOR, GLASS, MOULDING, LOCK, RUBBER, TRIM BOARD & FRAME STICKER.		240.00	100.00
	TO REMOVE & REFIT REAR R/H DOOR, GLASS, MOULDING, LOCK, RUBBER, TRIM BOARD & FRAME STICKER.		240.00	100.00
	TO RESET COMPUTER.		200.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING.		100.00	30.00
	PANEL BEATING INCLUSIVE OF THE REPAIR OF FRONT R/H DOOR SIDE MIRROR ASSY.		750.00	500.00
	SPRAY PAINTING.		850.00	550.00
			2,380.00	1,380.00
GRAND TOTAL			11,289.50	6,539.31
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CS/FCI19002063/Avd3n2

MARKET VALUE: \$40,000.00 (EST)-PAPER VALUE: \$29,700.00=NETT VALUE: \$10,300.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.