

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

ESTIMATE

EST. No EST0021422
Kow Eng Whatt Timothy

Page 1 of 1
Your ref. TP-SHD 9868M AXA
Job No. 70210
Our ref. 19.01.46
Payment
Date 31/1/2019

Attn

Vehicle No SFX 2293K
Vehicle Model : Citroen C4
Accident on ... 28/1/2019

Not Authorized

Resurvey B4 paint

5 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear sport rim RH (Original - 17")	1,699.70		1,699.70 <i>1500</i>
1.00	Pc	Rear door outer handle with knob RH	300.97		300.97 <i>300</i>
1.00	Pc	Rear door RH	1,607.60		1,607.60 <i>1600</i>
Labour & Misc:					
1.00		To check wheel alignment (computerised)	80.00		80.00 <i>600</i>
1.00		To check/clear fault codes	80.00		80.00 <i>✓</i>
1.00		Tuff coat	40.00		40.00 <i>300</i>
1.00		To knock dents on rear fender RH and renew of parts	600.00		600.00 <i>540</i>
1.00		To spray paint (blend front door RH)	900.00		900.00 <i>660</i>

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer *SS* 5 308.27
Signature: 371.58
5 679.85

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."