

REF: CS/HLA19002073/Asd352

Special Instruction:

US: \$ 10050.00

From (Person): Tracy Tan of HL Assurance Date/Time: 28/12/19
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: Prudent Adjustors

Workshop: 3D printing parts

OD(FP Re-inspection) / Evaluation

To Inspect Vehicle No: SLR 6005R Insured: SKA 171111

at Workshop m/s JD motorsports Tel: 9237 3644

of No. 25 Kaki Bukit Rd 4 #06-38

Policy No: _____ Claim No: mpc00988

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09-10-2018

(Client's Record)

01-02-2019 (Friday) @ 2pm

H.O.D. Enrolment/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 22/02/19 Confirmed with Richard Final Fig 4.9k, 06 days (Red \$5/50/5/%; Original 10 days)

Date/Time: _____ Submit Final Fig _____, _____ days (Red \$ _____ / _____ %; Original _____ days)

Date/Time	Action/Instruction
	SLA 6005R - X
	SKA 1744U - (CU / ERI) 5018548 / Phoebe?
	DA: 09/10/2018
	Confirmed with Phoebe direct billing to HL Assurance.

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

RECEIVED 26 FEB 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

<i>Fee Charged:</i>	
---------------------	--

Basic & Add

Transport

Photos

Others

Total

Date: _____

171

5E

34

87

33

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SLW600SR • Yr Regn: 2017 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

G.C

1498

Colour:

White

A/C

Insured / Std / NI / NA

Sp. Reading

25186

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22A8H0167424

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

01/02/19.

Survey held at

ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Reinspection.

Date/Time, File Pass No?

☐

Preli. Report

(1)

☐

Final Report

Date/Time, File Return to?

(2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

) \$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp. (\$

☐

Interview. (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Catherine Chong (LKK Auto)

From: phoebe@jpknights.com
Sent: Monday, 28 January, 2019 10:35 AM
To: assignments@lkkauto.com; Olivialau@lkkauto.com
Cc: Anil Kumar; HL Claims
Subject: FW: YOUR REF: MPC00998 (SKA1744U) & OUR REF: TCLAN.50393.18.JDM - ACCIDENT INVOLVING SLQ6005R & SKA1744U ON 09/10/18
Attachments: 2505_001.pdf; 2504_001.pdf; 2503_001.pdf; 2502_001.pdf; 2501_001.pdf; 2911_001.pdf; 4469_001.pdf

Dear Olivia,

We act on behalf of our principal, HL Assurance to handle their motor claims. We would like to appoint your surveyor, Mr Adrian Ling to conduct the physical reinspection as single joint expert.
Thank you.

Dear Anil,

Please provide the details of the appointment.
Thank you.

Kind Regards,
Phoebe Jay Xie

JP KNIGHTS PTE LTD | 33 UBI AVE 3 #05-47 VERTEX TOWER A SINGAPORE 408868 | CO REG: 200723763Z
Tel: (65) 6345 0068 | Fax: (65) 6344 5328 |
www.jpknights.com; www.aspectus.sg



Confidential: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Adrian.

Catherine Chong (LKK Auto)

From: Ronnie Tay <wei_845@outlook.com>
Sent: Monday, 28 January, 2019 11:46 AM
To: Catherine Chong (LKK Auto)
Subject: Re-inspection for SLQ 6005 R

Dear Catherine,

As spoken through tele-conversation, the re-inspection for the above mentioned vehicle will be on 1st February 2019 @ 1400 hours. Kindly revert for confirmation.

Best Regards,

Ronnie Tay

JD Motorsports PTE LTD

No. 25 Kaki Bukit Road 4
#06-38 Synergy@KB
Singapore 417800
HP: 92373644 Fax: 64514516

Disclaimer: This e-mail (and any attachment) is intended for the addressee(s) only and may contain information that is legally privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication and its contents is strictly prohibited. If you have received this email in error, please notify us immediately by return email and delete the document. This communication has not been transmitted via a private or secure link or in encrypted form and is therefore subject to the hazards of Internet communications, nor can it be guaranteed that this communication has not been the subject of unauthorised modification.

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L


Hp 96699986

INVOICE

Mr. Hu Hongfei
C/o JD Motorsports Pte Ltd
25 Kaki Bukit Road 4
06-38 Synergy @ KB
Singapore 417800

Invoice No : PA/18110010/tpw
Our Ref : PA/SLQ6005/0918/tpw
Date : 12 November 2018

Claim Type	Third Party	Date of Accident	09 October 2018
Vehicle No.	SLQ 6005 R	Date of Inspection	15 October 2018
No	Description		Amount (S\$)
1	Survey fees inclusive of Transportation and Photographs (81) copies		\$681.00
		Total	\$681.00
Singapore Dollar: Six Hundred And Eighty One Only			
All payments made payable to : Prudent Adjustors Services			


Prudent Adjustors Services

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L

Hp 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Hu Hongfei
C/o JD Motorsports Pte Ltd
25 Kaki Bukit Road 4
06-38 Synergy @ KB
Singapore 417800

Our Ref : PA/SLQ6005/1018/tpw
Date : 12 November 2018

REFERENCES

Claim Type	: Third Party	Date of Accident	: 09 October 2018
Vehicle No.	: SLQ 6005 R	Date of Assignment	: 15 October 2018
Make	: Mazda	Date of Inspection	: 15 October 2018
Model	: Mazda3 sedan 1.5AT LED	Date of Re-inspn.	: 17 October 2018
Reg. Date	: 17 July 2017	Chassis No	: JM6BN22A8H0167424
Color	: White	Engine No	: Blocked
Odometer	: 20088 km		

TYRE CONDITION

	<u>Front near side</u>	<u>Front off side</u>	<u>Rear near side</u>	<u>Rear off side</u>
Make	Toyo	Toyo	Toyo	Toyo
Size	205/60 R16	205/60 R16	205/60 R16	205/60 R16
Thread Balance	5 mm	5 mm	6 mm	6 mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at rear portion

Please refer to photographs and assessment of repairs for details

Enclosed (81) photographs depicting damage to the vehicle

Original Quotation : \$ 14,560.46

Revised Assessment **\$10,050.00 Lump sum**

Survey conducted at JD Motorsports Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Ten (10) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note:

The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
Reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: **SLQ 6005 R**

Our Ref: PA/SLQ6005/1018/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description Material	Qty	Condition	Original Quotation	Revised Quotation
1	Rear bumper	1 pc	Deformed	1,511.40	1,511.40 ¹⁹⁵
2	Rear bumper side retainer @ \$76.10/-	2 pcs	Bent	152.20	152.20 ✓
3	Rear bumper reflector @ \$90/- ^{not Repld}	2 pcs	Hdr cracked	180.00	180.00 ⁵³⁸
4	Rear bumper reinforcement	1 pc	Dented	764.40	764.40 ✓
5	Rear end panel ^{Repair}	1 pc	Dented	706.80	706.80 x
6	Rear end panel top garnish ^{not Repld}	1 pc	Deformed	174.70	174.70 x
7	Boot lid	1 pc	Repair	1,410.00	~ x
8	Boot lid logo	1 pc	Necessary	126.00	126.00 x
9	Boot lid emblem Mazda 3 ^{2 not Repld}	1 pc	Necessary	87.60	87.60 x
10	Boot lid emblem sky active ^{1 not Repld}	1 pc	Necessary	99.60	99.60 x
11	Front bumper	1 pc	Deformed	992.90	992.90 ✓
12	Front bumper side retainers @ \$66.90/-	2 pcs	Necessary	133.80	133.80 ✓
13	Front bumper bracket @ \$85.60/-	2 pcs	Bent RH ^{5191.80}	171.20	85.60 ✓
14	Front bumper reinforcement	1 pc	Bent ^{4153.44}	565.60	565.60 ✓
15	Front bumper lower grille ^{not Repld}	1 pc	Cracked	147.50	147.50 x
16	Front no. plate garnish ^{not Repld}	1 pc	Deformed	67.28	67.28 x
17	Front grille	1 pc	Cut	422.00	422.00 ✓
18	Front grille logo	1 pc	Cut	68.80	68.80 ✓
19	Headlamp assy @ \$1157.90/-	2 pcs	Scratched RH	2,315.80	1,157.90 ✓
				10,097.58	7,444.08
List price less 20%				2,019.52	1,488.82
				8,078.06	5,955.26
<u>Add special nett item</u>					
20	Front bumper clips	1 set	Necessary	43.70	43.70 ✓
21	Rear bumper clips	1 set	Necessary	43.70	43.70 ✓
22	Front number plate	1 pc	Scratch	55.00	50.00 ✓
23	Rear bumper reverse sensors	4 pcs	Malfunction	600.00	500.00 ²⁰⁰
				742.40	637.40

337.40

PRUDENT ADJUSTORS SERVICES

Vehicle No: **SLQ 6005 R**

Our Ref: **PA/SLQ6005/1018/tpw**

(Front Labour)

Remove-refit, panel beat, straighten
re-align support panel, bonnet headlamps
And all relevant accident damages.

800.00 ~~600.00~~ **400**

To check wiring & re-focus headlamps

120.00 ~~100.00~~ **30**

To putty and spray painting charges.

800.00 ~~600.00~~ **250**

1,720.00 1,300.00

(Rear Labour)

to remove-refit, cut-weld, panel beat,
re-align and repair of rear boot lid
rear spare tyre panel and rear fenders

1,500.00 ~~1,200.00~~ **400**

To remove & refit rear boot compartment
upholstery, garnish

180.00 150.00 **X**

To check wirings, including re-install
Of reverse sensors.

200.00 ~~180.00~~ **50**

To applied rear end panel sealant,
including reseal & water proof test

180.00 160.00 **X**

To applied anti rust treatment to affected
panel

160.00 100.00 **X**

To putty and spray painting charges.

1,800.00 ~~1,500.00~~ **500**

4,020.00 3,290.00


Total parts & labour concluded

14,560.46 **11,182.66**

Lump sum repair adjustment

10,050.00

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services
Bok Jee Tan

> Back to OneMotoring**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 6533C

Vehicle Details

Vehicle No.: SLQ6005R
Vehicle to be Exported: Yes
Intended Deregistration Date: 15 Oct 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 SEDAN 1.5 AT LED EU6
Primary Colour: White
Manufacturing Year: 2017
Engine No.: P520459138
Chassis No.: JM6BN22A8H0167424
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$19,406.00
Original Registration Date: 17 Jul 2017
First Registration Date: 17 Jul 2017
Transfer Count: 0
Actual ARF Paid: \$14,406.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Jul 2027
PARF Rebate Amount: \$10,804.00

Intended COE Rebate Details

COE Expiry Date: 16 Jul 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,801.00
COE Rebate Amount: \$34,240.00
Total Rebate Amount: \$45,044.00

The information contained herein is correct as at 15 Oct 2018

OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HL ASSURANCE PTE LTD		Ref : CS/HLA19002073/Asd3s2		
11 KEPPEL ROAD #11-01 ABI PLAZASINGAPORE 089057		Date : 26-02-2019		
		Code : HLA		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SKA 1744U	Veh. Inspected	SLQ 6005R	
Policy No.		Coverage (\$)	0.00	
Claim No.	MPC00988	Excess (\$)	0.00	
Assign From	TRACY TAN	Assign Date	28/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0167424	Colour	WHITE	
Odometer	25186	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60R16	TOYO	6 mm	
L/H Front Tyre	205/60R16	TOYO	6 mm	
R/H Rear Tyre	205/60R16	TOYO	6 mm	
L/H Rear Tyre	205/60R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	09/10/2018	Inspection Date	01/02/2019	
Survey held at	JD MOTORSPORTS PTE LTD 25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 6005R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	REPLACED	1,511.40	1,075.00
2	REAR BUMPER SIDE RETAINER @ \$76.10	REPLACED	152.20	152.20
2	REAR BUMPER REFLECTOR @ \$90.00	NOT CHANGED	180.00	-
1	REAR BUMPER REINFORCEMENT	REPLACED	764.40	538.00
1	REAR END PANEL	REPAIRED SEE LABOUR	706.80	-
1	REAR END PANEL TOP GARNISH	NOT CHANGED	174.70	-
1	BOOT LID	REPAIRED SEE LABOUR	1,410.00	-
1	BOOT LID LOGO	NOT CHANGED	126.00	-
1	BOOT LID EMBLEM MAZDA 3	NOT CHANGED	87.60	-
1	BOOT LID EMBLEM SKY ACTIVE	NOT CHANGED	99.60	-
1	FRONT BUMPER	REPLACED	992.90	992.90
2	FRONT BUMPER SIDE RETAINER @ \$66.90	REPLACED	133.80	133.80
2	FRONT BUMPER BRACKET @ \$85.60	O/S REPLACED	171.20	85.60
1	FRONT BUMPER REINFORCEMENT	REPLACED	565.60	565.60
1	FRONT BUMPER LOWER GRILLE	NOT CHANGED	147.50	-
1	FRONT NO. PLATE GARNISH	NOT CHANGED	67.28	-
1	FRONT GRILLE	REPLACED	422.00	422.00
1	FRONT GRILLE LOGO	REPLACED	68.80	68.80
2	HEADLAMP ASSY @ \$1157.90	O/S REPLACED	2,315.80	1,157.90
	LESS 20% DISCOUNT		-2,019.52	-1,038.36
			8,078.06	4,153.44
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	REPLACED	43.70	43.70
1	SET REAR BUMPER CLIPS (SN)	REPLACED	43.70	43.70
1	FRONT NUMBER PLATE (SN)	REPLACED	55.00	50.00
4	REAR BUMPER REVERSE SENSORS (SN)	REPLACED	600.00	200.00
			742.40	337.40

Report Ref No. CS/HLA19002073/Asd3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE-REFIT, PANEL BEAT, STRAIGHTEN RE-ALIGN SUPPORT PANEL, BONNET HEADLAMPS AND ALL RELEVANT ACCIDENT DAMAGES.		800.00	400.00
	TO CHECK WIRING & RE-FOCUS HEADLAMPS.		120.00	30.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		800.00	250.00
	TO REMOVE-REFIT, CUT-WELD, -PANEL BEAT, RE-ALIGN AND REPAIR OF REAR BOOT LID REAR SPARE TYRE PANEL AND REAR FENDERS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR END PANEL.		1,500.00	400.00
	TO REMOVE & REFIT REAR BOOT COMPARTMENT UPHOLSTERY, GARNISH.	NOT NECESSARY	180.00	-
	TO CHECK WIRINGS, INCLUDING RE-INSTALL OF REVERSE SENSORS.		200.00	50.00
	TO APPLIED REAR END PANEL SEALANT, INCLUDING RESEAL & WATER PROOF TEST.	NOT NECESSARY	180.00	-
	TO APPLIED ANTI RUST TREATMENT TO AFFECTED PANEL.	NOT NECESSARY	160.00	-
	TO PUTTY AND SPRAY PAINTING CHARGES.		1,800.00	500.00
			5,740.00	1,630.00
GRAND TOTAL			14,560.46	6,120.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,900.00

Report Ref No. CS/HLA19002073/Asd3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.