

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 18.25856 PD-O Date: 06th March 2019

Our Ref: CS3/ASM18015224/T1sd3s2-1

M/s AXA Insurance Pte Ltd

C/o: Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLL 1935R INSURED VEHICLE: YP 4408B ACCIDENT DATE: 18/06/2018

We thank you for your instruction on 30/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLL 1935R from M/s Vicom Ltd.
- b) Final Repair Bill of SLL 1935R from M/s Teamwork Garage Pte Ltd.
- c) Singapore Accident Statement of Vehicles SLL 1935R and YP 4408B.
- d) Colour damaged vehicle photographs of SLL 1935R.

Pre-Repair Inspection Date: 21/08/2018 at M/s Teamwork Garage Pte Ltd, 53 Ubi Avenue 1 #01-24 Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

Information Recorded: -

Registration Number

: SLL 1935R

Make & Model

: Honda Shuttle

Year of Registration

: 2017

Chassis Number

: GK81006146

Engine Capacity

: 1496 cc

- We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.