(08/11/13) wef REF: CC3 MSG 1900-	2103/UVd3n2
ASS. REC. BY: Maries	14574/
ASSI	GNMENT CONTRACTOR OF CONTRACTO
From: Date:	Veh No: SKN 25 TofCyr Regn: 5/14
Estimated Cost	Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / FP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or A/
To Inspect Vehicle No: SKN 2526C	Make: Manda Fif c.c 1317
at Workshop m/s	Colour Lata-Ce A/C: Insured / Std / NI / NA
of	Sp.Reading 6/097 T/Radio: Insured / Std / NI / NA
6 2 5 0 0 0 0 2	Eng/No:
0-1	C/No: 6K33000.963
T 911- FC	Gen. Cond/Good/Fair/Poor/Burnt
5.85 (4.95 (4.95))	Steering: Ing depl Jammed / Leaked / Burnt or
TO SECURE SECURE	Brake: Morder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / S/Rim / STD A/Rim or
Make of Veh:	190/0 2
	Tyre Size: F: // J / J / J / J / J / J / J / J / J /
(Policy Condition)  Remark: The yeb had commenced its  N/S O/S	K.
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
i cepail at the time of mapestion.	TOYO/YOKO or
Bal. or Market Value:	Front R/Bal R/Bal mm
IDAG Accident Rport Consistent? : Yes or No	100
Consistent? : Yes or No	7 / 1
Est. Repairs:	D.O.A. 30/1/19 D.O.I. 3/1/19
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT  Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	^ N
CNY 274 38695 h	ene 6.9 5.155.4 nd Dez 9 months
nert \$163011	
1219 Email GIA to Eiler	RECEIVED 0 7 MAR 2019
1/3/01/2010 - 11/1	wh Alm (Red 35,030.30, 789) 12019
6/5/19 0/5 \$ 10,000 an fund	070 1700 (Red 35,035.30, 1191)
Date/Time, File Pass to? : Preli. Report	Days Of Repair:   2
i) : Final Report	Resurvey No. of Trip: 2 Survey Fee:
Date/Time, File Return to?	Transportation:
2) 7/3- typist Add Fe	
The second secon	: Interview (\$) Photos
Report Format: merimen	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 10,000 2	: Weekend (\$
	TOTAL >60

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

	BFOLDER TRA	Est Submitted	Adt Assigned	Adt Rot	Adj Submitted	Ins Auth ed	Status
Case	Notified	ESC SUBTRICES					Pending for Survey
Surespect	01 Feb 2019		07 Feb 2019 11:17				Report
Main 16:17	16:17		process and the second	1			Cancel Case
	16:17		Edit Adj Rpt				Cancel Ca

Ma	Reference	Claim Details	Document	s S	how All
CLATM SUBF	OLDER DETAILS		[Created by insurer]		
Insured:	GEE YOKE LIN, ID: S1459135D				
Main Claimant:	TAN LI CHENG MELISSA (CHEN LIQING N	MELISSA), ID: S7919592			
Vehicle Reg. No.:	SKN2528C	Date of Loss:	[56 Months and 3 Days Fit		n Yr)]
Claim Type:	TP / 584058	Policy/Cover Note No.:	80455299AT2 (Comprehen- Coverage: 21/03/2018 - 20	sive) 0/03/2019	
Vehicle Reg. No. (Insured):	SCE9989B	Policy No. (Claimant):			
(insured).		Excess:	S\$3,500.00		
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Av	re 6, #01-46/48/50 Autobay,	, 417883 Kaki Bukit - Tel: 67	465405	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (H	IQ) - Tel: +65 6827 7888	[Handled by Muhd Ashik B	Madi - 6594 2548]	2/2010
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel:	6256-3561 [Handled by	MARCUS CHUA] [1mm.	Advice due 00/0	12/2015
Driver/Custo dian (Insured):	LOW CHEE HONG, HENRY ( / Male) , NRIC	: S9831918B Email:			
ASSOCIATE	D MAIL RECEIVED			View All Compose	Case Ma
There are no	mall for this case.				
ALL ASSOC	IATED TASKS		View All Search Tasks	Create New Task	Complet
	Priority Type Task Group Sub	ject Handler Assig	ned By Completed Or	Created On	Done

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Muhd Ashik B Madi

Date: 07 Mar 2019

#### Preliminary Advice

Insured Vehicle No : SCE9989B

TP Vehicle No

: SKN2528C

: HONDA FIT

Date of Inspection : 31/1/2019

Accident Date

Assignment Date

: 30/01/2019 : 07/02/2019

Est. Duration of Repair : 12

: FASTECH AUTO PTE LTD Inspection At

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,022.30
Revised Amount	:S\$	10,000.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,000.00
HITTERS W. W. C.		

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Friday, 1 February 2019 3:10 PM

To:

Eileen Ang

Cc:

SUR; KKLau; Accounts (LKKAuto)

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA:

30/01/2019, SKN 2528C (TP VEHICLE), SCE 9989B (OI VEHICLE)

Attachments:

GIA.pdf

Dear Eileen,

Please be informed that we had inspected the vehicle SKN 2528C at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 31/1/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Ways of Selling

honda fit

Model

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

## Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house? Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Advertiser Login

V

Make

honda fit

Classic Promo!Best Deal!Fast Selling!Hurry Down Now



Flexible Loan, Trade In Are Welcome: 100% Refund For Unapproved Loan, Classic Credit StarAd



Search Selection

Post an Ad

Browse by Category

1 vehicles

Honda Fit 1.3A G

\$46,000

Any

Price

\$8,080 /yr

Depreciation

Arry

19-Jun-2014

Reg Date

2014

1.317 cc

Eng Cap

Any

Mileage

Sort by Date Posted

Advanced Search 🔣

Veh Type

Submit

Available

Status

✓ 20 results/page ✓

Hatchback Sporty White, One Owner Only, Low Mileage Done, Low Fuel Consumption, Low Maintenance Cost, Very Well Maintained, Flexible In House Loan

Available

Packages Available. Prime Motor & Leasing

Posted: 17-Jan-2019 Tags: 2014 Honda Fit, 2014 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

20 v results/page

For old advertisements, view Expired ads

Home New Cars Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used honda fit, honda fit Singapore, used honda fit, used vehicles Singapore or even buy used honda fit, singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

#### Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

### SGEARMART.COM

Used Cars

Sell My Car

Directory

**Products** 

Insurance

Articles

F

Login 5

SUPREME

**New Cars** 

## NEW CARS | PRE-LOVED CARS | INSURANCE

FIT

Price Range

Depreciation

2013

Vehicle Type

Map

Share

٧

Photos

More Actions

Home » Used Cars » Urban Motors Pte Ltd » Honda Fit 1.3A G

#### Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



#### Honda Fit 1.3A G

Research Accessories Similar Overview **Financial** Insurance Add a Note Report Error Add to Shortlist Add to Compare Car Details Price \$46,800 Depreciation \$8,800 /yr View models with similar depreciation Reg Date 25-Nov-2013 (4yrs 9mths 23days COE left) 0 Manufactured 2009 85,000 km (16.4k /yr)

Transmission Auto 1,339 cc **Engine Cap** \$590 /yr Road Tax

73.0 kW (97 bhp) Power

View specs of the Honda Fit (2008-2013)

**Curb Weight** 1,010 kg

Features

Mileage

Accessories

\$932 Per Month. Good Condition. Flexible Loan Description

Package. Instant Approval. Ex Bankrupt Welcome. High

Trade In.

\$8,892

0 \$74,991 COE

0 \$13,892 OMV 0

\$42,323 as of today (change) Dereg Value

2 No. of Owners

ARF

Type of Veh Hatchback

PARF Car Category

Available Availability

> Add to Compare Add to Shortlist

Posted on: 20-Jan-2019 | Last Updated on: 20-Jan-2019

Add a Note





0

0

0









#### Seller Information

Urban Company » deale » 2 veh 19 Tank Address Search

Office No

Gary O Contact Person(s) Dan

#### Useful Services



Afraid of lem this car evalu Vehicle E

68411:

## > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** Vehicle Owner Particulars Singapore NRIC Owner ID Type: 9592H Owner ID: Vehicle Details SKN2528C Vehicle No.: No Vehicle to be Exported: 31 Jan 2019 Intended Deregistration Date: HONDA Vehicle Make: FIT 1.3G CVT ABS D/AIRBAG 2WD 5DR Vehicle Model: White Primary Colour: 2013 Manufacturing Year: L13B3100905 Engine No.: GK33000963 Chassis No.: 73.0 kW (97 bhp) Maximum Power Output: \$13,788.00 Open Market Value: 27 May 2014 Original Registration Date: 27 May 2014 First Registration Date: 0 Transfer Count: \$5,000.00 Actual ARF Paid: Intended PARF Rebate Details Yes PARF Eligibility: 26 May 2024 PARF Eligibility Expiry Date: \$3,750.00 PARF Rebate Amount: Intended COE Rebate Details 26 May 2024 COE Expiry Date: A - Car up to 1600cc & 97kW (130bhp) COE Category: 10 COE Period(Years): \$65,689.00 QP Paid: \$34,945.00 COE Rebate Amount: \$38,695.00 Total Rebate Amount:

The information contained herein is correct as at 31 Jan 2019

OK

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- at of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

<ol> <li>By the loagement of this report to the insurers, you aforesaid.</li> </ol>	u rigrepy consent to the districting of this report of the control	
	ACCIDENT STATEMENT	
Date Of Report	30/01/2019 16:54	
Date Of Accident	30/01/2019 15:50	
Exact Location Of Accident	ALONG PIE TWRDS CHANGI	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKN2528C	
Insured/Policyholder		
Name Of Registered Owner	TAN LI CHENG MELISSA (CHEN LIQING MELISSA)	
NRIC No	S7919592H	
Email Address	NOEMAIL	

(LOCAL) +65-97970260 Mobile Phone No OTHERS-97970260 Alternative Phone No

**Vehicle Particulars** 

HONDA Manufacturer

FIT 1.3G CVT ABS D/AIRBAG 2WD 5DR Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR Vehicle Category

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

COMPREHENSIVE Type Of Coverage

Fleet Policy

5065672821-04 Policy Number

Cover Note Number

Driver

TAN LI CHENG MELISSA (CHEN LIQING MELISSA) Name of Driver

S7919592H NRIC No 04/07/1979 Date Of Birth INDOOR Occupation Date Of Driving Pass 29/04/2000

18 YEARS AND 9 MONTHS **Driving Experience** 

FEMALE Gender

(LOCAL) +65-97970260 Mobile Number

Fax Number

OTHERS-97970260 Contact Number

NOEMAIL EMail Address

Address

BLK 79D #21-55 TOA PAYOH CENTRAL

Postcode

314079

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SCE9989B

Vehicle Make/Model/Colour

TOYOTA COROLLA ALTIS 1.6L CVT

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2** 

Vehicle Registration Number

**GBC9767Y** 

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

COMMERCIAL VEHICLE

#### Accident Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

3 0 JAN 2019

1DAC KAKI BUKIT(VAC) 23 KAKI BUKIT AVE 4

Singapore 415933
Reporting Centre Personnel's Signature
CE: 67416697

Name: Fax: 67492305 NRIC/FIN No.: Email: vackb@singnet.com.sg

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

KETCH PLAN	hala d			
				SKN 2528
		A	6	68C9767
on the stated		1 time, 1	was drivit	ny my
nehale A chi	y PIE to	wards changi	. In trust	of the
noticle stop.	& Leine	suit, sud,	denly & fe	lit an
impart from	selfend, the	n I reusti	gred that u	eliles
J		ause my		
and hit on	venule	C. There	were 3 ce	ns imported
in an audr	at.			
DECLARATION  I/We declare the foregoing particular			A I JAI	0.053

Policyholder's Signature Date & Time:

Mules

Oriver's Signature (If driver is not the policyholder)

Date & Time:

3 0 JAN 2013

IDAC KAKI BUKIT (VAC)

23 KAKI BUKIT AVE 4

Singapore 415933

Reporting Centre Perspandistatione
Name: Fax: 67492305

NRIC/FIN Namail: vackb@singnet.com.sg

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Not Adhorar 10,000/ 12 12 17.

Qty Particular SKN2528C		Amount S\$
List Item:		
1PCS REAR WINDSCREEN MOULDING	Nec	\$68.50
1PCS TAILGATE 707.00	Bookly 20	\$718.20
1PCS TAILGATE FIT EMBLEM	nu	\$32.90
1PCS TAILGATE INNER LOCK	DOM	\$145.50
1PCS TAILGATE LOCK STRIKER	11	\$68.20 🗴
1PCS TAILGATE INNER TRIM BOARD	De/cre	\$232.60
1SET TAILGATE INNER TRIM BOARD CLIPS	w	\$45.00
1PCS TAILGATE OUTER GARNISH	11	\$288.20 🐰
	11	\$38.20 ×
1PCS TAILGATE 'H' LOGO	11	\$625.30 X
1PCS TAILGATE REAR WIPER MOTOR	(ng	\$765.00
2PCS TAILLAMPS @\$382.50	66 850	
1PCS REAR BUMPER	7.5	\$493.70
2PCS REAR BUMPER SIDE RETAINERS @\$22.50	Berg	
1SET REAR BUMPER CLIPS	rec	\$39.00
2PCS REAR BUMPER SIDE GARNISHES @\$48.50	MSTM	\$97.00 186
1PCS TAILGATE WEATHERSTRIP	Yw1	\$92.30
2PCS REAR REVERSE SENSORS @\$185.00	Shed	\$370.00 2005.2
1PCS TAILLAMP HOUSING PANEL N/S	PO/Bin	\$ \$166.20
2PCS REAR FENDER N/S @\$845.30	1	\$1690.60 🗶
2PCS REAR FENDER INNER TRIM BOARD @\$266.30	De Cone	\$532.60
2PCS REAR DOORS @\$765.30	11	\$1530.60 >
1PCS REAR FLOOR PANEL	Buc	\$845.20
1PCS REAR FLOOR PANEL TOP BOARD 20%	merzed	\$266.90

9196.70

1 Kaki Bukit Ave 6 #01-48 Autobay Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty Particular		Amount S\$
List Item:		
1PCS ROOF PANEL	11	\$869.20 ×
1PCS ROOF PANEL INNER LINING	11	\$766.30 🗴
1PCS FRONT DOOR N/S	11	\$785.20 ×
1PCS FRONT DOOR GLASS OUTER MOULDING N/S	11	\$52.30 ×
1PCS BONNET	77/3u(	\$433.60
2PCS BONNET HINGES @\$35.00	17	\$70.00 ×
1PCS BONNET LOCK	721	\$89.30
1PCS BONNET RUBBER SEAL	rec	\$18.60
1PCS FRONT BUMPER	20/101	\$523.50
1PCS FRONT BUMPER TOW COVER	11	\$15.00 X
1PCS FRONT BUMPER CENTRE GRILLE	10-1	\$95.60
2PCS FRONT BUMPER SIDE RETAINERS @\$20.50	Bert	\$41.00
IPCS FRONT grille outergoinish.	CNL	\$245.00
1PCS FRONT GRILLE	(~9	\$137.50
1PCS FRONT GRILLE LOGO	rec	\$28.80
2PCS HEADLAMPS @\$643.00	holdern	\$1286.00
2PCS HEADLAMP LOWER BRACKETS @\$28.80	cre	\$57.60
1PCS FRONT SUPPORT PANEL	Bullow	\$428.00
1PCS HORN UNIT	11	\$46.70 🗶
1PCS AIR CON CONDENSER	Berf/pun	\$762.80
2PCS AIR CON CONDENSER TOP BRACKETS @\$10.80	11	\$21.60 🎉
1PCS AIRCON COOLING PIPE	11	\$211.30 ×
1PCS AIR CON DISCHARGE PIPE	12	\$320.50 X
		7305.40

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 20-0006262-D

Oty Particular		Amount S\$
Qty Particular		
List Item:	2	\$185.60 X
1PCS REAR FLOOR PANEL SIDE MEMBER N/S	- 1	
1PCS REAR FLOOR PANEL TOOLS SPONGE 385.40	- '/	\$422.50
1PCS REAR END PANEL	300/gm	\$269.80
1PCS REAR END PANEL TOP GARNISH	tw1	\$60.80
1PCS REAR WINDSCREEN	11	\$1050.20 🗶
2PCS REAR TAILGATE INNER TOP SIDE GARNISH @\$112.50	11	\$225.00 🗶
IPCS REAR END panel locksensor 225.30	cna	\$464.80
2PCS REAR EXHAUST MOUNTING @\$20.50	11	\$41.00 🗲
1PCS REAR EXHAUST HEAT SHIELD	NA	\$64.50 >
1PCS REAR AIR VENT	11	\$26.00 X
2PCS REAR DOOR INNER TRIM BOARDS @\$301.30	11	\$602.60 ×
2PCS REAR DOOR INNER LOCKS @\$186.20	17	\$372.40 🗡
1PCS REAR DOOR GLASS OUTER MOULDING N/S	11	\$49.60 ×
2SET REAR DOOR FRAME STICKERS @\$20.00	11	\$40.00 ×
2PCS REAR DOOR HINGES N/S @\$65.40	11	\$130.80 }
2PCS REAR DOOR WEATHERSTRIP @\$166.20	$\wedge \wedge$	\$332.40 🗡
1PCS REAR BACK SEAT REST	11	\$688.30 🗶
1PCS REAR BACK SEAT BELT N/S	11	\$466.20 ×
2PCS REAR SHOCK ABSORBER @\$115.30	11	\$230.60 🌂
1PCS REAR WHEEL HUB BEARING N/S	~ ~	\$332.30 🗡
1PCS REAR AXLE BEAM	11	\$865.40 🗡
1PCS REAR QUARTER GLASS N/S	11	\$285.30 7
10001194-4701011154-1701114-1701114-170114-170114-170114-170114-170114-170114-170114-170114-170114-170114-1701		7206. HO

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty Particular	Amount S\$
List Item:	
1PCS AIR CON SUCTION PIPE	11 \$285.40 X
1PCS AIRCON FAN COWLING	17 \$91.00 X
1PCS AIRCON FAN MOTOR	1 1 \$266.50 X
1PCS AIRCON FAN BLADE	1 1 \$92.20 X
1PCS RADIATOR	17 \$1137.00 X
1PCS RADIATOR FAN	\$91.00 €
1PCS RADIATOR FAN MOTOR	1 1 \$354.60 °C
1PCS RADIATOR FAN COWLING	11 \$95.20 ×
2PCS RADIATOR TOP BRACKETS @\$10.80	11 \$21.60 X
1PCS RADIATOR TOP HOSE	11 \$23.50 X
1PCS RADIATOR SPARE TANK	17 \$66.30 X
2PCS FRONT FENDERS @\$352.20	1 \$704.40 X
2PCS FRONT FENDER INNER SHIELDS @\$69.30	17 \$138.60 X
1SET FRONT FENDER INNER SHIELD CLIPS	4~ \$45.00 Å
1PCS WASHER TANK	11 \$68.30 €
1PCS RELAY BOX	11 \$385.00 <sup>★</sup>
1PCS FRONT WIRE HARNESS	11 \$936.90 X
1PCS ALTERNATOR	11 \$780.50 义
1PCS ALTERNATOR BELT	4 ~ \$59.40 ×
1PCS AIR CLEANER BOX TOP	17 \$44.70 X
1PCS AIR CLEANER BOX BOTTOM	11 \$107.30 X
1PCS ENGINE INLET MANIFOLD	MA \$565.50 ×
THES ENGINE INTELLIMENT OF	6359.90
	<b>V</b>

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 20-0006262-D

Qty	Particular		8	Amount S\$
List Ite	em:			\$580.30 ×
1PCS	DASHBOARD	100		
1PCS	ENGINE UNDER COVER	207	11	\$63.60 ×
List It	em Total:			Ti de la companya de
Speci	al Nett Item:			1
1SFT	REAR REVERSE LAMERA		Should	\$280.00
	REAR LICENCE PLATE W/HOLDER		But	\$50.00 40
1PCS	REAR WINDSCREEN SEALANT		w	\$50.00 40
1PCS	REAR WINDSCREEN SOLAR FILM		11	\$200.00 🗶
1PCS	REAR QUARTER GLASS SEALANT		11	\$50.00 🗓
	S REAR SPORT RIM N/S		NA	\$380.00 ×
1PC	S REAR TYRE N/S		17	\$200.00 💢
	T REAR DOOR VISOR		11	\$100.00 ×
1PC	S FRONT LICENCE PLATE W/HOLDER		sul	\$50.00 40
1PC	S FRONT WINDSCREEN SOLAR FILM		17	\$200.00 ×
	L RADIATOR COOLANT		rec	\$50.00
Spe	cial Nett Total:			\$1610.00
Lab	our Charge:			
			11	\$150.00 🗴
TO	WING CHARGE KINGROLLER.			\$100.00 30
ТО	CHECK WIRING.			
ТО	DISMANTLE & REPLACING REVERSE SENSOR.			\$80.00
то	DISMANTLE & REPLACING REAR WINDSCREEN.			\$150.00 120
				2733.90

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty	Particular		Amount S\$
Labour	Charge:		
TO DIS	MANTLE & REFIX REAR SEAT , CUSHION UPHOLSTERY.		\$300.00 [00
то со	NDUCT WHEEL ALIGNMENT.	11	\$100.00 🗶
TO DIS	MANTLE & REPLACING REAR UNDERCARRIAGE.	11	\$380.00 🗴
TO DIS	MANTLE & REFIX PETROL TANK.		\$100.00 60
то мо	OUNT VEHICLE ON CAR-O-LINER.	11	\$380.00 🗴
TO DIS	SMANTLE & REPLACING QUARTER GLASS N/S.	11	\$100.00 🏸
TO TR	ANFER REAR DOOR MECHANISM.	11	\$180.00 \( \mathcal{T} \)
TO RE	FILL AIR CON GAS.		\$150.00 100
TO DIS	SMANTLE & REFIX FRONT ENGINE ,GEAR BOX FOR FACILITA	TE	
REPAI	R FRONT CHASSIS.	11	\$500.00
TO DI	SMANTLE & REPLACING FRONT WINDSCREEN.	$\wedge \wedge$	\$150.00 ×
TO SP	RAY ANTI RUST PROOFING.		\$200.00 120
TO DI	SMANTLE & REPLACING FRONT DASHBOARD.	^^	\$380.00 X
TO DI	SMANTLE & REPLACING FRONT AIR BAG & REPROGRAMME	. ^^	\$500.00 ×
LABO	UR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLAC	ING PARTS.	\$5000.00 /800
	JTTY & SPRAY PAINTING.		\$3800.00 /800
	ur Charge Total:	12,220	\$12,700.00
	56 (19) 4 4 20 <b>35</b> 200 200 200 200 200 200 200 200 200 20		- TAL -

45,022.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/MSG19002103/UVD3N2

Date:

08/03/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

80455299AT2

Claimant Vehicle No :

SKN2528C

Insured Vehicle No:

SCE9989B

Date of Loss:

30/01/2019

Nature of Claim:

TP

Claim No: 584058

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SKN2528C

Make & Model: Reg. Date: HONDA FIT, 1.3 GF CVT (A) 27/05/2014 (Man. Year: 2013)

Engine No: Chassis No: Odometer: L13B3100905 GK33000963

61097 km

Colour:

White

Engine Capacity: Market Value/New Car 1317 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): CONDITION OF TYRES Yes Engine Modification:

No Pre-accident Condition:

195/55R15

Front Tyre Size: Front Left Side: 195/55R15

Rear Tyre Size: Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,322.00	8,338.40	23,983.60	74.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,700.00	4,180.00	8,520.00	67.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,022.00	12,518.40	32,503.60	72.19
Approved Total (Overridden) (S\$)		10,000.00	39	
(S\$)	45,022.00	10,000.00	35,022.00	77.79
+ GST 7.00/7.00% (S\$)	3,151.54	700.00	2,451.54	77.79
Nett Amount (S\$)	48,173.54	10,700.00	37,473.54	77.79

INSPECTION

Date of Assignment:

07/02/2019

Date Inspected:

31/01/2019 Inspected At:

Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair:

12.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 08 Mar 2019)

Parts:

143

HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKN2528C)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

		mended Parts Part No. Particulars	Condition	Repairer's	Amount
	2	*REAR WINDSCREEN MOULDING	Necessary	68.50 F	*68.50 FL
1	1	*TAILGATE	Badly Dented	718.20 F	*703.00 FL
2	1	*TAILGATE	Necessary	32.90 F	*32.90 FL
3	1	*TAILGATE INNER LOCK	Dented/Jammed	145.50 F	*145.50 FL
4		*TAILGATE LOCK STRIKER	Not Necessary	68.20 F	*-FL
5 6	1	*TAILGATE INNER TRIM BOARD	Deformed/Cracked	232.60 F	*232.60 FL
		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	45.00 F	*45.00 FL
7 8	1	*TAILGATE OUTER GARNISH	Not Necessary	288.20 F	*-FL
9	1	*TAILGATE H LOGO	Not Necessary	38.20 F	*-FL
10	1	*TAILGATE REAR WIPER MOTOR	Not Necessary	625.30 F	*-FL
	2	*TAILLAMPS	Cracked	765.00 F	*765.00 FL
11	1	*REAR BUMPER	Distorted	493.70 F	*493.70 FL
12	2	*REAR BUMPER SIDE RETAINERS	Bent	45.00 F	*45.00 FL
13 14	1	*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
	-	*REAR BUMPER SIDE GARNISHES	N/s Twisted	97.00 F	*48.50 FL
15	1	*TAILGATE WEATHERSTRIP	Twisted	92.30 F	*92.30 FL
16		*TAILLAMP HOUSING PANEL N/S	Dented/Bent	166.20 F	*166.20 FL
17 18	1 2	*REAR FENDER N/S	Repair	1,690.60 F	*-FL
19	2	*REAR FENDER INNER TRIM BOARD	Deformed/Cracked	532.60 F	*532.60 FL
		*REAR DOORS	Not Necessary	1,530.60 F	*-FL
20	2	*REAR FLOOR PANEL	Buckled	845.20 F	*845.20 FL
21	1	*REAR FLOOR PANEL TOP BOARD	Warped	266.90 F	*266.90 FL
22		*REAR FLOOR PANEL SIDE MEMBER N/S	Repair	185.60 F	*-FL
23	1	*REAR FLOOR PANEL TOOLS SPONGE	Deformed/Torn	422.50 F	*385.40 FL
24		*REAR END PANEL	Badly Dented	269.80 F	*269.80 FL
25	1	*REAR END PANEL TOP GARNISH	Twisted	60.80 F	*60.80 FL
26	1	*REAR WINDSCREEN	Not Necessary	1,050.20 F	*- FL
27 28	2	*REAR TAILGATE INNER TOP SIDE GARNISH	Not Necessary	225.00 F	*-Fl
29	1	*REAR END PANEL LOCK SENSOR	Cracked	464.80 F	*225.30 Fl
30	2	*REAR EXHAUST MOUNTING	Not Necessary	41.00 F	*-FI
31	1	*REAR EXHAUST HEAT SHIELD	Not Necessary	64.50 F	*- FI
	1	*REAR AIR VENT	Not Necessary	26.00 F	*- FI
32	2	*REAR DOOR INNER TRIM BOARDS	Not Necessary	602.60 F	*-FI
33		*REAR DOOR INNER LOCKS	Not Necessary	372.40 F	*-F
34	2	*REAR DOOR GLASS OUTER MOULDING N/S	Not Necessary	49.60 F	*-F
35	1	*SET REAR DOOR FRAME STICKERS	Not Necessary	40.00 F	*-F
36	2	*REAR DOOR HINGES N/S	Not Necessary	130.80 F	*-F
37	2	*REAR DOOR WEATHERSTRIP	Not Necessary	332.40 F	*-F
38		*REAR BACK SEAT REST	Not Necessary	688.30 F	*-F
39		*REAR BACK SEAT BELT N/S	Not Necessary	466.20 F	*-F
40		*REAR SHOCK ABSORBER	Not Necessary	230.60 F	*-F
41		*REAR WHEEL HUB BEARING N/S	Not Necessary	332.30 F	*-F
42		*REAR AXLE BEAM	Not Necessary	865.40 F	*- F
43		*REAR QUARTER GLASS N/S	Not Necessary	285.30 F	*- F
44		Report was unsubmitted during	The state of the s		

lo.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
5	1		*ROOF PANEL	Not Necessary	869.20 F	*-FL
22.00	1		*ROOF PANEL INNER LINING	Not Necessary	766.30 F	*-FL
45.04	1		*FRONT DOOR N/S	Not Necessary	785.20 F	*-FL
17 18	1		*FRONT DOOR GLASS OUTER MOULDING N/S	Not Necessary	52.30 F	*- FL
I.I. A.	1		*BONNET	Dented/Buckled	433.60 F	*433.60 FL
19			*BONNET HINGES	Not Necessary	70.00 F	*-FL
50	2			Twisted	89.30 F	*89.30 FL
51	1		*BONNET LOCK	Necessary	18.60 F	*18.60 FL
52	1		*BONNET RUBBER SEAL		523.50 F	*523.50 FL
53	1		*FRONT BUMPER	Dented/Torn	07100000000000000000000000000000000000	*-FL
54	1		*FRONT BUMPER TOW COVER	Not Necessary	15.00 F	
55	1		*FRONT BUMPER CENTRE GRILLE	Torn	95.60 F	*95.60 FL
56	2		*FRONT BUMPER SIDE RETAINERS	Bent	41.00 F	*41.00 FL
57	1		*FRONT GRILLE OUTER GARNISH	Cracked	245.00 F	*245.00 FL
58	1		*FRONT GRILLE	Cracked	137.50 F	*137.50 FL
59	1		*FRONT GRILLE LOGO	Necessary	28.80 F	*28.80 FL
60	2		*HEADLAMPS	Holder Cracked	1,286.00 F	*1,286.00 FL
61	2		*HEADLAMP LOWER BRACKETS	Cracked	57.60 F	*57.60 FL
62	1		*FRONT SUPPORT PANEL	Bent/Twisted	428.00 F	*428.00 FL
63	1		*HORN UNIT	Not Necessary	46.70 F	*-FL
	355		*AIR CON CONDENSER	Bent/Punctured	762.80 F	*762.80 FL
64	1		*AIR CON CONDENSER TOP BRACKETS	Not Necessary	21.60 F	*-FL
65	2			5 G11 (1 P T T T T T T T T T T T T T T T T T T	211.30 F	*-FL
66	1		*AIRCON COOLING PIPE	Not Necessary	320.50 F	*-FL
67	1		*AIRCON DISCHARGE PIPE	Not Necessary		*-FL
68	1		*AIR CON SUCTION PIPE	Not Necessary	285.40 F	
69	1		*AIRCON FAN COWLING	Not Necessary	91.00 F	*-FL
70	1		*AIRCON FAN MOTOR	Not Necessary	266.50 F	*-FL
71	1		*AIRCON FAN BLADE	Not Necessary	92.20 F	*- FL
72	1		*RADIATOR	Not Necessary	1,137.00 F	*-FL
73	1		*RADIATOR FAN	Not Necessary	91.00 F	*-FL
74	1		*RADIATOR FAN MOTOR	Not Necessary	354.60 F	*-FL
75	1		*RADIATOR FAN COWLING	Not Necessary	95.20 F	*- FL
76	2		*RADIATOR TOP BRACKETS	Not Necessary	21.60 F	*- FL
77	1		*RADIATOR TOP HOSE	Not Necessary	23.50 F	*-FL
78	4		*RADIATOR SPARE TANK	Not Necessary	66.30 F	*-FL
			*FRONT FENDERS	Repair	704.40 F	*-FL
79 80	2		*FRONT FENDER INNER SHIELDS	Not Necessary	138.60 F	*-FL
			*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	45.00 F	*-FL
81	1		*WASHER TANK	Not Necessary	68.30 F	*-FL
82	1			Not Necessary	385.00 F	*-FL
83	1		*RELAY BOX		936.90 F	*-FL
84	1		*FRONT WIRE HARNESS	Not Necessary		*-FL
85	1		*ALTERNATOR	Not Necessary	780.50 F	*-FL
86	1		*ALTERNATOR BELT	Not Necessary	59.40 F	
87	1		*AIR CLEANER BOX TOP	Not Necessary	44.70 F	*- FL
88	1		*AIR CLEANER BOX BOTTOM	Not Necessary	107.30 F	*-FL
89	1		*ENGINE INLET MANIFOLD	Not Necessary	565.50 F	*-FL
90	1		*DASHBOARD	Not Necessary	580.30 F	*-FL
91	1		*ENGINE UNDER COVER	Not Necessary	63.60 F	*-FL
92	1		*SET REAR REVERSE CAMERA	Shorted	280.00 FS	*280.00 FS
93	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
94	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	*-FS
95 96	1		*REAR QUARTER GLASS SEALANT	Not Necessary	50.00 FS	
				Not Necessary	380.00 FS	*-FS
97	1		*REAR SPORT RIM N/S	Not Necessary	200.00 FS	
98	1		*REAR TYRE N/S		100.00 FS	
99	1		*SET REAR DOOR VISOR	Not Necessary		All and the second
100	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	
101	1		*FRONT WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	(4)
102	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*50.00 FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
103		*REAR REVERSE SENSORS	Shorted	370.00 FS	*200.00 FS
F=Fra	nchise	part. S=SpcNett. L=ListItemDisc.	Sub Total (S\$)	32,322.00	10,260.50
		- List Item Discount on L I			1,922.10
			Total Parts (S\$	32,322.00	8,338.40
		Report was unsubmitted during	g this print-out.		

### Recommended Miscellaneous Items There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			0.00
1	TOWING CHARGE KINGROLLER	New	150.00	0.00
2	TO CHECK WIRING	New	100.00	30.00
3	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
4	TO DISMANTLE & REPLACING REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX REAR SEAT, CUSHION UPHOLSTERY	New	300.00	100.00
6	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
7	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE	New	380.00	0.00
8	TO DISMANTLE & REFIX PETROL TANK	New	100.00	60.00
9	TO MOUNT VEHICLE ON CAR-O-LINER	New	380.00	0.00
10	TO DISMANTLE & REPLACING QUARTER GLASS N/S	New	100.00	0.00
11	TO TRANFER REAR DOOR MECHANISM	New	180.00	0.00
12	TO REFILL AIR CON GAS	New	150.00	100.00
13	TO DISMANTLE & REFIX FRONT ENGINE, GEAR BOX FOR FACILITATE REPAIR FRONT CHASSIS	New	500.00	0.00
14	TO DISMANTLE & REPLACING FRONT WINDSCREEN	New	150.00	0.00
15	TO SPRAY ANTI RUST PROOFING	New	200.00	120.00
16	TO DISMANTLE & REPLACING FRONT DASHBOARD	New	380.00	0.00
17	TO DISMANTLE & REPLACING FROTN AIR BAG & REPROGRAMME	New	500.00	0.00
18	LABOUR FOR PANEL BEATING, CUTWELD, STRAIGHTEN & REPLACING PARTS	New	5,000.00	1,800.00
19	TO PUTTY & SPRAY PAINTING	New	3,800.00	1,800.00
	Gross Labour Cost (S\$)		12,700.00	4,180.00
_	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >