

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0145/2019/PH
Date	:	

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Benjamin Matthews
Address	:	39 Bridport Avenue Singapore 559329
Telephone	:	HP +65 92382848
Type of Claim	:	Own Damage Claims
Policy No.	:	1700049946-01
Vehicle No	:	SKD 3803 D
Model Code	:	Audi Q7 2.0 TFSI QU
Model / Year	:	23/6/2017
Engine No	:	CYR 040891
Chassis No	:	WAUZZZ4M3HD053551
Mileage	:	24117 KM
Date In	:	28-Jan-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Jan-19
Place of Accident	:	CTE filtering into PIE Changi

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 3803 D

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 300.00 ✓
3	To remove and renew air con condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00 ✓
4	To dismantle and renew front bumper, bonnet, rhs front fender and rhs headlight. To repair rhs front door. Renew front lock carrier and align to position. Re-organise front crash management	\$ 6,400.00
5	To respray front bumper, front bumper spoiler, hinges, bonnet, rhs front fender, rhs front door and both front wheel arc covers.	\$ 5,000.00
6	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 13,572.00

$$680 \times 6.5 = 3800$$

~~3000~~

Shf.

$$4 \times 600 = 2400$$

$$2 \times 200 = 400$$

2750.2800

Shf.

2800

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 3803 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,242.00	OK ✓
1	FRONT BUMPER FIXING PARTS	\$ 403.00	OK ✓
2	COVER FOR TOWING EYE-ANTHRACITE	\$ 36.00	X
3	FRONT BUMPER AIR GUIDE - LH/RH	2 \$ 120.00	?
4	FRONT BUMPER END CAP - LH/RH	2 \$ 64.00	X
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	\$ 252.00	OK ✓
6	GRILLE ANTHRACITE - LOWER CENTRE	\$ 187.00	X
7	UNDERRUM BAR BARCELONETA SILVER	\$ 735.00	X
8	CLOSING ELEMENT	\$ 191.00	?
9	FRONT SPOILER-LH/RH	2 \$ 384.00	X
10	SPOILER - LH/RH OUTER	2 \$ 80.00	X
11	RADIATOR GRILLE	\$ 2,269.00	OK ✓
12	COVER FOR RADIATOR GRILLE	\$ 62.00	?
13	FRONT BUMPER COVER	\$ 56.00	OK ✓
14	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 271.00	?
15	FRONT BUMPER END CAP - RH	\$ 31.00	X
16	SPOILER - RH FRONT	\$ 55.00	X
17	FRONT BUMPER CARRIER	\$ 791.00	?
18	FRONT BUMPER GUIDE SECTION - RH	\$ 40.00	?
19	SUPPORT - RH/LH	2 \$ 66.00	?
20	FRONT BUMPER COVER	\$ 119.00	?
SUB - TOTAL SPARE PARTS		\$ 8,454.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 3803 D .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FOAM FILLER PIECE	\$ 156.00	?
22	FRONT BUMPER SENSOR	1.8 \$ 693.00	m.g. ✓
23	FRONT BUMPER SENSOR SEAL	4 \$ 12.00	re ✓
24	HORN - HIGH TONE RH	\$ 206.00	?
25	FRONT FENDER - RH	\$ 1,481.00	bt ✓
26	ATTACHMENT PARTS FOR FENDER	\$ 69.00	re ✓
27	FRONT FENDER BRACE - RH	\$ 94.00	bt ✓
28	WHEEL HOUSING LINER - RH	\$ 223.00	?
29	REAR WHEEL HOUSING LINER - RH	\$ 223.00	?
30	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 50.00	?
31	BONNET	\$ 4,511.00	bt ✓
32	ATTACHMENT PARTS FOR BONNET	\$ 89.00	re X
33	LID HINGE - LH/RH	2 \$ 152.00	?
34	BONNET STRUT	\$ 133.00	X
35	BONNET IMPACT PROTECTION - FRONT	\$ 97.00	re ✓
36	COVER FOR HEADLAMPS - LH/RH	2 \$ 186.00	re ✓
37	COVER - RH	\$ 40.00	X
38	STRIKER - LH/RH	2 \$ 218.00	?
39	BOWDEN CABLE - CENTER	\$ 53.00	bt ✓
40	LID LOCK WITH MICRO SWITCH	2 \$ 401.00	bt ✓
SUB - TOTAL SPARE PARTS		\$ 9,087.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 3803 D .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	FLAT CONNECTOR FOR LOCKING MECHANISM	\$ 12.00	?
42	LID LOCK CABLE	\$ 81.00	?
43	RELEASE LEVER	\$ 13.00	dis ✓
44	LED HEADLIGHT RH	\$ 9,074.00	che ✓
45	CONTROL UNIT FOR LIGHT CONTROL SYSTEM - RH	\$ 685.00	?
46	POWER MODULE FOR MAIN LIGHT ELECTRONICS	\$ 716.00	?
47	FAN FOR HEADLIGHT	\$ 363.00	?
48	MOUNTING FOR MAIN BEAM HEADLIGHT	\$ 107.00	che ✓
49	SIDE MEMBER	\$ 456.00	?
50	HEAD LIGHT WASHER LIFT CYLINDER - RH	\$ 181.00	?
51	WHEEL COVER - LH/RH	2 \$ 1,044.00	new ✓
52	LOCK CARRIER	\$ 1,100.00	che ✓
53	A/C CONDENSER	\$ 878.00	bt ✓
54	CHARGED AIR COOLER	\$ 855.00	bt ✓
55	COOLER FOR COOLANT	\$ 676.00	new ✓
56	COOLANT	4 \$ 84.00	new ✓
57	TWIN FAN RING	\$ 274.00	?
58	RADIATOR FAN WITH CONTROL UNIT-LH/RH	2 \$ 2,924.00	?
59	FRONT BUMPER AIR GUIDE - LH/RH	2 \$ 50.00	?
60	AIR GUIDE -UPPER/LOWER	2 \$ 74.00	fm ✓
61	FRONT NUMBER PLATE	S/N \$ 25.00	bt ✓
62	SUNDRIES	\$ 800.00	?
TOTAL SPARE PARTS		\$ 38,013.00	
TOTAL LABOUR CHARGES		\$ 13,572.00	
GRAND TOTAL		\$ 51,585.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpin 97445749
Not authorize
Ex: to be advise.
Resurvey before paint
10 days
s4v@lkkauto.com
2/2/19 @ 420 pm.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager



Allan Wu
Claims Consultant