

①

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHA5875J

DATE: 31. Jan. 2019

MAKE : HYUNDAI

MODEL : Sonata

DOA: 30. Jan. 2019

AXA

LS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper			\$538.80
10	Front Bumper Clips		\$2.20	\$22.00
1	Radiator Grille			\$282.10
SUB TOTAL				\$842.90
LESS 20%				\$168.58
DISCOUNTED TOTAL				\$674.32
1	Front Licence Plate			\$25.00
1	Front Licence Plate Casing			\$20.00
				\$45.00
Labour Charge				
1	Panel Beating			\$300.00
1	Spray Painting Charge(Fender,2Doors, Mirror)			\$300.00
TOTAL LABOUR				\$600.00
ESTIMATE TOTAL				\$1,319.32
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Larry Ng

X R  
X N N  
/ CRK

Nett / CR  
Nett / CR

200  
200

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 5875J

DATE 31/1/2019 16:07

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid			\$ 1,349.50	/BUC
	Boot Lid Lock Upper			\$ 132.10	/TAM
	Boot Lid Lock Lower			\$ 30.30	/TAM
	Boot Lid Sonata Plate			\$ 43.60	/NEC
	Boot Lid Hyundai Plate			\$ 24.20	/NEC
	Boot Lid 'H' Emblem			\$ 26.10	/NEC
	Boot Lid CRDI Plate			\$ 22.70	/NEC
	Boot Lid Lamp (LH/RH)		\$ 230.20	\$ 460.40	/CRK
	Rear Bumper			\$ 578.40	/LPR
	Rear Bumper Reinforcement			\$ 483.30	?
	Rear Bumper Clip			\$ 22.00	/NEC
	Rear Bumper Sponge			\$ 137.40	?
	Rear Bumper Under Cover			\$ 185.80	/DEF
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00	?
	Tail Lamp (LH/RH)		\$ 344.00	\$ 688.00	?
	Rear Panel			\$ 391.80	?
	Rear Panel Garnish			\$ 95.80	?
	Rear Fender (LH)			\$ 1,935.90	/DEF
	Rear Windscreen Moulding			\$ 60.00	/NEC
	<b>SUB TOTAL</b>			<b>\$ 6,743.30</b>	
	<b>LESS 20%</b>			<b>\$ 1,348.66</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 5,394.64</b>	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett / NEC
	Rear No. Plate			\$ 25.00	Nett ?
	Rear Bumper Reverse Sensor			\$ 135.70	Nett / NEC
	Rear Windscreen Sealant			\$ 46.00	Nett / NEC
				<b>\$ 236.70</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$ 1,200.00	600
	Spray Painting Charge			\$ 1,200.00	600
	Wiring Charge			\$ 30.00	/NEC
	Tuff Kote			\$ 50.00	/NEC
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	50
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80
	Remove/Refix Reverse Sensor			\$ 80.00	30
	<b>TOTAL LABOUR</b>			<b>\$ 2,830.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 8,461.34</b>	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Larry Ng