

ASS. REC. BY:

REF: es/CTI19002118/Dvd3^{sz}

Special Instruction:

Surveyor: 3m/nASSIGNMENT (Office)From (Person): MeimienIrene Tay

of

CTIDate/Time: 31/1/19 @ 4:54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JKK 828

Insured:

SMC 708Y

at Workshop m/s

Kairz worksRepairer: Team work

Tel:

9295 9989

of

53 ubi Ave 4 #02-24

Policy No:

DMPCSN 30716618000

Claim No:

SNM19D200545C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/01/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1/2/19 @ 9:18am

Person Contacted:

DarrenVehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

JKK 828 - XSMC 708Y - NA / CTI 19001912 / K4D.O.A: 28/1/19

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To: Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: JKK 828 Regn: 2007 August
 Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda Civic C.C. 1998

Colour: Blue Black A/C Insured / Std / NI / NA

Sp. Reading: 264629 T/Radio: Insured / Std / NI / NA

Eng/No: K20Z21921648

C/No: PMHFD26307D401652

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size: F: 215/45 R17

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 28/01/2019

D.O.I. 28/01/2019

Survey held at: Teknwork Peta Ubi

Des. of Damages: Frt ☒ Rear ☒ O/S / N/S / U/C / Rooftop or

Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Chine Eiping SMC 708Y

MV RM 37K SGD abt 12K

12/04/19 found 4/3 5000/- with 5 dgs. (Red 5584.96, 539)

RECEIVED 12 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 12/4 - typist

Report Format:

merimen

Lump Sum / I.B.I: (\$

5000/-

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. tips (\$

☐

Weekend (\$

Survey Fee:

Transportation

1) S + RS \$

2) Photos

3) Others

4) TOTAL

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2019		31 Jan 2019 16:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	MOHAMAD ZULSADHLI BIN MOHAMAD
Vehicle Reg. No.:	JKK828
Claim Type:	TP / SNM19D200545C02
Vehicle Reg. No. (Insured):	SMC708Y
	Excess: S\$0.00
Repairer:	Karz Work Solutions (HQ) 53 Ubi Avenue 1 #02-24, Paya Ubi Industrial Park, 408934 Eunos - Tel: 9295 9989
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/02/2019]
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 31 January 2019 4:42 PM
To: karzwork@gmail.com
Cc: assignments; Admin A
Subject: CTP REF NO. SNM19D200545C02 KZ REF NO. K1901-01 - ACCIDENT INVOLVING SMC708Y, PA5852E AND JKK828 ON 28 JANUARY 2019
Attachments: 20190131164128.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

As you have agreed to our list of surveyors.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with Karz Work Solutions .

Thank you.

Irene Tay

Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Angie Foo

Ime (S)

From: Karz Work Solutions <karzwork@gmail.com>
Sent: Tuesday, 29 January, 2019 11:58 AM
To: Claims Dept of CTI
Subject: OUR REF: K1901-01 // YOUR REF: SMC708Y ACCIDENT INVOLVING SMC708Y AND JKK 828 AND PA5852E
Attachments: 20190129115204654.pdf

WITHOUT PREJUDICE

OUR REF: K1901-01 // YOUR REF: SMC708Y

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR JKK828
ACCIDENT INVOLVING JKK828 AND SMC708Y AND PA5852E

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction – Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

1. Appoint LKK.

Regards,

Karz Work Solutions
53 Ubi Ave 1
#02-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 1130
Fax: 6844 2474

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

30 JAN 2019

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN

JKK828

No. Sijil **6770789**
db8Wof9K

Nama Pemunya
Berdaftar

JU-ICHI ENTERPRISE SDN BHD

82047-1
(SYT)

Alamat

NO 12 A JALAN SAHABAT 1 TAMAN EMAS KLUANG
86000 KLUANG JOHOR

No. Enjin

K20Z21921648

No. Chasis

PMHFD263070401662

Buatan

HONDA

Nama Model

CIVIC 2.0L I-VTEC (A)

Keupayaan Enjin

1998

Bahan Bakar

PETROL

Warna

HITAM

Keles. Kegunaan

PERSENDIRIAN-MOTOKAR SYARIKAT

Jenis Badan

MOTOKAR

Tahun Dibuat

2007

Tarikh Pendaftaran

23/08/2007

Status Pemunya

SYARIKAT/PERTUBUHAN

Muatan Tempai

5

Duduk

5

Kadar Lesen

6 bulan

12 bulan

Kenderaan Motor

379.00

758.00

B.G.M.B.G.K

B.T.T

Berat Kerp

B.T.M

B.G.1

B.G.2

B.G.3

B.G.4

B.G.5

B.G.6

B.G.7

B.G.8

B.G.9

B.G.10

B.G.11

B.G.12

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan

oleh Pengerah JPJ Negeri

STESAN PENGUATIHAN TERI LUNING

UNTUK KEGUNAAN PEJABAT

PEHANGGAL TEMPAT

NOTA PENTING

- Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).
- Semak butiran kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
- Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membatalkan lesen 60 hari sebelum tempohnya tamat.
- Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berfungsi.
- Jika anda menjual kenderaan, simpankan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan menyerahkan borang JPJ3, JPJ3A kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
- Pemunya berdaftar kenderaan adalah bertanggungjawab dengan setiap urusan berkaitan dengan kenderaan sehingga pertukaran lesen lesen disempurnakan dan kenderaan telah didaftarkan dengan lesen pemakainya.
- Jika alamat anda bertukar, kemudiannya berakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN

NO. PENDAFTARAN

JKK828

No. Sijil **6770789**
db8W019K

Nama Pemunya
Berdaftar

JU-1CH1 ENTERPRISE SDN BHD

82847-1
[SYT]

Alamat

NO 12 A JALAN SAHABAT 1 TAMAN EMAS KLUANG
86000 KLUANG JOHOR

No. Enjin **K20Z21921648**
No. Chasis **PMHFD26307D401652**
Buatan **HONDA**
Nama Model **CIVIC 2.0L I-VTEC (A)**
Keupayaan Enjin **1998**
Bahan Bakar **PETROL**
Warna **HITAM**
Kelas Kegunaan **PERSENDIRIAN-MOTOKAR SYARIKAT**
Jenis Badan **MOTOKAR**
Tahun Dibuat **2007**
Tarikh Pendaftaran **23/08/2007**
Status Pemunya **SYARIKAT/PERTUBUHAN**
Muatan Tempak
Duduk **5**
Kadar Lesen
Kenderaan Motor **6 bulan 12 bulan**
379.00 750.00

B D M B G K

B T T

Perat Kerb

B T M

B G 1

B G 2

B G 3

B G 4

B G 5

B G 6

B G 7

B G 8

B G 9

B G 10

B G 11

B G 12

Tandatangan Pemunya Berdaftar

Pendaftaran ini dilakukan
oleh Pengerah JPJ Negeri **STESIN PENKUALA NEGERI LALANG**

UNTUK KEGUNAAN PEJABAT

PEMANGKUAN TEMPATAN

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balak polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).
2. Semak butiran kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membekalkan lesen 60 hari sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ jika kenderaan anda tidak berlesen.
5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengesahkan borang JPJ/K3/JPJ/K3A kepada Pengerah JPJ dalam tempoh 14 hari dari tarikh penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran maklumat disempurnakan dan kenderaan telah didaftarkan dengan nama pemua baru.
7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

MSIG INSURANCE (MALAYSIA) BHD
NO 7 BANGUNAN HILA
JALAN YAYASAN
86000 KLUANG
JOHOR

Stamp Duty Paid

ENHANCED PRIVATE CAR INSURANCE POLICY

RENEWAL CERTIFICATE

Name of Insured	Policy Number
JU-ICHI ENTERPRISE SDN BHD	JK-87104260-MPC
NO.4B SECOND & THIRD FLOOR JALAN SENTOL SOUTH WING KLUANG PARADE 86000 KLUANG JOHOR DARUL TAKZIM	Account Number JKHL003A
	Period of Insurance
	From : 27/08/2018
	To : 26/08/2019
	(both dates inclusive)

Vehicle Registration No. : JKK828
Business Registration No. / NRIC No. : 82847-T
Business / Profession : RETAIL TRDG-GEN MERCHANDISE

Engine No. : K20Z21921648
Chassis No. : PMHFD26307D401652
Make : 111 HONDA
Model : 051 CR-V
Vehicle Description : HONDA CR-V 1-VTEC
Seating Capacity Including Driver : 5

Cover : COMPREHENSIVE
Vehicle Use : Private Car for Business Use
Log Book No. : 5310067
Cubic Capacity : 1,998 CC
Year of Manufacture : 2007
Excess (RM) : 0

Your Estimate Value Including Accessories	(RM) :	37,000.00
Basic Premium	(RM) :	1,122.09
No Claims Discount (55.0 %)	(RM) :	617.15
Optional Add-On Covers		
Windscreen (RM900.00)	(RM) :	135.00
Any Authorised Driver	(RM) :	50.00
Legal Liability of Passengers	(RM) :	7.50
Annual Premium	(RM) :	697.44
Premium After Discount	(RM) :	697.44
GST On Premium	(RM) :	0.00
Stamp Duty	(RM) :	10.00
AMOUNT DUE	(RM) :	707.44

Printed by 6749LWL1 on 26/07/2018

JK-87104260-MPC

Page 1



**SINGAPORE
POLICE FORCE**



T/20190128/2118

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

1 of 4

Report No. T/20190128/2118

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/01/2019 16:47		Vide Report No.:		Station Diary No.: 32	
Informant's Particulars					
Name of Informant: MOHD ZULFADHLI BIN MOHAMMED			Address: 111 JALAN TANJUNG FELDA BUKIT BATU , 81000 KULAI JOHOR		
ID Type / ID No.: NEW MALAYSIAN IC / 860921236043			Contact No.: Home/Office: Mobile: 0176279089		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 32	Date of Birth: 21/09/1986	Type of Informant: Driver		
Race: Malay			Language: Malay		Institution / School Name:
Occupation: PERSONAL DRIVER			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 28/01/2019 14:15	Type of Location: Straight Road
Location: Along Road 1 WHITLEY ROAD ALONG WHITLEY ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JKK828	Car	HONDA	CIVIC	Black	Seriously Damaged	0
PA5852E	Van	TOYOTA	HIACE DX 3.0 AUTO	Silver		0
SMC708Y	Car	VOLKSWAGO N	NEW GOLF 1.4 AT 5K13G5	Blue		0



**SINGAPORE
POLICE FORCE**



T/20190128/2118

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

2 of 4

Report No. T/20190128/2118

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MOHD ZULFADHLI BIN MOHAMMED	ID No.	860921236043
Related Vehicle	JKK828 (Car)	Contact No.	0176279089
Hospital/Clinic	GALILEE CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	28/01/2019	Date Discharge	28/01/2019
No. of Days granted Medical Leave	04	Degree of Injury	NIL
Driver			
Name	YEO YUK CHYE	ID No.	S1725517G
Related Vehicle	PA5852E (Van)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHUA SOON LEONG	ID No.	S7614949F
Related Vehicle	SMC708Y (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 28 January 2019 at about 1415hrs, I was driving my vehicle JKK828 (Honda Civic) along Whitley Road. I then stopped at the traffic light as it was red. Upon the traffic light turning green, I then felt a knock at the rear of my vehicle. I then stopped my vehicle and discovered that I was in a chain collision involving 1 car and 1 van. I was then informed by the van driver that he had knocked into the front vehicle, resulting in the front vehicle colliding onto my vehicle's rear bumper. We exchanged particulars. The van driver then called for his workshop assistance and I was directed to a workshop located at Paya Ubi Industrial (Teamwork Garage). After handing over my vehicle to the workshop, I then went to Galilee Clinic located at Block 342 Ubi Avenue 1 #01-935 as I was feeling pain at my back and legs. I was then issued with a 4



**SINGAPORE
POLICE FORCE**



T/20190128/2118

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 4

Report No. T/20190128/2118

CONTINUATION OF REPORT

days of Medical Leave due to the accident.



SINGAPORE
POLICE FORCE



T/20190128/2118

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

4 of 4

Report No. T/20190128/2118

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt TRAVINDER JIT SINGH

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

28/01/2019 16:47

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED
MOHD SAID

Contact No.: 65476172

Classification Of Case:

Authentication Stamp

NP168



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

China Taiping Insurance (Singapore) Pte Ltd
 105 Cecil Street #19-00
 The Octagon
 Singapore 069534

Vehicle number	JKK828
Make / Model	HONDA/CIVIC
Chassis number	
Accident date	28 JANUARY 2019
Reference	K1901-82

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER <i>Deentol</i>	738.00 ✓ <i>RM390</i>
2	REAR BUMPER LOWER BRACKET <i>hnl</i>	47.00 X
2	REAR BUMPER SIDE RETAINER <i>Hnl</i>	38.00 X
1	REAR END PANEL <i>Bnc</i>	531.00 ✓ <i>RM550</i>
1	REAR END PANEL TOP GARNISH <i>broken</i>	90.50 ✓
2	REAR TAILLAMP <i>crack</i>	536.00 ✓ <i>1pc RM390</i>
1	REAR EXHAUST SILENCER <i>bst</i>	853.00 ✓ <i>RM500</i>
2	REAR EXHAUST CHROME PIPE <i>bst</i>	97.00 ✓
2	REAR EXHAUST MOUNTING <i>Hnl</i>	30.00 X
2	REAR FENDER INNER TRIM <i>Hnl</i>	295.00 X
1	BOOTLID <i>Deentol</i>	710.00 ✓ <i>RM650</i>
1	BOOTLID OUTER KEY LOCK <i>Hnl</i>	197.00 X
1	BOOTLID WEATHERSTRIP <i>defunct</i>	95.00 ✓
1	BOOTLID EMBELM LOGO -H <i>hlc</i>	45.00 ✓
1	BOOTLID EMBLEM -CIVIC <i>hlc</i>	39.00 ✓
1	BOOTLID EMBLEM - 2.0 <i>hlc</i>	41.00 ✓
1	BOOTLID EMBELM -I-VTEC <i>hlc</i>	35.00 ✓
2	BOOTLID LAMP <i>crack mounty</i>	455.00 ✓ <i>1pc RM200</i>
1	BOOTLID LOCK <i>bst</i>	296.00 ✓ <i>RM200</i>
1	BOOTLID LOCK STRIKER <i>rev</i>	65.00 X
2	BOOTLID HINGE <i>hl</i>	58.00 X
1	BOOTLID INNER TRIM <i>Hnl</i>	229.00 X
1	SPARE TYRE TOP BOARD <i>bst</i>	297.00 ✓ <i>RM180</i>
<i>Spare tyre panel RM1200</i>		
		5817.50
Less 20%		1163.50
Subtotal		4654.00
Balance C/F		4654.00
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
Balance B/F		4654.00
1 SET	REAR BUMPER CLIP <i>hlc</i>	40.00 <i>30/-</i>
1 SET	REAR BOOTLID INNER TRIM CLIP <i>Hnl</i>	30.00 X
1 SET	REAR REVERSE SENSOR <i>Dome</i>	400.00 <i>220/-</i>
1	JOINT SEALANT <i>hlc</i>	150.00 <i>40/-</i>
Subtotal		620.00
Balance C/F		5274.00

4858.50
3886.868

290.00

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	5274.00
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE, REFIT REAR LINING, TRIM AND GANRISH	200.00 100/-
3	REMOVE AND RENEW REAR EXHAUST ASSY	120.00 60/-
4	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 80/-
6	PANEL BEATING ON AFFECTED AREAS	1400.00 900/-
7	SPRAY PANTING ON AFFECTED AREAS	1500.00 800/-
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	3780.00
	Grand total	9054.00

10,584.96

28/01/2019 e 1800hrs

h/a Andrew

2/Sum

5 dgs.

rym

2 KK Auto

8

6226.68

Supp 1080.96

7307.64

4/s 5000/-

List price will
be base on

Msia pruhst.

8

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
 3RD PARTY CLAIM SUPPLEMENTRY

China Taiping Insurance (Singapore) Pte Ltd
 105 Cecil Street #19-00
 The Octagon
 Singapore 069534

Vehicle number	JKK828
Make / Model	HONDA/CIVIC
Chassis number	
Accident date	28 JANUARY 2019
Reference	K1901-01

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	SPARE TYRE COMPARTMENT PANEL <i>Detach</i>	1351.20 ✓
		1351.20
	Less 20%	270.24
	Subtotal	1080.96
	Balance C/F	1080.96
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	1080.96
1	FLOOR INSULATOR <i>114</i>	150.00 ✗
	Subtotal	150.00
	Balance C/F	1230.96
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	1230.96
1	REMOVE AND RENEW FLOOR INSULATOR <i>114</i>	150.00 ✗
2	REMOVE AND REFIT FUEL TANK <i>114</i>	150.00 ✗
	Subtotal	300.00
	Grand total	1530.96

1 ya
2 kkk Auto

1080.96

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jan 2019		31 Jan 2019 16:54 Edit Adj Rpt	S\$5,000.00 Edit Estimates	S\$5,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHUA SOON LEONG, ID: S7614949F			
Main Claimant:	MOHAMAD ZULSADHLI BIN MOHAMAD			
Vehicle Reg. No.:	JKK828	Date of Loss:	28/01/2019 14:00 - :59 [137 Months and 5 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D200545C02	Policy/Cover Note No.:	DMPCSN30716618000	
Vehicle Reg. No. (Insured):	SMC708Y	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Karz Work Solutions (HQ) 53 Ubi Avenue 1 #02-24, Paya Ubi Industrial Park, 408934 Eunos - Tel: 9295 9989			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 13/02/2019]			
Driver/Custodian (Insured):	CHUA SOON LEONG (/ Male) , NRIC: S7614949F Email:			
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***JKK828 (SNM19D200545C02)**
[SMC708Y]

TP

MOHAMAD ZULSADHLI BIN MOHAMAD

Jan 28 2019 2:00PM

[CHUA SOON LEONG]

Karz Work Solutions

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/19 18:08	Rear View Right	 Load JPG	☒
2	03/04/19 18:08	Rear View Left	 Load JPG	☒
3	03/04/19 18:09	General View	 Load JPG	☒
4	03/04/19 18:09	General View	 Load JPG	☒
5	03/04/19 18:09	General View	 Load JPG	☒
6	03/04/19 18:09	General View	 Load JPG	☒
7	03/04/19 18:10	General View	 Load JPG	☒
8	03/04/19 18:10	General View	 Load JPG	☒
9	03/04/19 18:10	General View	 Load JPG	☒
10	03/04/19 18:10	General View	 Load JPG	☒
11	03/04/19 18:10	General View	 Load JPG	☒
12	03/04/19 18:10	General View	 Load JPG	☒
13	03/04/19 18:10	General View	 Load JPG	☒
14	03/04/19 18:10	General View	 Load JPG	☒
15	03/04/19 18:10	General View	 Load JPG	☒
16	03/04/19 18:10	General View	 Load JPG	☒
17	03/04/19 18:10	General View	 Load JPG	☒
18	03/04/19 18:10	General View	 Load JPG	☒
19	03/04/19 18:11	General View	 Load JPG	☒
20	03/04/19 18:11	General View	 Load JPG	☒
21	03/04/19 18:11	General View	 Load JPG	☒
22	03/04/19 18:11	General View	 Load JPG	☒
23	03/04/19 18:11	General View	 Load JPG	☒
24	03/04/19 18:11	General View	 Load JPG	☒
25	03/04/19 18:11	General View	 Load JPG	☒
26	03/04/19 18:11	General View	 Load JPG	☒
27	03/04/19 18:11	General View	 Load JPG	☒
28	03/04/19 18:11	General View	 Load JPG	☒
29	03/04/19 18:11	General View	 Load JPG	☒
30	03/04/19 18:11	General View	 Load JPG	☒
31	03/04/19 18:11	General View	 Load JPG	☒
32	03/04/19 18:11	General View	 Load JPG	☒
33	03/04/19 18:12	General View	 Load JPG	☒
34	03/04/19 18:12	General View	 Load JPG	☒
35	03/04/19 18:12	General View	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	03/04/19 18:12	General View	 Load JPG	☒
37	03/04/19 18:12	General View	 Load JPG	☒
38	03/04/19 18:12	General View	 Load JPG	☒
39	03/04/19 18:12	General View	 Load JPG	☒
40	03/04/19 18:12	General View	 Load JPG	☒
41	03/04/19 18:12	General View	 Load JPG	☒
42	03/04/19 18:12	General View	 Load JPG	☒
43	03/04/19 18:12	General View	 Load JPG	☒
44	03/04/19 18:12	General View	 Load JPG	☒
45	03/04/19 18:12	General View	 Load JPG	☒
46	03/04/19 18:12	General View	 Load JPG	☒
47	03/04/19 18:13	General View	 Load JPG	☒
48	03/04/19 18:13	General View	 Load JPG	☒
49	03/04/19 18:13	General View	 Load JPG	☒
50	03/04/19 18:13	General View	 Load JPG	☒
51	03/04/19 18:13	General View	 Load JPG	☒
52	03/04/19 18:13	General View	 Load JPG	☒
53	03/04/19 18:13	General View	 Load JPG	☒
54	03/04/19 18:13	General View	 Load JPG	☒
55	03/04/19 18:13	General View	 Load JPG	☒
56	03/04/19 18:13	General View	 Load JPG	☒
57	03/04/19 18:14	General View	 Load JPG	☒
58	03/04/19 18:14	General View	 Load JPG	☒
59	03/04/19 18:14	General View	 Load JPG	☒
60	03/04/19 18:14	General View	 Load JPG	☒
61	03/04/19 18:14	General View	 Load JPG	☒
62	03/04/19 18:14	General View	 Load JPG	☒
63	03/04/19 18:14	General View	 Load JPG	☒
64	03/04/19 18:14	General View	 Load JPG	☒
65	03/04/19 18:14	General View	 Load JPG	☒
66	03/04/19 18:14	General View	 Load JPG	☒
67	03/04/19 18:15	Odometer Reading	 Load JPG	☒
68	03/04/19 18:15	Chassis Number	 Load JPG	☒
69	03/04/19 18:15	Finishing Photo	 Load JPG	☒
70	03/04/19 18:15	Finishing Photo	 Load JPG	☒
71	03/04/19 18:15	Finishing Photo	 Load JPG	☒
72	03/04/19 18:15	Finishing Photo	 Load JPG	☒
73	03/04/19 18:15	Finishing Photo	 Load JPG	☒
74	03/04/19 18:16	Finishing Photo	 Load JPG	☒
75	03/04/19 18:16	Finishing Photo	 Load JPG	☒
76	03/04/19 18:16	Finishing Photo	 Load JPG	☒
77	03/04/19 18:16	Finishing Photo	 Load JPG	☒
78	03/04/19 18:16	Finishing Photo	 Load JPG	☒
79	03/04/19 18:16	Finishing Photo	 Load JPG	☒
80	03/04/19 18:16	Finishing Photo	 Load JPG	☒
81	03/04/19 18:16	Finishing Photo	 Load JPG	☒
82	03/04/19 18:16	Finishing Photo	 Load JPG	☒
83	03/04/19 18:16	Finishing Photo	Load JPG	☒

Photos/Images			3 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	03/04/19 18:16	Finishing Photo	 Load JPG	☒
85	03/04/19 18:16	Finishing Photo	 Load JPG	☒
86	03/04/19 18:16	Finishing Photo	 Load JPG	☒
87	03/04/19 18:16	Finishing Photo	 Load JPG	☒
88	03/04/19 18:16	Finishing Photo	 Load JPG	☒
89	03/04/19 18:17	Finishing Photo	 Load JPG	☒
90	03/04/19 18:17	Finishing Photo	 Load JPG	☒
91	03/04/19 18:17	Finishing Photo	 Load JPG	☒
92	03/04/19 18:17	Finishing Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119002118/DVD3S2

Date: 23/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30716618000

Claimant Vehicle No: JKK828 Insured Vehicle No: SMC708Y

Date of Loss: 28/01/2019 Nature of Claim: TP Claim No: SNM19D200545C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JKK828 Engine No: K20Z21921648

Make & Model: HONDA CIVIC, 1.5 (A) Chassis No: PMHFD263070401652

Reg. Date: 23/08/2007 (Man. Year: 2007) Odometer: 264629 km

Colour: Black

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17

Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm

Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,504.96	5,257.76	1,247.20	19.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	2,050.00	2,030.00	49.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,584.96	7,307.76	3,277.20	30.96
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	10,584.96	5,000.00	5,584.96	52.76
+ GST 7.00/7.00% (S\$)	740.95	350.00	390.95	52.76
Nett Amount (S\$)	11,325.91	5,350.00	5,975.91	52.76

INSPECTION

Date of Assignment: 31/01/2019

Date Inspected: 28/01/2019 Inspected At: TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #02-24, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2019)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JKK828)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	738.00 FL	*738.00 FL
2	2		*REAR BUMPER LOWER BRACKET	Not Necessary	47.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Not Necessary	38.00 FL	*- FL
4	1		*REAR END PANEL	Buckled	531.00 FL	*531.00 FL
5	1		*REAR END PANEL TOP GARNISH	Broken	90.50 FL	*90.50 FL
6	2		*REAR TAILLAMP	Cracked	536.00 FL	*536.00 FL
7	1		*REAR EXHAUST SILENCER	Bent	853.00 FL	*853.00 FL
8	2		*REAR EXHAUST CHROME PIPE	Bent	97.00 FL	*97.00 FL
9	2		*REAR EXHAUST MOUNTING	Not Necessary	30.00 FL	*- FL
10	2		*REAR FENDER INNER TRIM	Not Necessary	295.00 FL	*- FL
11	1		*BOTLID	Dented	710.00 FL	*710.00 FL
12	1		*BOOTLID OUTER KEY LOCK	Not Necessary	197.00 FL	*- FL
13	1		*BOOTLID WEATHERSTRIP	Deformed	95.00 FL	*95.00 FL
14	1		*BOOTLID EMBLEM LOGO - H	Necessary	45.00 FL	*45.00 FL
15	1		*BOOTLID EMBLEM - CIVIC	Necessary	39.00 FL	*39.00 FL
16	1		*BOOTLID EMBLEM - 2.0	Necessary	41.00 FL	*41.00 FL
17	1		*BOOTLID EMBLEM - I-VTEC	Necessary	35.00 FL	*35.00 FL
18	2		*BOOTLID LAMP	Mtg Cracked	455.00 FL	*455.00 FL
19	1		*BOOTLID LOCK	Bent	296.00 FL	*296.00 FL
20	1		*BOOTLID LOCK STRIKER	Repair	65.00 FL	*- FL
21	2		*BOOTLID HINGE	Not Necessary	58.00 FL	*- FL
22	1		*BOOTLID INNER TRIM	Not Necessary	229.00 FL	*- FL
23	1		*SPARE TYRE TOP BOARD	Bent	297.00 FL	*297.00 FL
24	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
25	1		*SET REAR BOOTLID INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
26	1		*SET REVERSE SENSOR	Damaged	400.00 FS	*220.00 FS
27	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS
28	1		*SPARE TYRE COMPARTMENT PANEL	Dented	1,351.20 FL	*1,351.20 FL
29	1		*FLOOR INSULATOR	Not Necessary	150.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	7,938.70	6,499.70
- List Item Discount on L Items 20.00/20.00% (S\$)	1,433.74	1,241.94
Total Parts (S\$)	6,504.96	5,257.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM.	New	60.00	30.00
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH.	New	200.00	100.00
3	REMOVE AND RENEW REAR EXHAUST ASSY.	New	120.00	60.00
4	REMOVE AND RENEW REAR REVERSE SENSOR.	New	150.00	40.00
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW.	New	200.00	80.00
6	PANEL BEATING ON AFFECTED AREAS.	New	1,400.00	900.00
7	SPRAY PAINTING ON AFFECTED AREAS.	New	1,500.00	800.00
8	APPLY ANTI RUST ON AFFECTED AREAS.	New	150.00	40.00
9	REMOVE AND RENEW FLOOR INSULATOR.	New	150.00	0.00
10	REMOVE AND REFIT FUEL TANK.	New	150.00	0.00
Gross Labour Cost (\$\$)			4,080.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >