

REPAIR ESTIMATE

Client: AXA Insurance Pte Ltd
Address: 8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Attention: Motor Claim Department
Contact No: 6880 4888
Fax No:
Email:

Date: 12/2/2019
Veh No: SJL3605D
Veh Model: TOYOTA COROLLA ALTIS
Mileage:

Service Advisor		Payment Terms	Quotation Validity
Name:	Muhammad Idram	Due Upon Receipt	
Contact No:	87489825		
Email:	muhammad_idram@pitstop.com.sg		
Fax No:			

S/No	Description	Price	Actions		Remarks
1	REAR BUMPER <i>Repair</i>	\$480.00	Accept	Reject <i>✓</i>	
2	LHS RETAINER(LONG) <i>3 m</i>	\$68.00	Accept	Reject <i>✓</i>	
3	LHS RETAINER(SHORT)	\$50.00	Accept	Reject <i>✓</i>	
3	RIM <i>6x</i>	\$160.00	Accept <i>✓</i>	Reject	
4	CONDUCT WHEEL ALIGNMENT BEFORE REPAIR	\$140.00 <i>80</i>	Accept	Reject	
5	CONDUCT WHEEL ALIGNMENT AFTER REPAIR	\$140.00 <i>80</i>	Accept	Reject	
6	BODYWORKS:TO DISMANTLE AND REFIX THE ABOVE MENTIONED PARTS <i>500</i>	\$600.00	Accept	Reject	
Remark	*We will advise if further supplementary items are necessary*				
Estimated Days of Repair:	4	Working Day	Sub-Total	\$1,638.00	
			Gst	\$114.66	
			Total	\$1,752.66	

The above is based on initial assessment. We will advise further if there is supplementary repair.

Customer Signature / Date

(To accept this quotation, please sign & return)

Company Stamp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
1/1 13/02/19.
03 Days

bill: 820
4/5: 650

(605w)

660