

16/2/2019

PAGE 1/3



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

ATTN: GUO QIANG.

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 14 DAYS.

Customer: WZH023 / SOMPO INSURANCE
Chassis No: MRHFC5650JT001617
License No: SME5148U
Mileage: 5192
Engine No: R16B25501883

Document No: SVO19007900
Printed By: JESHURUEBEN
Order Date: 1. February 2019
Order Time: 2:15:52 PM
Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72104)						
	OWNER: LIM KWAN HUI						
	OWNER INSURER: AVIVA LTD						
	ACC DATE: 31/01/2019						
	SURVEYED BY: GUO QIANG (LKK)						
	DATE: 01/02/2019						
	REF NO: CMTD1900663/AGC						
	TP INSURER: SOMPO INSURANCE						
	TP VEH: SGN8660K						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	2	45.00		90.00	6.30	96.30
68500-TEA-N00ZZ	LID COMP TRUNK	1	486.20	25	364.65	25.53	390.18
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSYTRUNK	1	74.30	25	55.72	3.90	59.62
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	100.60	25	75.45	5.28	80.73
75722-TBA-A00	EMBLEM SETRR.	1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	1	11.00	25	8.25	0.58	8.83
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71506-TEX-Y00	COVERRR.TOWING HOOK	1	8.70	25	6.52	0.46	6.98
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	164.70	25	123.52	8.65	132.17
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.80	25	5.85	0.41	6.26
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	1	7.80	25	5.85	0.41	6.26
34155-TEX-Y01	LIGHT ASSYL.LID	1	122.30	25	91.72	6.42	98.14
34150-TEX-Y01	LIGHT ASSYR.LID	1	122.30	25	91.72	6.42	98.14
33550-TEA-T01	TAILLIGHT ASSYL.	1	281.30	25	210.97	14.77	225.74
33500-TEA-T01	TAILLIGHT ASSYR.	1	261.40	25	196.05	13.72	209.77
39680-TEX-Y41ZN	SENSOR ASSY, PARKING NH696	4	133.90	25	401.70	28.12	429.82
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30	25	44.47	3.11	47.58
74940-SZW-003	BUZZER ASSYSMART	1	61.30	25	45.97	3.22	49.19
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	30.44	465.36
91505-TM8-003	CLIP,BUMPER	16	2.30	25	27.60	1.93	29.53
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71190-TEA-T00	BEAML.FR.BUMPER UPPER	1	26.70	25	20.02	1.40	21.42
71140-TEA-T00	BEAMR.FR.BUMPER UPPER	1	26.70	25	20.02	1.40	21.42
71130-TEA-T00	BEAM COMPPR.BUMPER	1	345.90	25	259.42	18.16	277.58
71150-TEA-T00	BEAM COMPPR.BUMPER CENTER UPP	1	214.80	25	161.10	11.28	172.38
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	73.80	25	55.35	3.87	59.22
71125-TEA-T01	MOLDINGFR.GRILLE	1	100.40	25	75.30	5.27	80.57
75700-TBA-A00	EMBLEM	1	15.00	25	11.25	0.79	12.04



SERVICE PRE-INVOICE

PAGE 2/3

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
Chassis No: MRHFC5650JT001617
License No: SME5148U
Mileage: 5192
Engine No: R16B25501883

Document No: SVO19007900
Printed By: JESHURUEBEN
Order Date: 1. February 2019
Order Time: 2:15:52 PM
Service Advisor: RUEBEN THOMAS

90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
33150-TEC-306	HEADLIGHT ASSY,L.	1	585.70	25	439.27	30.75	470.02
33100-TEC-306	HEADLIGHT ASSY,R.	1	585.70	25	439.27	30.75	470.02
80100-TBA-A01	CONDENSER ASSY	1	704.40	25	528.30	36.98	565.28
91555-TBA-K01	CLIPAMBIENT SENSOR	1	5.40	25	4.05	0.28	4.33
75701-TBA-A10	EMBLEM,H-MARK	1	12.20	25	9.15	0.64	9.79
19010-5FA-Z01	RADIATOR COMP	1	1,100.50	25	825.37	57.78	883.15
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	25	52.20	3.65	55.85
SUM PARTS:					6,044.13	423.08	6,467.21
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML01I	0760	1	100.00		100.00	7.00	107.00
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)						
BML02I	0760	1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BOJSE	0760	1	80.00		160.00	11.20	171.20
	BODY JOINT SEALANT.						
BOBC	0959	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BP00R	EXT-YBH	1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BA02R	0760	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BMF00D	0760	1	250.00		250.00	17.50	267.50
	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)						
BKOT00R	0760	1	250.00		250.00	17.50	267.50
	REMOVE & RENEW RR FLOOR INSULATOR.(N)						
BMA01D	0760	1	280.00		280.00	19.60	299.60
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)						
BOMISC1	0760	1	300.00		300.00	21.00	321.00
	RESET VEHICLE SMART ENTRY SYSTEM (N)						
BOMISC1	0760	1	300.00		300.00	21.00	321.00
	REMOVE, INSTALL & ADJUST REAR VIEW CAMERA (N)						
BMI03D	0760	1	350.00		350.00	24.50	374.50
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BKTG02R	0760	1	450.00		450.00	31.50	481.50
	REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST & ALIGN TRUNK.(N)						
BKBH01S	0760	1	840.00		840.00	58.80	898.80
	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
Chassis No: MRHFC5650JT001617
License No: SME5148U
Mileage: 5192
Engine No: R16B25501883

Document No: SVO19007900
Printed By: JESHURUEBEN
Order Date: 1. February 2019
Order Time: 2:15:52 PM
Service Advisor: RUEBEN THOMAS

BKRP02M	0760	1	2,800.00	2,800.00	196.00	2,996.00
	CUT OFF & RENEW RR PANEL. CUT RR FLOOR					
	ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.					
BP06R	EXT-YBH	1	2,700.00	2,700.00	189.00	2,889.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)					
BP02R		1	450.00	450.00	31.50	481.50
	SPRAY PAINTING ON FRONT BUMPER & BULKHEAD					
BMC01D	0760	1	230.00	230.00	16.10	246.10
	REMOVE & INSTALL RADIATOR WITH FITTINGS.					
	PRESSURE TEST COOLING SYSTEM.(N)					

SUM LABOUR: 9,990.00 699.30 10,689.30

TOTAL SGD 16,034.13 1,122.38 17,156.51

Total Payable (SGD) 17,156.51

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: SOMPO INSURANCE SINGAPORE	Document No.	: SQT19000750	Page	1
	50 RAFFLES PLACE #05-01/06	Date	: 16. Feb 2019		
	SINGAPORE LAND TOWER	Customer No.	: WZH023		
	SINGAPORE 048623	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SME5148U	Engine No	: R16B25501883		
Chassis No	: MRHFC5650JT001617	Date Time	: 16. Feb 2019 9:05:38 AM		
Model	: CIVIC 1.6 VTI YM2018	Surveyor Name	:		
Owner's Name	: LIM KWAN HUI	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 31/1/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
SUPPLEMENTARY PARTS & LABOUR							
91555-TBA-K01	CLIPAMBIENT SENSOR	1	5.40	25	4.05	0.28	4.33
75701-TBA-A10	EMBLEM,H-MARK	1	12.20	25	9.15	0.64	9.79
19010-5FA-Z01	RADIATOR COMP	1	1100.50	25	825.37	57.78	883.15
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	25	52.20	3.65	55.85
Sum Item					890.77	62.35	953.12
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	230.00		230.00	16.10	246.10
Sum Labor					230.00	16.10	246.10

Survey By

Date & Time

Excess

Status

Signature

Total Amount 1,120.77 78.45 1,199.22

Total (Inclusive of GST) 1,199.22

Printed on 16/2/2019 9:07:36 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)