

ASS. REC. BY:

REF:

CS/SMO19002120/GVD362

Special Instruction:

Surveyor

Guo Qiang

ASSIGNMENT (Office)

Meimen

From (Person) Chan Shu Hui Agnes

of SMO

Date/Time: 31/1/19 @ 4:33pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 51484

Insured:

SGN 8660K

at Workshop m/s

Kah Motor

Tel:

9072 1766

of

15 Ubi Rd 4

Policy No:

DISMTMPV0100 7655

Claim No:

CMTD1900663

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/1/19

1/2/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

5:25pm @ 1/2/19

Person Contacted:

Rueben

Vehicle ☒ IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SME 51484 - X

SGN 8660K - CC3/MSG19002102/UTD3

20A: 31/1/2019

07/02/19

@ 16:01 pm revised IA to Chan Shu Hui Agnes via meimen.

18/2/19

Final fig \$ 16,034.13 confirmed by email (Ref 3868.41, 1990)

Xarl.

REF: SMO

2681B

VEHICLE

Form Date 1/2/19

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No: SME 51484

at Workshop m/s

Kah Motor
15 ubi Rd 4

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date Person Contacted:

Date / Time Action / Instruction

Veh No: SME 51484 Yr Regn 02 Oct 2018

Type: ☒ M. Car ☐ M. Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Trailer or

Make: Honda civic C.C. 1597

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No:

ChNo: MRHFC5650 JT001617

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orModi: Nil ☐ S/Rim ☐ STD A/Rim or

Tyre Size F: 245/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. D.O.I. 01-02-17

Survey held at w/s 12pm

Des. of Damages ☒ Frt ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 10 FEB 2019

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2) 18/2 - typist

Report Format: mer. men

Lump Sum / I.B. / IS 16,034.13

Days Of Repair: 13

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp. \$☐ Interview. \$☐ Tech. Invs. \$☐ Weekend \$

Survey Fee:

Transportation:

1) 3 x PD \$

1) Photo:

1) Video:

TOTAL:

450

10

460

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2019		31 Jan 2019 16:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHIA WEE KEE, ID: S7722645A		
Main Claimant:	LIM KWAN HUI, ID: S8232681B		
Vehicle Reg. No.:	SME5148U	Date of Loss:	31/01/2019 09:00 - :59
Claim Type:	TP / CMTD1900663	Policy/Cover Note No.:	D18MTMPV01007655 (Comprehensive)
Vehicle Reg. No. (Insured):	SGN8660K	Policy No. (Claimant):	
		Excess:	
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/02/2019]		
Driver/Custodian (Insured):	HU KAITIAN (), NRIC: S8134060I, Tel: +6590258052		
Adj Asg. Remarks:	PIC: Rueben 90721766		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

1/31/19
ver✓

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 07 Feb 2019

Preliminary Advice

Insured Vehicle No	: SGN8660K	Accident Date	: 31/01/2019
TP Vehicle No	: SME5148U	Assignment Date	: 31/01/2019
Make	: HONDA CIVIC	Est. Duration of Repair	: 12 Days
Date of Inspection	: 01/02/2019		
Inspection At	: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,781.77
Revised Amount	:S\$	16,136.26
Check Items (Estimated)	:S\$	461.01
Total	:S\$	16,597.27
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2681B
Vehicle Details	
Vehicle No.:	5ME5148U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	Maroon
Manufacturing Year:	2018
Engine No.:	R16B25501883
Chassis No.:	MRHFC5650JT001617
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,645.00
Original Registration Date:	02 Oct 2018
First Registration Date:	02 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$20,903.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Oct 2028
PARF Rebate Amount:	\$15,677.00
Intended COE Rebate Details	
COE Expiry Date:	01 Oct 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,997.00
COE Rebate Amount:	\$25,597.00
Total Rebate Amount:	\$41,274.00

The information contained herein is correct as at 18 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	31/01/2019 13:54
Date Of Accident	31/01/2019 08:40
Exact Location Of Accident	TPE TOWARDS PIE NEAR KPE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SME5148U
Insured/Policyholder	
Name Of Registered Owner	LIM KWAN HUI
NRIC No	S8232681B
Email Address	LIM.KWAN.HUI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93258840
Alternative Phone No	OFFICE-93258840
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC-1.6 VTI CVT (A)
Exact Purpose for which vehicle was being used at time of accident	TRAVELLING TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10873873
Cover Note Number	
Driver	
Name of Driver	LIM KWAN HUI
NRIC No	S8232681B
Date Of Birth	26/09/1982
Occupation	INDOOR
Date Of Driving Pass	26/12/2013
Driving Experience	5 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93258840
Fax Number	
Contact Number	OFFICE-93258840
Email Address	LIM.KWAN.HUI@GMAIL.COM

Address	APT BLK 706 HOUGANG AVENUE 2 #08-171
Postcode	530706
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TEH LIK YIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT NO: T/20190131/7006. THIRD PARTY DIRECT SETTLEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGN8660K
Vehicle Make/Model/Colour	KIA/FORTE K3/SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HU KAITIAN
NRIC/Passport Number	S8134060I
Contact Number	90258052

Address
 Postcode
 Insurance Company Name SOMPO INSURANCE SINGAPORE PTE. LTD.
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGW4457K
 Vehicle Make/Model/Colour TOYOTA/ALTIS/SILVER
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver MUHAMMED ALI BIN NAZIR AHAMED
 NRIC/Passport Number S7533508C
 Contact Number 87525744
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLL7222A
 Vehicle Make/Model/Colour VOLKSWAGEN/SHARAN/BLUE
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TEE SIEW PENG JULIE
 NRIC/Passport Number S7442426J
 Contact Number 98585202
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLN2477D
 Vehicle Make/Model/Colour MERCEDES/CLA180/BLACK
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LEE HUANG KIANG
 NRIC/Passport Number S6910468A
 Contact Number 90053741
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TEH LIK YIN
 Approximate Age 33
 Injuries Sustain LIGHT
 Injured person in which vehicle? SME5148U

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

BLK 996A, BUANGKOK CRESCENT
#14-877

Postcode

531996

Vehicle Number: SMF5148USKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 31/01/2019
1230hrs

Driver's Signature

(if driver is not the policyholder)
Date & Time: 31/01/2019
1230 hrs

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

Vehicle Number: SMES148U

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report T/20190131/7006

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time: 31/01/2019
1230hrs

[Signature] (policyholder)
Driver's Signature
(If driver is not the policyholder)
Date & Time: 31/01/2019
1230hrs

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190131/7006

1 of 5

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190131/7006

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/01/2019 12:08			Vide Report No.: G/20190131/0074		Station Diary No.:
Informant's Particulars					
Name of Informant: LIM KWAN HUI			Address: APT BLK 706 HOUGANG AVENUE 2 #08-171 SINGAPORE 530706		
ID Type / ID No.: NRIC NO / S8232681B			Contact No.: Home/Office:		Mobile: 93258840
Nationality: SINGAPORE CITIZEN			Email: lim.kwan.hui@gmail.com		
Sex: Male	Age: 36	Date of Birth: 26/09/1982	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Professor			Driving Licence Information: Class: 3A		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 31/01/2019 08:40	Type of Location: Expressway
Location: TAMPINES EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 90 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGN8660K	Car	KIA	forte K3	Silver	Slightly Damaged	0
SGW4457K	Car	TOYOTA	Altis	Silver	Slightly Damaged	0
SLL7222A	Car	VOLKSWAGO N	SHARAN	Blue	Slightly Damaged	1
SLN2477D	Car	MERCEDES BENZ	CLA180	Black	No Damage	0



**SINGAPORE
POLICE FORCE**



T/20190131/7006

2 of 5

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190131/7006

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SME5148U	Car	HONDA	CIVIC 1.6 VTI CVT	Maroon	Seriously Damaged	1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SME5148U	AVIVA LTD	10873873	02/10/2018	01/10/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Hu Kaitian		ID No.	S8134060I
Related Vehicle	SGN8660K (Car)		Contact No.	90258052
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	Muhammed Ali Bin Nazir Ahamed		ID No.	S7533508C
Related Vehicle	SGW4457K (Car)		Contact No.	87525744
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190131/7006

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 5

Report No. T/20190131/7006

CONTINUATION OF REPORT

Driver			
Name	Tee Siew Peng Julie		ID No. S7442426J
Related Vehicle	SLL7222A (Car)		Contact No. 98585202
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Driver			
Name	Lee Huang Kiang		ID No. S6910468A
Related Vehicle	SLN2477D (Car)		Contact No. 90053741
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Passenger			
Name	Teh Lik Yin		ID No. S8571015Z
Related Vehicle	SME5148U (Car)		Contact No. 97226239
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	31/01/2019		Date Discharge 31/01/2019
No. of Days granted Medical Leave	02		Degree of Injury Slight
Driver			
Name	LIM KWAN HUI		ID No. S8232681B
Related Vehicle	SME5148U (Car)		Contact No. 93258840
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3A Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL



SINGAPORE
POLICE FORCE



T/20190131/7006

4 of 5

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190131/7006

CONTINUATION OF REPORT

Brief Details.

Location along TPE towards PIE, near KPE. We were driving on lane 1 when the car in front came to a stop, so we came to a stop too. After a short while (1-2 seconds), we felt a huge impact from behind us, followed by a smaller one. As a result of the impacts from the back, our car shifted forward hitting the car in front of us.

Have videos and photos exceeding 2MB.



**SINGAPORE
POLICE FORCE**



T/20190131/7006

5 of 5

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190131/7006

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
31/01/2019 12:08

Classification Of Case:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SME5148U

Chassis No : MRHFC5650JT001617

Model : CIVIC 1.6 VTI YM2018

Owner's Name : LIM KWAN HUI

Ins Policy No. :

Date of Accident : 31/1/2019

Document No. : SQT19000530

Date : 31. Jan 2019

Customer No. : WZH023

Svc Advisor : RUEBEN THOMAS

Engine No : R16B25501883

Date | Time : 31. Jan 2019 12:48:12 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: LIM KWAN HUI						
	OWNER INSURER: AVIVA LTD						
	ACC DATE: 31/01/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: SOMPO INSURANCE						
	TP VEH: SGN8660K						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) / BT	2	45.00		90.00 ✓	6.30	96.30
68500-TEA-N00ZZ	LID COMP TRUNK / BNC	1	486.20	25	364.65 ✓	25.53	390.18
74865-TEA-T01	WEATHERSTRIPTRUNK LID / Tui	1	70.00	25	52.50 ✓	3.68	56.18
68660-TEA-T10ZZ	HINGE COMPL.TRUNK X SGT NN	1	44.80	25	33.60	2.35	35.95
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	44.80	25	33.60	2.35	35.95
74851-TEA-003	LOCK ASSYTRUNK / DT	1	74.30	25	55.72 ✓	3.90	59.62
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE / Mis	1	100.60	25	75.45 ✓	5.28	80.73
75722-TBA-A00	EMBLEM SETRR. / SMC	1	11.80	25	8.85 ✓	0.62	9.47
75725-TEA-T01	EMBLEMRR.	1	11.00	25	8.25 ✓	0.58	8.83
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER / RL	1	617.20	25	462.90 ✓	32.40	495.30
91505-TM8-003	CLIP,BUMPER / RL	7	2.30	25	12.07 ✓	0.84	12.91
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER / RL	1	36.40	25	27.30 ✓	1.91	29.21
71506-TEX-Y00	COVERRR.TOWING HOOK / RL	1	8.70	25	6.52 ✓	0.46	6.98
71598-TEA-T01	SPACERL,RR.BUMPER SIDE / SMC	1	11.50	25	8.62 ✓	0.60	9.22
71593-TEA-T01	SPACERR,RR.BUMPER SIDE / SMC	1	11.50	25	8.62 ✓	0.60	9.22
71555-TBA-A00	BRACKETL,RR.BUMPER SIDE / SMC	1	2.30	25	1.72 ✓	0.12	1.84
71505-TBA-A00	BRACKETR,RR.BUMPER SIDE / SMC	1	2.30	25	1.72 ✓	0.12	1.84
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER X BT	1	164.70	25	123.52 ✓	8.65	132.17
71508-TEA-T00	GARNISHL,RR.BUMPER SIDE / RL	1	7.80	25	5.85 ✓	0.41	6.26
71503-TEA-T00	GARNISHR,RR.BUMPER SIDE / RL	1	7.80	25	5.85 ✓	0.41	6.26
33555-TEA-T01	REFLECTOR ASSYL,RR. X NN	1	7.20	25	5.40	0.38	5.78



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SME5148U
Chassis No : MRHFC5650JT001617
Model : CIVIC 1.6 VTI YM2018
Owner's Name : LIM KWAN HUI
Ins Policy No. :
Date of Accident : 31/1/2019

Document No. : SQT19000530
Date : 31. Jan 2019
Customer No. : WZH023
Svc Advisor : RUEBEN THOMAS
Engine No : R16B25501883
Date | Time : 31. Jan 2019 12:48:12 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33505-TEA-T01	REFLECTOR ASSY,RR. <i>X NN</i>	1	7.20	25	5.40	0.38	5.78
71504-TBA-A00	COVER,FINISHER <i>X NN</i>	1	11.90	25	8.92	0.62	9.54
34155-TEX-Y01	LIGHT ASSY,LID <i>/ 1 unit</i>	1	122.30	25	91.72	6.42	98.14
34150-TEX-Y01	LIGHT ASSY,RR,LID	1	122.30	25	91.72	6.42	98.14
33550-TEA-T01	TAILLIGHT ASSY, <i>/ 1 unit</i>	1	281.30	25	210.97	14.77	225.74
33500-TEA-T01	TAILLIGHT ASSY, <i>/ 1 unit</i>	1	261.40	25	196.05	13.72	209.77
39530-TEA-H01	CAMERA ASSY,RR VI <i>/ 1 unit</i>	1	315.60	25	236.70	16.57	253.27
32131-TEA-R00	SUB CORD,RR,BUMPER CORNER SENS <i>/ 1 unit</i>	1	28.10	25	21.07	1.47	22.54
39680-TEX-Y41ZT	SENSOR ASSY,PARKING <i>/ 1 unit</i>	4	145.80	25	437.40	30.62	468.02
38387-TZ5-A01	ANTENNA ASSY,LF <i>/ 1 unit</i>	1	59.30	25	44.47	3.11	47.58
74940-SZW-003	BUZZER ASSY,SMART <i>/ 1 unit</i>	1	61.30	25	45.97	3.22	49.19
66100-TEC-307ZZ	PANEL SET,RR <i>/ 1 unit</i>	1	243.10	25	182.32	12.76	195.08
66154-TBA-A00ZZ	STIFFENER,L,RR,PANEL SIDE <i>/ 1 unit</i>	1	26.70	25	20.02	1.40	21.42
66114-TBA-A00ZZ	STIFFENER,R,RR,PANEL SIDE <i>/ 1 unit</i>	1	26.70	25	20.02	1.40	21.42
65550-TEA-T00ZZ	PAN COMP,SPARE TIRE <i>/ 1 unit</i>	1	216.70	25	162.52	11.38	173.90
72841-SA0-315	OIL SHEET <i>/ 1 unit</i>	1	36.10	25	27.07	1.89	28.96
84620-TEA-Z11ZA	LINING ASSY,TRUNK LID <i>/ 1 unit</i>	1	32.90	25	24.67	1.73	26.40
84640-TEA-Z01ZA	LINING ASSY,RR,PANEL <i>/ 1 unit</i>	1	50.30	25	37.72	2.64	40.36
84521-TEA-Q01ZA	LID ASSY,SPARE TIRE <i>/ 1 unit</i>	1	60.20	25	45.15	3.16	48.31
84542-TET-H00	BOX COMP,TOOL <i>/ 1 unit</i>	1	38.00	25	28.50	2.00	30.50
84651-TEA-Q01ZA	LINING ASSY,L,TRUNK SIDE <i>/ 1 unit</i>	1	48.90	25	36.67	2.57	39.24
84601-TEA-Q01ZA	LINING ASSY,R,TRUNK SIDE <i>/ 1 unit</i>	1	48.90	25	36.67	2.57	39.24
71101-TEA-T00ZZ	FACE,FR,BUMPER <i>/ 1 unit</i>	1	579.90	25	434.92	30.44	465.36
91505-TM8-003	CLIP,BUMPER <i>/ 1 unit</i>	16	2.30	25	27.60	1.93	29.53
71198-TEA-T01	SPACER,L,FR,BUMPER SIDE <i>/ 1 unit</i>	1	10.40	25	7.80	0.55	8.35
71193-TEA-T01	SPACER,R,FR,BUMPER SIDE <i>/ 1 unit</i>	1	10.40	25	7.80	0.55	8.35
71190-TEA-T00	BEAM,L,FR,BUMPER UPPER <i>/ 1 unit</i>	1	26.70	25	20.02	1.40	21.42
71140-TEA-T00	BEAM,R,FR,BUMPER UPPER <i>/ 1 unit</i>	1	26.70	25	20.02	1.40	21.42
71102-TBA-A10	GRILLE,FR,BUMPER LOWER <i>/ 1 unit</i>	1	36.10	25	27.07	1.89	28.96
71108-TEA-T00	GARNISH,L,FR,BUMPER SIDE <i>/ 1 unit</i>	1	18.00	25	13.50	0.95	14.45

Printed on 31/1/2019 3:52:14 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SME5148U
Chassis No : MRHFC5650JT001617
Model : CIVIC 1.6 VTI YM2018
Owner's Name : LIM KWAN HUI
Ins Policy No. :
Date of Accident : 31/1/2019

Document No. : SQT19000530 Page 3
Date : 31. Jan 2019
Customer No. : WZH023
Svc Advisor : RUEBEN THOMAS
Engine No : R16B25501883
Date | Time : 31. Jan 2019 12:48:12 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incld GST	
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE X NN X NN	1	18.00	25	13.50	0.95	14.45	
71145-S21-000	BASEFR LIC PLATE X NN X NN	1	37.80	25	28.35	1.98	30.33	
71130-TEA-T00	BEAM COMPFR.BUMPER B / BT	1	345.90	25	259.42	18.16	277.58	
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP / BT.	1	214.80	25	161.10	11.28	172.38	
71121-TEA-T01	BASE,FR.GRILLE CHROME - CAA	1	73.80	25	55.35	3.87	59.22	
71125-TEA-T01	MOLDINGFR.GRILLE - CAA	1	100.40	25	75.30	5.27	80.57	
75700-TBA-A00	EMBLEM - MCL	1	15.00	25	11.25	0.79	12.04	
90301-ST0-003	NUTPUSH 3MM - MCL	2	2.10	25	3.15	0.22	3.37	
74146-TEA-T00	RUBBERHOOD SEAL X NN	1	27.60	25	20.70	1.45	22.15	
74127-TEA-T00	COVERFR.BULKHEAD X X NN	1	18.20	25	13.65	0.96	14.61	
33150-TEC-Q01	HEADLIGHT ASSYL - 4 CAA	1	585.70	25	439.27	30.75	470.02	
33100-TEC-Q01	HEADLIGHT ASSY,R - 4 CAA	1	585.70	25	439.27	30.75	470.02	
80100-TBA-A01	CONDENSER ASSY B / BT	1	704.40	25	528.30	36.98	565.28	
Air-Con sensor clip - 2 R.					Sum Item	6011.77	420.83	6,432.60
BOSUN	SUNDRIES	1	50.00	20 ✓	50.00	3.50	53.50	
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	✓ ✓	100.00	7.00	107.00	
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00	✓ ✓	100.00	7.00	107.00	
BOJSE	BODY JOINT SEALANT	2	100.00	20 160 ✓	200.00	14.00	214.00	
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00	
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	✓ 180	250.00	17.50	267.50	
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00	✓ 130	150.00	10.50	160.50	
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	250.00	✓ ✓	250.00	17.50	267.50	
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	250.00	✓ ✓	250.00	17.50	267.50	
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	280.00	✓ ✓	280.00	19.60	299.60	
BOMISC1	RESET VEHICLE SMART ENTRY SYSTEM (N)	1	320.00	✓ 300	320.00	22.40	342.40	
BOMISC1	REMOVE, INSTALL & ADJUST REAR VIEW CAMERA (N)	1	320.00	✓ 300	320.00	22.40	342.40	
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	✓ ✓	350.00	24.50	374.50	
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST &	1	450.00	✓ ✓	450.00	31.50	481.50	

Printed on 31/1/2019 3:52:14 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

Registration No : SME5148U

Chassis No : MRHFC5650JT001617

Model : CIVIC 1.6 VTI YM2018

Owner's Name : LIM KWAN HUI

Ins Policy No. :

Date of Accident : 31/1/2019

Document No. : SQT19000530 Page 4

Date : 31. Jan 2019

Customer No. : WZH023

Svc Advisor : RUEBEN THOMAS

Engine No : R16B25501883

Date | Time : 31. Jan 2019 12:48:12 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	560	1200.00	✓ 840	1200.00	84.00	1284.00
BKRP02M	CUT OFF & RENEW RR PANEL. CUT RR FLOOR	1	4500.00	3920	4500.00	315.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	450	2900.00	✓ 2700	2900.00	203.00	3103.00
BP02R	SPRAY PAINTING ON FRONT BUMPER & BULKHEAD	1	1000.00	✓ 450	1000.00	70.00	1070.00
Sum Labor					12770.00	893.90	13,663.90

Survey By

Date & Time

Excess

Status

Signature

Total Amount 18,781.77 1,314.73 20,096.50

Total (Inclusive of GST) 20,096.50

19,903.54

13 12 Days.

before paint photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 31/1/2019 3:52:14 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

16/2/2019

PAGE 1/3



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

ATTN: GUO QIANG.

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 14 DAYS.

Customer: WZH023 / SOMPO INSURANCE
 Chassis No: MRHFC5650JT001617
 License No: SME5148U
 Mileage: 5192
 Engine No: R16B25501883

Document No: SVO19007900
 Printed By: JESHURUEBEN
 Order Date: 1. February 2019
 Order Time: 2:15:52 PM
 Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO: 72104)						
	OWNER: LIM KWAN HUI						
	OWNER INSURER: AVIVA LTD						
	ACC DATE: 31/01/2019						
	SURVEYED BY: GUO QIANG (LKK)						
	DATE: 01/02/2019						
	REF NO: CMTD1900663/AGC						
	TP INSURER: SOMPO INSURANCE						
	TP VEH: SGN8680K						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	2	45.00		90.00	6.30	96.30
68500-TEA-N00ZZ	LID COMP TRUNK	1	486.20	25	364.65	25.53	390.18
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSYTRUNK	1	74.30	25	55.72	3.90	59.62
74890-TEA-T112B	GARNISH ASSYRR.LICENSE	1	100.60	25	75.45	5.28	80.73
75722-TBA-A00	EMBLEM SETRR.	1	11.80	25	8.85	0.62	9.47
75725-TEA-T01	EMBLEMRR.	1	11.00	25	8.25	0.58	8.83
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
91505-TMB-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71506-TEX-Y00	COVERRR.TOWING HOOK	1	8.70	25	6.52	0.46	6.98
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.30	25	1.72	0.12	1.84
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	164.70	25	123.52	8.65	132.17
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.80	25	5.85	0.41	6.26
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	1	7.80	25	5.85	0.41	6.26
34155-TEX-Y01	LIGHT ASSYL.LID	1	122.30	25	91.72	6.42	98.14
34150-TEX-Y01	LIGHT ASSYR.LID	1	122.30	25	91.72	6.42	98.14
33560-TEA-T01	TAILLIGHT ASSYL.	1	281.30	25	210.97	14.77	225.74
33500-TEA-T01	TAILLIGHT ASSYR.	1	261.40	25	196.05	13.72	209.77
39680-TEX-Y41ZN	SENSOR ASSY, PARKING NH696	4	133.90	25	401.70	28.12	429.82
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30	25	44.47	3.11	47.58
74940-SZW-003	BUZZER ASSYSMART	1	61.30	25	45.97	3.22	49.19
66100-TEC-307ZZ	PANEL SETRR.	1	243.10	25	182.32	12.76	195.08
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.70	25	20.02	1.40	21.42
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	30.44	465.36
91505-TMB-003	CLIP,BUMPER	16	2.30	25	27.60	1.93	29.53
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71190-TEA-T00	BEAML.FR.BUMPER UPPER	1	26.70	25	20.02	1.40	21.42
71140-TEA-T00	BEAMR.FR.BUMPER UPPER	1	26.70	25	20.02	1.40	21.42
71130-TEA-T00	BEAM COMPFR.BUMPER	1	345.90	25	259.42	18.16	277.58
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP	1	214.80	25	161.10	11.28	172.38
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	73.80	25	55.35	3.87	59.22
71125-TEA-T01	MOLDINGFR.GRILLE	1	100.40	25	75.30	5.27	80.57
75700-TBA-A00	EMBLEM	1	15.00	25	11.25	0.79	12.04

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

PAGE 2/3

Customer: WZH023 / SOMPO INSURANCE
Chassis No: MRHFC5650JT001617
License No: SME5148U
Mileage: 5192
Engine No: R16B25501883

Document No: SVO19007900
Printed By: JESHURUEBEN
Order Date: 1. February 2019
Order Time: 2:15:52 PM
Service Advisor: RUEBEN THOMAS

90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
33150-TEC-306	HEADLIGHT ASSY,L	1	585.70	25	439.27	30.75	470.02
33100-TEC-306	HEADLIGHT ASSY,R	1	585.70	25	439.27	30.75	470.02
80100-TBA-A01	CONDENSER ASSY	1	704.40	25	528.30	36.98	565.28
91555-TBA-K01	CLIPAMBIENT SENSOR	1	5.40	25	4.05	0.28	4.33
75701-TBA-A10	EMBLEM,H-MARK	1	12.20	25	9.15	0.64	9.79
19010-5FA-Z01	RADIATOR COMP	1	1,100.50	25	825.37	57.78	883.15
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	25	52.20	3.65	55.85
SUM PARTS:					6,044.13	423.08	6,467.21
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML01I	0760	1	100.00		100.00	7.00	107.00
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)						
BML02I	0760	1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BOJSE	0760	1	80.00		160.00	11.20	171.20
	BODY JOINT SEALANT.						
BOBC	0959	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BP00R	EXT-YBH	1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BA02R	0760	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BMF00D	0760	1	250.00		250.00	17.50	267.50
	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)						
BKOT00R	0760	1	250.00		250.00	17.50	267.50
	REMOVE & RENEW RR FLOOR INSULATOR.(N)						
BMA01D	0760	1	280.00		280.00	19.60	299.60
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)						
BOMISC1	0760	1	300.00		300.00	21.00	321.00
	RESET VEHICLE SMART ENTRY SYSTEM (N)						
BOMISC1	0760	1	300.00		300.00	21.00	321.00
	REMOVE, INSTALL & ADJUST REAR VIEW CAMERA (N)						
BM103D	0760	1	350.00		350.00	24.50	374.50
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BKTG02R	0760	1	450.00		450.00	31.50	481.50
	REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST & ALIGN TRUNK.(N)						
BKBH01S	0760	1	840.00		840.00	58.80	898.80
	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.						

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

© SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZH023 / SOMPO INSURANCE
Chassis No: MRHFC5650JT001617
License No: SME5148U
Mileage: 5192
Engine No: R16B25501883

Document No: SVO19007900
Printed By: JESHURUEBEN
Order Date: 1. February 2019
Order Time: 2:15:52 PM
Service Advisor: RUEBEN THOMAS

BKRP02M	0760 CUT OFF & RENEW RR PANEL CUT RR FLOOR ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,800.00	2,800.00	196.00	2,996.00
BP06R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,700.00	2,700.00	189.00	2,889.00
BP02R	SPRAY PAINTING ON FRONT BUMPER & BULKHEAD	1	450.00	450.00	31.50	481.50
BMC01D	0760 REMOVE & INSTALL RADIATOR WITH FITTINGS. PRESSURE TEST COOLING SYSTEM.(N)	1	230.00 (P)	230.00	16.10	246.10
			SUM LABOUR:	9,990.00	699.30	10,689.30
			TOTAL SGD	16,034.13	1,122.38	17,156.51
Total Payable (SGD)						17,156.51

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SME5148U
Chassis No : MRHFC5650JT001617
Model : CIVIC 1.6 VTI YM2018
Owner's Name : LIM KWAN HUI
Ins Policy No. :
Date of Accident : 31/1/2019

Document No. : SQT19000750
Date : 16. Feb 2019
Customer No. : WZH023
Svc Advisor : RUEBEN THOMAS
Engine No : R16B25501883
Date | Time : 16. Feb 2019 9:05:38 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
SUPPLEMENTARY PARTS & LABOUR							
91555-TBA-K01	CLIPAMBIENT SENSOR / <i>NBC</i>	1	5.40	25	4.05	0.28	4.33
75701-TBA-A10	EMBLEM.H-MARK / <i>NBC</i>	1	12.20	25	9.15	0.64	9.79
19010-5FA-Z01	RADIATOR COMP / <i>ent</i>	1	1100.50	25	825.37	57.78	883.15
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 / <i>NBC</i>	3	23.20	25	52.20	3.65	55.85
Sum Item					890.77	62.35	953.12
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS. /	1	230.00		230.00	16.10	246.10
Sum Labor					230.00	16.10	246.10

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 1,120.77 78.45 1,199.22
Total (Inclusive of GST) 1,199.22

Printed on 16/2/2019 9:07:36 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 18 February 2019 9:30 AM
To: 'Jeshurueben Rao Thomas'; Guo Qiang (LKKAUTO)
Cc: SUR; Admin A; Admin-D (LKKAUTO)
Subject: RE: Pre-Invoice Of Vehicle No: SME5148U For Finalising

Dear Rueben,

WITHOUT PREJUDICE

Final Repair Costs \$16,034.13 before GST

Repair Period*(Working Day) 13 days instead of 14 days.

Kindly send Final invoice and all supporting documents to SOMPO INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jeshurueben Rao Thomas <jeshurueben@honda.com.sg>
Sent: Saturday, 16 February 2019 9:11 AM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: Pre-Invoice Of Vehicle No: SME5148U For Finalising

Dear Guo Qiang,

We enclosed the total final repair costs of...

Vehicle No. SME5148U

Final Repair Costs (include GST) \$17,156.51

Repair Period*(Working Day) 14 days

*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank You

Warmest Regards

Jeshurueben Rao Thomas (Rueben)
Bodyshop Service Advisor
Kah Motor Body Repair Centre
15, Ubi Road 4
Singapore 408610
Tel : 68465672
Hp : 90721766



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2019		31 Jan 2019 16:33 Edit Adj Rpt	S\$16,034.13 Edit Estimates	S\$16,034.13 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHIA WEE KEE , ID: S7722645A								
Main Claimant:	LIM KWAN HUI , ID: S8232681B								
Vehicle Reg. No.:	SME5148U	Date of Loss:	31/01/2019 09:00 - :59 [3 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1900663	Policy/Cover Note No.:	D18MTMPV01007655 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGN8660K	Policy No. (Claimant):							
		Excess:							
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/02/2019]								
Driver/Custodian (Insured):	HU KAITIAN (). NRIC: S8134060I, Tel: +6590258052								
Adj Asg. Remarks:	PIC: Rueben 90721766								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SME5148U (CMTD1900663)**
[SGN8660K]
TP
LIM KWAN HUI
Jan 31 2019 9:00AM
[CHIA WEE KEE]
Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	31/01/19 16:32	Accident Statement From: SC - Reg. No: SGN8660K, Claimant: CHIA WEE KEE	 Load HTML	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/19 16:01	Adjuster Immediate Advice	 Load HTML	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/02/19 09:33	General View	 Load JPG	☒
2	18/02/19 09:33	General View	 Load JPG	☒
3	18/02/19 09:33	General View	 Load JPG	☒
4	18/02/19 09:33	General View	 Load JPG	☒
5	18/02/19 09:33	General View	 Load JPG	☒
6	18/02/19 09:33	General View	 Load JPG	☒
7	18/02/19 09:33	General View	 Load JPG	☒
8	18/02/19 09:33	General View	 Load JPG	☒
9	18/02/19 09:33	General View	 Load JPG	☒
10	18/02/19 09:33	General View	 Load JPG	☒
11	18/02/19 09:33	General View	 Load JPG	☒
12	18/02/19 09:33	General View	 Load JPG	☒
13	18/02/19 09:33	General View	 Load JPG	☒
14	18/02/19 09:33	General View	 Load JPG	☒
15	18/02/19 09:33	General View	 Load JPG	☒
16	18/02/19 09:33	General View	 Load JPG	☒
17	18/02/19 09:33	General View	 Load JPG	☒
18	18/02/19 09:33	General View	 Load JPG	☒
19	18/02/19 09:33	General View	 Load JPG	☒
20	18/02/19 09:33	General View	 Load JPG	☒
21	18/02/19 09:33	General View	 Load JPG	☒
22	18/02/19 09:33	General View	 Load JPG	☒
23	18/02/19 09:33	General View	 Load JPG	☒
24	18/02/19 09:33	General View	 Load JPG	☒
25	18/02/19 09:33	General View	 Load JPG	☒
26	18/02/19 09:33	General View	 Load JPG	☒
27	18/02/19 09:33	General View	 Load JPG	☒
28	18/02/19 09:33	General View	 Load JPG	☒
29	18/02/19 09:33	General View	 Load JPG	☒
30	18/02/19 09:33	General View	 Load JPG	☒
31	18/02/19 09:33	General View	 Load JPG	☒
32	18/02/19 09:33	General View	 Load JPG	☐

Assessment Reports			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	18/02/19 09:33	General View	 Load JPG	☒
34	18/02/19 09:33	General View	 Load JPG	☒
35	18/02/19 09:33	General View	 Load JPG	☒
36	18/02/19 09:33	General View	 Load JPG	☒
37	18/02/19 09:33	General View	 Load JPG	☒
38	18/02/19 09:33	General View	 Load JPG	☒
39	18/02/19 09:33	General View	 Load JPG	☒
40	18/02/19 09:33	General View	 Load JPG	☒
41	18/02/19 09:33	General View	 Load JPG	☒
42	18/02/19 09:33	General View	 Load JPG	☒
43	18/02/19 09:33	General View	 Load JPG	☒
44	18/02/19 09:33	General View	 Load JPG	☒
45	18/02/19 09:33	General View	 Load JPG	☒
46	18/02/19 09:33	General View	 Load JPG	☒
47	18/02/19 09:33	General View	 Load JPG	☒
48	18/02/19 09:33	General View	 Load JPG	☒
49	18/02/19 09:33	General View	 Load JPG	☒
50	18/02/19 09:33	General View	 Load JPG	☒
51	18/02/19 09:33	General View	 Load JPG	☒
52	18/02/19 09:33	General View	 Load JPG	☒
53	18/02/19 09:33	General View	 Load JPG	☒
54	18/02/19 09:33	General View	 Load JPG	☒
55	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
56	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
57	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
58	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
59	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
60	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
61	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
62	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
63	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
64	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
65	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
66	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
67	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
68	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
69	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
70	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
71	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
72	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
73	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
74	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
75	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
76	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
77	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
78	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
79	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
80	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
81	18/02/19 09:35	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
82	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
83	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
84	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
85	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
86	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
87	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
88	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
89	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
90	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
91	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
92	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
93	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
94	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
95	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
96	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
97	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
98	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
99	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
100	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
101	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
102	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
103	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
104	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
105	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
106	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
107	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
108	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
109	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
110	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
111	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
112	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
113	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
114	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
115	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
116	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
117	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
118	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
119	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
120	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
121	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
122	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
123	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
124	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
125	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
126	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
127	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
128	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
129	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
130	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
131	18/02/19 09:35	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
132	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
133	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
134	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
135	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
136	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
137	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
138	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
139	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
140	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
141	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
142	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
143	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
144	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
145	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
146	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
147	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
148	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
149	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
150	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
151	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
152	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
153	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
154	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
155	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
156	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
157	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
158	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
159	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
160	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
161	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
162	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
163	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
164	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
165	18/02/19 09:35	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/02/19 16:40	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002120/GVD3E2

Date: 18/02/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTMPV01007655

Claimant Vehicle No: SME5148U Insured Vehicle No: SGN8660K

Date of Loss: 31/01/2019 Nature of Claim: TP Claim No: CMTD1900663

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME5148U

Make & Model: HONDA CIVIC, 1.6 L VTI (A) Engine No: R16B25501883

Reg. Date: 02/10/2018 (Man. Year: 2018) Chassis No: MRHFC5650JT001617

Colour: Black Odometer: 0 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16

Front Left Side: Hankook 9 mm Rear Left Side: Hankook 9 mm

Front Right Side: Hankook 9 mm Rear Right Side: Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,952.54	6,064.13	888.41	12.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,950.00	9,970.00	2,980.00	23.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,902.54	16,034.13	3,868.41	19.44
+ GST 7.00/7.00% (S\$)	1,393.18	1,122.39	270.79	19.44
Nett Amount (S\$)	21,295.72	17,156.52	4,139.20	19.44

INSPECTION

Date of Assignment: 31/01/2019

Date Inspected: 01/02/2019 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 13.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2019)
Parts: 143	HONDA CIVIC 1.6 L VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SME5148U)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*NUMBER PLATE WITH CASING	Bent	90.00 FS	*90.00 FS
2	1		*LID COMP TRUNK	Buckled	364.65 FS	*364.65 FS
3	1		*WEATHERSTRIPTRUNK LID	Twisted	52.50 FS	*52.50 FS
4	1		*HINGE COMPL. TRUNK	Not Necessary	33.60 FS	*- FS
5	1		*HINGE COMPR.TRUNK	Not Necessary	33.60 FS	*- FS
6	1		*LOCK ASSYTRUNK	Bent	55.72 FS	*55.72 FS
7	1		*GARNISH ASSYRR.LICENSE	Missing	75.45 FS	*75.45 FS
8	1		*EMBLEM SETRR.	Necessary	8.85 FS	*8.85 FS
9	1		*EMBLEMRR.	Necessary	8.25 FS	*8.25 FS
10	1		*FACE ASSY,RR.BUMPER	Deformed	462.90 FS	*462.90 FS
11	1		*CLIP, BUMPER (7PCS)	Necessary	12.07 FS	*12.07 FS
12	1		*GARNISH, RR. BUMPER LOWER	Deformed	27.30 FS	*27.30 FS
13	1		*COVERRR.TOWING HOOK	Cut	6.52 FS	*6.52 FS
14	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
15	1		*SPACERR.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
16	1		*BRACKETL.RR.BUMPER SIDE	Necessary	1.72 FS	*1.72 FS
17	1		*BRACKETR.RR.BUMPER SIDE	Necessary	1.72 FS	*1.72 FS
18	1		*BEAM COMPRR.BUMPER	Bent	123.52 FS	*123.52 FS
19	1		*GARNISHL.RR.BUMPER SIDE	Deformed	5.85 FS	*5.85 FS
20	1		*GARNISHR.RR.BUMPER SIDE	Scratched	5.85 FS	*5.85 FS
21	1		*REFLECTOR ASSYL.RR	Not Necessary	5.40 FS	*- FS
22	1		*REFLECTOR ASSYR.RR	Not Necessary	5.40 FS	*- FS
23	1		*COVERR.FINISHER	Not Necessary	8.92 FS	*- FS
24	1		*LIGHT ASSYL.LID	Cut	91.72 FS	*91.72 FS
25	1		*LIGHT ASSYR.LID	Cut	91.72 FS	*91.72 FS
26	1		*TAILLIGHT ASSYL.	Cracked	210.97 FS	*210.97 FS
27	1		*TAILLIGHT ASSYR.	Cracked	196.05 FS	*196.05 FS
28	1		*CAMERA ASSY, RR VI	Not Necessary	236.70 FS	*- FS
29	1		*SUB CORDRR.BUMPER CORNER SENS	Not Necessary	21.07 FS	*- FS
30	1		*SENSOR ASSY, PARKING (4PCS)	Damaged	437.40 FS	*401.70 FS
31	1		*ANTENNA ASSYL.F.	Damaged	44.47 FS	*44.47 FS
32	1		*BUZZER ASSYSMART	Damaged	45.97 FS	*45.97 FS
33	1		*PANEL SETRR.	Buckled	182.32 FS	*182.32 FS
34	1		*STIFFENERL.RR.PANEL SIDE	Buckled	20.02 FS	*20.02 FS
35	1		*STIFFENER,R.RR.PANEL SIDE	Buckled	20.02 FS	*20.02 FS
36	1		*PAN COMPSPARE TIRE	Not Necessary	162.52 FS	*- FS
37	1		*OIL SHEET	Not Necessary	27.07 FS	*- FS
38	1		*LINING ASSYTRUNK LID	Not Necessary	24.67 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*LINING ASSYRR.PANEL	Deformed	37.72 FS	*37.72 FS
40	1		*LID ASSYSPARE TIRE	Not Necessary	45.15 FS	*- FS
41	1		*BOX COMPTOOL	Not Necessary	28.50 FS	*- FS
42	1		*LINING ASSYL.TRUNK SIDE	Not Necessary	36.67 FS	*- FS
43	1		*LINING ASSYR.TRUNK SIDE	Not Necessary	36.67 FS	*- FS
44	1		*FACEFR.BUMPER	Deformed	434.92 FS	*434.92 FS
45	1		*CLIP, BUMPER (16PCS)	Necessary	27.60 FS	*27.60 FS
46	1		*SPACERL.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
47	1		*SPACERR.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
48	1		*BEAML.FR.BUMPER UPPER	Broken	20.02 FS	*20.02 FS
49	1		*BEAMR.FR.BUMPER UPPER	Broken	20.02 FS	*20.02 FS
50	1		*GRILLEFR.BUMPER LOWER	Not Necessary	27.07 FS	*- FS
51	1		*GARNISHL.FR.BUMPER SIDE	Not Necessary	13.50 FS	*- FS
52	1		*GARNISHR.FR.BUMPER SIDE	Not Necessary	13.50 FS	*- FS
53	1		*BASEFR LIC PLATE	Not Necessary	28.35 FS	*- FS
54	1		*BEAM COMPFR.BUMPER	Bent	259.42 FS	*259.42 FS
55	1		*BEAM COMPFR.BUMPER CENTER UPP	Bent	161.10 FS	*161.10 FS
56	1		*BASE,FR.GRILLE CHROME	Cracked	55.35 FS	*55.35 FS
57	1		*MOLDINGFR.GRILLE	Cracked	75.30 FS	*75.30 FS
58	1		*EMBLEM	Necessary	11.25 FS	*11.25 FS
59	1		*NUTPUSH 3MM (2PCS)	Necessary	3.15 FS	*3.15 FS
60	1		*RUBBERHOOD SEAL	Not Necessary	20.70 FS	*- FS
61	1		*COVERFR.BULKHEAD	Not Necessary	13.65 FS	*- FS
62	1		*HEADLIGHT ASSYL	Cracked	439.27 FS	*439.27 FS
63	1		*HEADLIGHT ASSY, R	Cracked	439.27 FS	*439.27 FS
64	1		*CONDENSER ASSY	Bent	528.30 FS	*528.30 FS
65	1		*AIR-CON SENSOR CLIP (NPA)	Broken	0.00 FS	*- FS
66	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
67	1		*CLIPAMBIENT SENSOR	Necessary	4.05 FS	*4.05 FS
68	1		*EMBLEM,H-MARK	Necessary	9.15 FS	*9.15 FS
69	1		*RADIATOR COMP	Cut	825.37 FS	*825.37 FS
70	3		*COOLANT ANTI-FREEZE TYPE 2	Necessary	52.20 FS	*52.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,952.54	6,064.13
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	100.00	100.00
2	BODY JOINT SEALANT	New	200.00	160.00
3	BODY UNDERSIDE COATING	New	100.00	100.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	180.00
5	REMOVE & RENEW REVERSE SENSORS - 4PCS	New	150.00	130.00
6	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	250.00	250.00
7	REMOVE & RENEW RR FLOOR INSULATOR	New	250.00	250.00
8	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	280.00	280.00
9	RESET VEHICLE SMART ENTRY SYSTEM	New	320.00	300.00
10	REMOVE, INSTALL & ADJUST REAR VIEW CAMERA	New	320.00	300.00
11	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	350.00	350.00
12	REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST &	New	450.00	450.00
13	STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGED PARTS	New	1,200.00	840.00
14	CUT OFF & RENEW RR PANEL. CUT RR FLOOR	New	4,500.00	2,800.00
15	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	2,900.00	2,700.00
16	SPRAY PAINTING ON FRONT BUMPER & BULKHEAD	New	1,000.00	450.00
17	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	230.00	230.00
18	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	100.00	100.00
Gross Labour Cost (\$\$)			12,950.00	9,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >