

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE
50 RAFFLES PLACE #05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SME5148U
Chassis No : MRHFC5650JT001617
Model : CIVIC 1.6 VTI YM2018
Owner's Name : LIM KWAN HUI
Ins Policy No. :
Date of Accident : 31/1/2019

Document No. : SQT19000750
Date : 16. Feb 2019
Customer No. : WZH023
Svc Advisor : RUEBEN THOMAS
Engine No : R16B25501883
Date | Time : 16. Feb 2019 9:05:38 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
SUPPLEMENTARY PARTS & LABOUR							
91555-TBA-K01	CLIPAMBIENT SENSOR / NBC	1	5.40	25	4.05	0.28	4.33
75701-TBA-A10	EMBLEM,H-MARK / NBC	1	12.20	25	9.15	0.64	9.79
19010-5FA-Z01	RADIATOR COMP / ent	1	1100.50	25	825.37	57.78	883.15
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 / NBC.	3	23.20	25	52.20	3.65	55.85
Sum Item					890.77	62.35	953.12
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS. /	1	230.00		230.00	16.10	246.10
Sum Labor					230.00	16.10	246.10

Survey By

Date & Time

Excess

Status

Signature

Total Amount 1,120.77 78.45 1,199.22

Total (Inclusive of GST) **1,199.22**

Printed on 16/2/2019 9:07:36 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)