

MBM WHEELPOWER PTE LTD

Your Ref: SKL1090P

Our Ref: SMH2835Z

To: AXA

CC

Fax

*Not with paint
Resurvey B & paint
4-5 days*

Date: 31/1/2019
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: HONDA SHUTTLE HYBRID 1.5
Chassis No.: GB72000055
Engine No.: LEB7100080
Year of Make: 2018
Accident Date: 29 January 2019

ESTIMATE FOR VEHICLE NO. : SMH2835Z

DESCRIPTION

REAR WINDSCREEN MOUDLING
TAIL GATE
TAIL GATE WEATHERSTRIP
TAIL GATE LOCK
TAIL GATE STRIKER
TAIL GATE INNER TRIM BOARD
TAIL GATE INNER TRIM BOARD CLIPS
TAIL GATE LAMP RH
TAIL GATE LAMP LH
TAIL GATE "SHUTTLE" EMBLEM
TAIL GATE "HYBRID" EMBLEM
TAIL GATE "HONDA" LOGO
TAIL GATE CENTER OUTER CHROME MOULDING
REAR BUMPER
REAR BUMPER CLIPS
REAR BUMPER RH REFLECTOR PLATE
REAR BUMPER LH REFLECTOR PLATE
REAR BUMPER RH REFLECTOR
REAR BUMPER LH REFLECTOR
REAR BUMPER RH TOW COVER

QTY

1 \$
1 \$
1 \$
1 \$
1 \$
1 \$
10 \$
1 \$
1 \$
1 \$
1 \$
1 \$
1 \$
1 \$
1 \$
10 \$
1 \$
1 \$
1 \$
1 \$
1 \$

List Price

166.00
1,432.00
220.00
308.00
55.00
394.00
50.00
490.00
490.00
76.00
92.00
70.00
460.00
1,390.00
50.00
75.00
75.00
187.00
187.00
40.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

mbm wheelpower

END PANEL	1	\$		727.00 ?
END PANEL TOP GARNISH	1	\$	<i>Ref</i>	216.00 ✓
END PANEL TOP GARNISH CLIPS	10	\$	<i>Ref</i>	50.00 ✓
REAR RH FENDER INNER TRIM BOARD	1	\$	<i>Ref</i>	460.00 X
REAR LH FENDER INNER TRIM BOARD	1	\$	<i>Ref</i>	460.00 ✓
Total:			\$	8,220.00
LESS 20%			\$	(1,644.00)
Parts Total:			\$	6,576.00

SPECIAL NETT

BODY SEALANT	1	\$		80.00 ?
REVERSE SENSOR	1 SET	\$		400.00 ?
WINDSCREEN SEALANT	1	\$	<i>Ref 405m</i>	80.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$		?	1,200.00
TO REMOVE AND REPLACE REAR WINDSCREEN	\$		<i>1201</i>	150.00
TO DISMANTLE & TRANSFER TAIL GATE FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR	\$		<i>601</i>	80.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$		?	100.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$		?	150.00
TO REMOVE & REPLACE BUMPER SENSORS	\$			40.00 ✓
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$		<i>201</i>	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$		<i>6601</i>	1,200.00
Total:			\$	10,136.00
7% GST:			\$	709.52
Grand Total:			\$	10,845.52

Mbm wheelpowerpte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
t62628888 f64525333

Company Registration Number : 200204110W