



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJB 4325 H
HONDA STREAM
RN6

not Arthur
18/2/19
Thyph. Aden
5 day.

4/5 ~~4500~~

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
	REAR BOOTLID <i>300/100/100 ✓</i> <i>903.00</i>		\$ 963.00 ✓
	REAR BOOTLID LOCK <i>7m ✓</i> <i>109.50</i>		\$ 289.00 ✓
	REAR BOOTLID WEATHERSTRIP <i>7m ✓</i>		\$ 162.10 ✓
	REAR BOOTLID INNER TRIM <i>De/cm ✓</i>		\$ 282.90 ✓
	REAR BOOTLID INNER TRIM HANDLE <i>11 X</i>		\$ 29.00 X
	REAR BOOTLID LOGO <i>11 X</i>		\$ 58.90 X
	REAR BOOTLID EMBLEM - STREAM <i>1m ✓</i> <i>32.60</i>		\$ 48.60 ✓
	REAR BOOTLID WINDSCREEN GLASS MOULDING <i>12L ✓</i>		\$ 65.00 ✓
	REAR BUMPER <i>70/100 ✓</i> <i>665.40</i>		\$ 832.90 ✓
	REAR BUMPER TOW COVER <i>7m ✓</i>		\$ 28.40 ✓
	REAR BUMPER SIDE RETAINER L+R <i>2/100 ✓</i>		\$ 56.80 ✓
	REAR BUMPER BRACKET L+R <i>11 X</i>		\$ 68.20 X
	TAILLAMP L+R <i>2m ✓</i> <i>338.80 x 2 = 677.60</i>		\$ 852.40 ✓
	TAILLAMP PANEL L+R <i>12 X</i>		\$ 380.00 X
	TAILLAMP CLIPS L+R <i>12 X</i>		\$ 20.00 X
	REAR END PANEL <i>300/100 ✓</i> <i>306.10</i>		\$ 486.70 ✓
	REAR END PANEL INNER PANEL <i>7m. 12 X</i>		\$ 346.30 X
	REAR END PANEL TOP GARNISH <i>7m ✓</i>		\$ 156.80 ✓
	REAR FENDER L+R <i>12 X</i>		REPAIR X
	REAR FENDER INNER TRIM L+R <i>12 X</i>		\$ 796.00 ✓
	REAR FLOOR PANEL <i>12 X</i>		\$ 892.30 X
	REAR FLOOR PANEL TOP BOARD L+R <i>11 X</i>		\$ 480.00 X
	SPARE WHEEL BRACKET <i>12 X</i>		\$ 167.00 X
	REAR EXHAUST PIPE <i>11 X</i>		\$ 786.90 X
	REAR EXHAUST PIPE GASKET <i>11 X</i>		\$ 34.70 X
	REAR EXHAUST PIPE MOUNTING <i>11 X</i>		\$ 45.90 X
		SUBTOTAL	\$ 8,329.80
		LESS 20%	\$ 1,665.96
		PARTS TOTAL	\$ 6,663.84
	SPECIAL NETT	QTY	PRICE
	REAR NUMBER PLATE <i>500 X</i>		\$ 80.00 X
	REVERSE SENSOR <i>500/100 ✓</i> <i>200 5.00</i>		\$ 250.00 X
	REVERSE CAM <i>11 X</i>		\$ 400.00 X
	REAR END PANEL SEALANT <i>1m 50 5.00</i>		\$ 100.00 50
	SPARE WHEEL PANEL SEALANT <i>11 X</i>		\$ 100.00 X
	SPARE WHEEL INSULATOR <i>11 X</i>		\$ 150.00 X
	REAR BUMPER CLIPS <i>1m 40 5.00</i>		\$ 50.00 40
	REAR FENDER COWLING CLIPS <i>11 X</i>		\$ 100.00 X
	REAR FENDER INNER TRIM CLIPS <i>11 X</i>		\$ 100.00 X

BOOTLID INNER TRIM CLIPS	nm ✓		\$ 50.00	10
REAR END PANEL TOP GARNISH CLIPS	11 X		\$ 50.00	X
		SPECIAL NETT TOTAL	\$ 1,430.00	
LABOUR		QTY	PRICE	
TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	680		\$ 1,600.00	
TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1000		\$ 1,400.00	
TO RUST PROOF ACCIDENT AFFECTED AREA	60		\$ 100.00	
TO RNR REAR WINDSCREEN	120		\$ 150.00	
TO RNR REAR BOOT MECHANISM	60		\$ 150.00	
TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	80		\$ 400.00	
TO RNR REVERSE SENSOR & CHECK FUNCTION.	50		\$ 80.00	
TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	17X		\$ 200.00	
TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	30		\$ 100.00	
TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11X		\$ 150.00	
TO DO WATER LEAK TEST .	11X		\$ 100.00	
TO CLEAN AND VACUUM TO ASSIST WORK LOAD	11X		\$ 100.00	
		LABOUR TOTAL	\$ 4,530.00	
		GRAND TOTAL COST	\$ 12,623.84	

PAGE 2 OF 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4242-20
507
P-2121-10
S.N-340-20
1dne-2080-20
45241-10