



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2002992
INV Date 07/04/2020
Reference CC4/EQI19002132/R1pa3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SKM 5207P
Insured Veh. GBE 2324C
Claim No. DM19HO00295/JT
Policy No. DMCPHQ18-006721
Accident Date 28/01/2019
Inspection Date 31/01/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI19002132/R1pa3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 07-04-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 2324C	Veh. Inspected	SKM 5207P
Policy No.	DMCPHQ18-006721	Coverage (\$)	0.00
Claim No.	DM19HO00295/JT	Excess (\$)	0.00
Assign From	JANICE	Assign Date	31/01/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ B180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2462422J230232	Colour	GREY
Odometer	90956	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/01/2019	Inspection Date	31/01/2019
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 5207P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (WCP)	DEFORMED	730.00	730.00
1	REAR BUMPER SIDE HOLDER -LH (WCP)	NOT NECESSARY	8.00	-
1	REAR BUMPER SIDE HOLDER -RH(WCP)	NOT NECESSARY	8.00	-
10	REAR BUMPER CLIPS @\$2.80(WCP)	NECESSARY	28.00	28.00
1	REAR BUMPER REINFORCEMENT (WCP)	DEFORMED	240.00	240.00
1	REAR BUMPER FOAM -LH/RH ,CENTRE (WCP)	NOT NECESSARY	57.00	-
1	REAR BUMPER LOWER GARNISH (WCP)	DEFORMED	65.00	65.00
1	REAR BUMPER LOWER CHROME -LH (WCP)	NECESSARY	73.00	73.00
1	REAR BUMPER LOWER CHROME -RH (WCP)	NECESSARY	73.00	73.00
6	REAR BUMPER SENSOR @\$140.00 (WCP)	NECESSARY (2 PCS ONLY)	840.00	280.00
1	REAR BUMPER SENSOR WIRE (WCP)	NOT NECESSARY	50.00	-
1	REAR BUMPER TOWING COVER -RH (WCP)	MISSING	36.00	36.00
1	REAR BUMPER TOP CHROME (WCP)	NECESSARY	82.00	82.00
1	REAR BOOT (WCP)	BENT	1,100.00	1,100.00
1	REAR BOOT GLASS (WCP)	BROKEN	1,150.00	1,150.00
1	REAR BOOT TOP LOCK (WCP)	NECESSARY	114.00	114.00
1	REAR BOOT BOTTOM LOCK (WCP)	NOT NECESSARY	20.00	-
1	REAR BOOT MER LOGO (WCP)	NECESSARY	27.00	27.00
1	REAR BOOT B180 WORDING (WCP)	NECESSARY	45.00	45.00
1	REAR BOOT OUTER CHROME (WCP)	SCRATCHED	138.00	138.00
1	REAR BOOT RUBBER (WCP)	NOT NECESSARY	93.00	-
1	REAR BOOT REFLECTOR -LH (WCP)	NOT NECESSARY	220.00	-
1	REAR BOOT REFLECTOR -RH (WCP)	CRACKED	220.00	220.00
1	REAR BOOT INNER TRIM -BIG (WCP)	DEFORMED	87.00	87.00
1	REAR BOOT INNER TRIM -LH (WCP)	NOT NECESSARY	78.00	-
1	REAR BOOT INNER TRIM -RH (WCP)	NOT NECESSARY	78.00	-
1	REAR SPARE PANEL FLOOR PANEL W/TOP INSULATOR (WCP)	NOT NECESSARY	450.00	-
1	REAR PANEL (WCP)	NOT NECESSARY	520.00	-
1	REAR PANEL TOP GARNISH (WCP)	NECESSARY	45.00	44.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST PIPE CHROME -LH (WCP)	NOT NECESSARY	155.00	-
1	REAR EXHAUST PIPE CHROME -RH (WCP)	SCRATCHED	155.00	155.00
1	TAIL LAMP -LH (WCP)	NOT NECESSARY	230.00	-
1	TAIL LAMP -RH (WCP)	NOT NECESSARY	230.00	-
1	REAR SPAFETY BELT LH (WCP)	NECESSARY	220.00	220.00
1	REAR SPAFETY BELT RH (WCP)	NECESSARY	220.00	220.00
1	FRONT SAFETY BELT -RH (WCP)	NECESSARY	355.00	335.00
1	FRONT SAFETY BELT BUCKLE W/SENSOR -LH (WCP)	BENT	135.00	135.00
1	FRONT SAFETY BELT BUCKLE W/SENSOR RH (WCP)	BENT	135.00	135.00
1	L/R FENDER INNER TOP TRIM (WCP)	NOT NECESSARY	110.00	-
1	REAR BOOT LAMP SPONGE -LH (WCP) (ADDITIONAL)	NECESSARY	15.00	15.00
1	REAR BOOT LAMP SPONGE -RH (WCP) (ADDITIONAL)	NECESSARY	15.00	15.00
	COST PLUS 15%		1,297.50	864.30
			9,947.50	6,626.30
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOT GLASS V-COOL (SN)	NECESSARY	400.00	300.00
1	SET REAR NUMBER PLATE WITH CASING (SN)	BENT	35.00	35.00
			435.00	335.00
	<u>LABOUR</u>			
1	CONTROL OIL FUL PUMP .	NOT NECESSARY	250.00	-
	TO KNOCK OUT DENTS ON REAR PANEL,REAR SPARE TYRE FLOOR PANEL ,REAR BOOT.CUT /WELD & REPLACE ACCIDENT PARTS.		1,200.00	600.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		1,200.00	600.00
	TO CHECK WIRING.		50.00	30.00
	TO REMOVE REFIX END PANEL GARNISH TO FACILITATE REPAIRS.		80.00	60.00
	TO REMOVE ,REPLACE REAR BUMPER SENSOR .		100.00	80.00
	TO REMOVE,REPLACE FRONT HEADREST -LH,RH.	NOT NECESSARY	300.00	-
	TO RESEY ECU.		200.00	200.00
	TO TUFF KOTE.		120.00	80.00
	TO REMOVE,REPLACE REAR BOOT GLASS.		150.00	120.00
	TO REMOVE,REPLACE REAR EXHAUST PIPE.		150.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE ,REPLACE REAR R/F SAFETY BELTS -LH,RH & BUCKLES.	NOT NECESSARY	500.00	400.00
	TO REMOVE,REFIT REAR SEAT ,GARNISH & RELATED PARTS.		300.00	200.00
	TO REPROGRAM PRESAFE FUNCTIONS TROUBLE CODE.		600.00	-
			5,200.00	2,470.00
GRAND TOTAL			15,582.50	9,431.30
RECOMMENDED COST OF REPAIRS				9,431.30

Report Ref No. CC4/EQI19002132/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKM 5207P

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKM 5207P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

