Date: 07/04/2020



 $51~\mathrm{UBI~AVE~1}, \#02\text{-}25~\mathrm{PAYA~UBI~INDUSTRIAL~PARK}, \mathrm{SINGAPORE~408933~TEL:} \\ (065)~62563561~\mathrm{FAX:} \\ (065)~62564315$

To: M/s EQ INSURANCE COMPANY LTD

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBE 2324C	(Insd Veh)	Your Ref. No. : DM19HO00295/JT
	SKM 5207P	(TP Veh)	Our Ref. No. : CC4/EQI19002132/R1pa3q2
Date of Accident	28/1/2019		

Liability		100%	
Final Repair Cost	: \$	10,091.49	
Loss of Use	: \$		days
Rental (If any)	: \$	3,400.00	34 days
Others:	: \$	2.00	
	: \$		
		13,493.49	
Final Settlement Sum	: \$	13,000.00	GLOBAL SUM
Remarks	:		

Pay	Payment Instruction: Payee's Breakdown							
1)	PROGRESSIVE CAR CARE PTE LTD	:\$	13,000.00					
		:\$						

JOANNE LEE LKK Auto Consultants Pte Ltd



Progressive Car Care Pte Ltd (Co. Reg. No. 201006949C) Blk 3022A Ubi Road 1 #01-45/ 46 S408716 T: +65 6741 5336 | F: +65 6741 7208 E: claims@procarcare.com.sg W: www. procarcare.com.sg

Our Ref: TP 0119-5383

25.05.2019

EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

Attn: Motor Claims Department

Dear Sir,

ACCIDENT INVOLVING VEHICLE: SKM 5207 P & GBE 2324 C ON 28.01.2019

We are the authorized repair workshop for the owner of motor vehicle no: SKM 5207 P which was involved in the above captioned accident with your insured vehicle: GBE 2324 C. The vehicle owner has requested and authorized us to assist him in presenting the claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Cost of Repair (incl gst)	\$ 10,091.49
02)	GIA Search Fee	\$ 2.00
03)	Reimbursement - Loss of Rental (36days)	\$ 3,700.00
		\$ 13,793.49

We enclosed herewith the following documents to support the claims:-

- a) Letter of Authorisation / GIA report(s) / Insurance Certificate, etc...
- b) Final Tax Invoice / Car Rental No 7362 / GIA Search Fee Invoice

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you Yours faithfully

Pei Wen

For Progressive Car Care Pte Ltd

Email: claims@procarcare.com.sg



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC4/EQI19002132/R1hb3

04 April 2019

YING SENG AIR-CON & REFRIGERATION SERVICE

810 GEYLANG ROAD #04-14 CITY PLAZA SINGAPORE 409286 Attn: The Management

Dear Sir/Madam,

ACCIDENT INVOLVING GBE 2324C AND SKM5207P ON 28/01/2019

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SKM 5207P against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE

Case Handler

DID: 6749 5792

FAX: 6741 4108

EMAIL: vicalpeh@lkkauto.com



Progressive Car Care Pte Ltd (Co. Reg. No. 201006949C) Blk 3022A Ubi Road 1 #01-45/ 46 S408716 T: +65 6741 5336 | F: +65 6741 7208 E: claims@procarcare.com.sg W: www. procarcare.com.sg

Date : 25 May 2019
Date : 25 May 2019 Our Ref : TP 0119-5383
11 Koh Cheng Chye Nric No S2512381F
Residing at 32 Ah Hood Road #11-02 Smgapore owner of
Vehicle No_SKM5307Phereby authorize PROGRESSIVE CAR CARE PTE LTD at
Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716 to resolve the above matter.
In respect of this authorization, I./ We confirmed to accept whatsoever settled or agreed by them
and also agreed that all Payments include Loss of Use to make in favour of
PROGRESSIVE CAR CARE PTE LTD.
I / We am/are fully aware that all settlement made in respect of the accident occurred on

1 Cohang Chys SIGNATURE OF OWNER

Final discharge of the claims inclusive of damages, loss of use etc.

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg GST:201006949C RCB NO:201006949C

KOH CHENG CHYE M/S:

32 AH HOOD ROAD

#11-02

SINGAPORE 329977

ATTN:

Your Ref No:

TP 0119-5383 Claim Type: Third Party

Accident Date: TP Veh Reg No:

28/01/2019 GBE 2324 C Claim No:

EST1504509

Ref No:

PS1503445

Date:

25 May 2019 A27849501QMY

Policy No: Veh Reg No:

SKM5207P

Make/Model:

MERCEDES BEN B180

(R17 BI)

Chassis No:

WDD2462422J230232

Engine No: Reg. Date:

27091030323135 12/03/2014

Final Repair Bill SKM5207P

	Description	U/Price	Quantity	Cost	Amount
				<u>SS</u>	<u>S\$</u>
	Special Net				
1	REAR BOOT GLASS V-COOL	300.00	1 PC	300.00	
2	REAR NUMBER PLATE WITH CASING	35.00	1 SET	35.00	
					335.00
	Spare Parts		24		
3	REAR BUMPER	730.00	1 PC	730.00	
4	REAR BUMPER CLIPS	2.80	10 PC	28.00	
5	REAR BUMPER REINFORCEMENT	240.00	1 PC	240.00	
6	REAR BUMPER LOWER GARNISH	65.00	1 PC	65.00	
7	REAR BUMPER LOWER CHROME - LH	73.00	1 PC	73.00	
8	REAR BUMPER LOWER CHROME - RH	73.00	1 PC	73.00	
9	REAR BUMPER SENSOR	140.00	2 PC	280.00	
10	REAR BUMPER TOWING COVER - RH	36.00	1 PC	36.00	
11	REAR BUMPER TOP CHROME	82.00	1 PC	82.00	
12	REAR BOOT	1,100.00	1 PC	1,100.00	
13	REAR BOOT GLASS W/MOULDING	1,150.00	1 PC	1,150.00	
14	REAR BOOT TOP LOCK	114.00	1 PC	114.00	
15	REAR BOOT MER LOGO	27.00	1 PC	27.00	
16	REAR BOOT B180 WORDING	45.00	1 PC	45.00	
17	REAR BOOT OUTER CHROME	138.00	1 PC	138.00	
18	REAR BOOT REFLECTOR - RH	220.00	1 PC	220.00	
19	REAR BOOT INNER TRIM - BIG	87.00	1 PC	87.00	
20	REAR PANEL TOP GARNISH	44.00	1 PC	44.00	
21	REAR EXHAUST PIPE CHROME - RH	155.00	1 PC	155.00	
22	REAR SAFETY BELT - LH	220.00	I PC	220.00	
23	REAR SAFETY BELT - RH	220.00	I PCS	220.00	
24	FRONT SAFETY BELT - RH	335.00	1 PCS	335.00	
25	REAR SAFETY BELT BUCKLE W/SENSOR - LH	135.00	1 PCS	135.00	
26	REAR SAFETY BELT BUCKLE W/SENSOR - RH	135.00	I PCS	135.00	
27	REAR BOOT LAMP SPONGE - LH	15.00	I PC	15.00	
28	REAR BOOT LAMP SPONGE - RH	15.00	1 PC	15.00	
	•			5,762.00	
		Add	15%	864.30	6,626.30

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg GST:201006949C RCB NO:201006949C

KOH CHENG CHYE M/S:

32 AH HOOD ROAD

#11-02

SINGAPORE 329977

ATTN:

Your Ref No:

Claim Type:

Accident Date: TP Veh Reg No:

TP 0119-5383 Third Party

28/01/2019 GBE 2324 C Date:

Ref No:

Claim No:

Policy No:

Veh Reg No: SKM5207P MERCEDES BEN B180

Make/Model:

Chassis No: Engine No:

27091030323135

WDD2462422J230232

EST1504509

PS1503445

25 May 2019

A27849501QMY

Reg. Date:

12/03/2014

(R17 BI)

Final Repair Bill SKM5207P

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	SS
Labour				
29 TO KNOCK OUT DENTS ON REAR PANEL, REAR SPARE TYRE FLOOR PANEL, REAR BOOT, CUT/WELD & REPLACE ACCIDENT PARTS	600.00	1 JOB	600.00	
30 TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.00	1 JOB	600.00	
31 TO CHECK WIRING	30.00	1 JOB	30.00	
32 TO REMOVE, REFIX END PANEL GARNISH TO FACILITATE REPAIRS	60.00	1 JOB	60.00	
33 TO REMOVE. REPLACE REAR BUMPER SENSOR	80.00	1 JOB	80.00	
34 TO RESET ECU	200.00	1 JOB	200.00	
35 TO TUFF-KOTE	80.00	1 JOB	80.00	
36 TO REMOVE, REPLACE REAR BOOT GLASS	120.00	1 JOB	120.00	
37 TO REMOVE, REPLACE REAR EXHAUST PIPE	100.00	1 JOB	100.00	
38 TO REMOVE, REPLACE REAR R/F SAFETY BELTS - LH, RH & BUCKLES	400.00	1 JOB	400.00	
39 TO REMOVE, REFIT REAR SEAT, GARNISH & RELATED PARTS	200.00	1 JOB	200.00	
				2,470.00

Total S\$ 9.431.30 Add GST @ 7% 660.19 Total Amount payable S\$ 10,091.49

TOTAL: SINGAPORE DOLLAR TEN THOUSAND NINETY ONE AND CENTS FORTY NINE ONLY

For Progressive Car Care Pte Ltd PROGRESSIVE CAR CARE PTE ATD Blk 3022A Ubi Road 1 # 01-45/46

Singapore 408716 Tel: 6741 5336 Fax: 6741 72/08 Email: claims@procarcaré.com.sg

AUTHORISED SIGNATURE



EXPRESS RENTAL

TP 0119-53 SKM207 p 53

Blk 3022A Ubi Road 1 #01-45 Singapore 408716 Tel: 6841 8055 (2 Lines) Fax: 6741 7208

RENTAL AGREEMENT NO: 7362

and an extension process of the contract of th	ne do to do dividir de la companione de	RENTAL AGREEMENT NO: 1302
HIRER'S PARTICULAR	e a linguistre be a	GUARANTOR / ADD. DRIVER
Name : Koh Chong Ch	10.	Name :
Address : 32 Ah Hosel	Rd.	Address:
#11-02 (329977))	owite los roquer. Per o o o
removing people to the light sure that good clays in the Earth on Market A. Harris of	1	Complete the minimum of the sea stands with the three first in all the search matter, at late, while the control of the search o
Nric No : 82512381F	idayo tahaning ma	Nric No :
Tel (R) :		Tel (R) Surface in a great de lace de la lace de la companya de Adrience
H/P 975144 3	Section 1-100 And	H/P send of the control of the contr
	No part of the same	The party of the first of the party of the p
Off :		Off grant toutline research for any and grant to the second secon
Licence Expiry : Class :	S None could be by a b	Licence Expiry : Class :
Driving		Driving to the east, and patch and provide the east of
Experience : Age :		Experience : Age :
Co.Name/ Address :		Co.Name/ Address
At a state of the		an including growthere, and the service of the serv
	a ye ya ji in inigi.	representations of the control of th
and the second and a second are second as the second and the secon	per concernation	The second secon
more it as to the entire stream of acts As before the form suffer fan falliel	Processor 1	Latrace representative that of the execution of the partial of the extraction of the first of the execution
Occupation:	er of the state of the state of	Occupation:
Make : Merceles B	enz.	Vehicle No: 5K82782 H.
RENTAL CHARGES	S\$	METHODS OF PAYMENT
Hours @\$ per hour	0.0	(0.1190 to 0.014"
6 Days @\$ 150 per day	900.	Cash and the second to require the confidence of
Weeks @\$ per week Monthly @\$ >>>> per month	2800	Bill Co:
Monthly @\$)SOO per month SUB-TOTAL	2800	Credit Card No: 10 process (LAM) after any process appears a process against a process and the control of the c
Deposit		Exp. Date
TOTAL CHARGE	3700	Type: and are also as the second of the person of sure of the second with the second of the second o
	,	XCESS CLAUSE CLAUSE CONTROL SENSE OF SE
Hirer is responsible for the first S\$ 300 (I.e.EXPRESS RENTAL'S) vehicle and also fir party's vehicle for each and every accident / da	st 65 amage.	excess for collision / damage / fire & theft for the first party excess for collision / damage / fire & theft to third
CHECK OUT	ont an expect of 44	CHECK IN WE also served and relate to the spring by these because of a review of an extra contract of the spring of the served and the spring of the spring
Date Out 28 119 Time Out 1441	and the state of t	Date In 6 3 19 Time In 1 210

HIRER'S DECLARATION

I have read the terms & conditions on overleaf of this rental agreement. I acknowledge receipt of vehicle in good condition plus accessories and if I opt to pay by credit/charge card, my signature here is to deemed to have been made on the application credit card charge slip. I am aware that Express Rental may have to take necessary steps by contact my employer in order to qualify me as a hirer.

4 Chy Chya

Hire's Signature

EXPRESS RENTAL



OFFICIAL RECEIPT

EXPRESS RENTAL OFFICIAL REBIX 3022A Ubi Road 1 #01-45 Singapore 408716 Tel: 6841 8055 (2 Lines) Fax: 6741 7208

5522 No:

Date:

Seven

Koh Cheng Chy

Thousand Three

the sum of Dollars.

Received from_

Mug

7362 安

being payment of.

SKS JF871

Cash/Cheque No.

All receipts subject to the clearance of cheque.

EXPRESS RENTAL

Authorised Signature



GENERAL INSURANCE ASSOCIATION OF SINGAPORE **RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No:

GR-19-015769

Date of Request:

28/01/2019

Your Ref No:

Online Purchase

Progressive Car Care Pte Ltd Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Dear Sir/Madam,

Enquiry Date

28/01/2019

Enquiry By

Lily Lim

TP Vehicle No.

GBE2324C

Accident Date

28/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBE2324C	EQ Insurance Company Ltd	06/10/2018-05/10/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE **RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-19-015769

Date of Request:

28/01/2019

Your Ref No:

Online Purchase

Progressive Car Care Pte Ltd Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Dear Sir/Madam,

Enquiry Date

28/01/2019

Enquiry By

Lily Lim

TP Vehicle No.

GBE2324C

Accident Date

28/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

PO

PAS AUTO PTE LTD

Blk 32, Sin Ming Drive #01-325 Singapore 575706 Tel : 6452 3938 (6 Lines) Fax : 6452 7936

Date: 01/02/2019

PRORESSIVE CAR CARE PTE LTD

Dear Sir/Madam,

Re: Spare Parts From (Over Air Order) VIN.WDD2462422J230232 SKM5207P

Part No 246 740 0101 REAR BOOT

246 740 2500 REAR BOOT GLASS 246 740 1293 REAR OUTER HANDEL 246 740 0070 TIAL GATE INNER TRIM 246 490 0027 EXHAUST CHORME PIPE RH 246 860 0000/0100 REAR SAFETY BELT LH/RH 246 860 2969/3069 REAR SELT BUCKLE LH/RH

Refer to the above mentioned, we regret to informed you that the parts you've order from us currently do not have the stock right now. Hence, we will have to order from oversea.

Therefore, estimated arrival of parts from the agent will be in 14~21 Days or more.

After purchase order we will no accept any reason to cancel order.

We apologize for the inconvenience caused.

Yours faithfully,

Pas Auto Pte Ltd

Import & Export Stockist Mercedes-Benz Spare Parts & Accessories





PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,

REMARK: SKM5207P WENDY

SINGAPORE 408716

REPRINT

#01-45/46

PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706) TEL NO: 64523938 (6 LINES) FAX NO: 64527936

A/C DEPT: 64590882

Business Reg & GST NO: 201512120M



TAX INVOICE

INV NO: 1214816

DATE : 01/02/2019

A/C NO : 006949

TERM : 30

PAGE : 1 OF 1

ISSUE : TTH

DELIVER TO:

Printed on 12/02/2019 12:00:34

	20						
ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
Ç1.	246 880 3340 9999	RR BUMPER	3W2D18	1	PCS	730.00	730.00/-
2	003 990 9497MB	REAR BUMPER CLIP	SS2A30	10	PCS	2.80	28.00/-
3	246 885 0921MB	REAR BUMPER LOWER CHROME LH	SS2Q04	1	PCS	73.00	73.00/-
4	246 885 1021MB	REAR BUMPER LOWER CHROME RI	SS2Q04	1	PCS	73.00	73.00
5	000 905 0242MB	REAR BUMPER SENSOR	SS2B17	2	PCS	140.00	280.00/-
6	246 885 1022 9999	RR BUMPER TOWING COVER	SS2C07	1	PC	36.00	36.00/-
7	246 885 0011MB	RR BUMPER TOP CHROME	SS2Q04	1	PC	82.00	82.00
8	246 740 0101MB	REAR BOOT	DC	1	PCS	1,100.0	1,100.00
9	246 740 2500MB	REAR BOOT GLASS	DC	1	PC	1,150.0	1,150.00 /-
10	246 817 0016MB	BOOT MER LOGO	SS2D06	4 1	PCS	27.00	27.00~
11	246 817 0915MB	MODEL PLATE B180	SS2D05	1	PC	45.00	45.00
12	246 740 1293MB	REAR BOOT OUTER CHROME	DC	1	PC	138.00	138.00 /_
13	246 906 6400MB	REAR BOOT REFLECTOR RH	SS3D07 **	1	PC	220.00	220.00 /-
14	246 490 0027MB	EXHAUST CHORME PIPE RH	DC	_1	PC	155.00	155.00 /-
15	246 860 0000 9C94	REAR SAFETY BELT LEFT	DC	1	PCS	220.00	220.00/-
16	246 860 0100 9C94	REAR SAFETY BELT RH	DC	1	PCS	220.00	220.00/-
17	246 740 0701 9H68	TAIL GATE INN TRIM	DC	1	PC	87.00	87.00/-

RECEIVED BY

PICKED BY: 8839

SUB-TOTAL : S\$

TOTAL

4,664.00

ADD 7% GST : S\$

326.48 : S\$ 4,990.48

Goods sold are not returnable except Repairs/Serviced at authorized workshop.



BLK 32 SIN MING DRIVE #01-325 S(575706) TEL NO: 64523938 (6 LINES) FAX NO: 64527936

DELIVER TO:

A/C DEPT: 64590882

Business Reg & GST NO: 201512120M



TAX INVOICE

INV NO : 1215155

OCT

DATE : 11/02/2019 A/C NO : 006949

TERM : 30

: 1 OF 1 PAGE

ISSUE : TTH

REPRINT

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,

#01-45/46

SINGAPORE 408716

REMARK: SKM5207P WENDY

Printed on 12/02/2019 4:49:44

-	ITEM	I PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE TO	TAL AMT.
	1 8	246 610 1100MB	REAR REINDORCEMENT	3W2F03	1	PCS	240.00 ~	240.00/-
/	2	246 885 3425MB	LOWER GARNISH	DC	1	PC	65.00	65.00/-
	3	246 740 1301MB	REAR BOOT TOP LOCK	DC	1	PC	114.00_	. 114.00

PICKED BY: MIC

SUB-TOTAL

: S\$ 419.00

ADD 7% GST : S\$

TOTAL

: S\$

448.33

29.33

Goods sold are not returnable except Repairs/Serviced at authorized workshop.

5083



BLK 32 SIN MING DRIVE #01-325 S(575706) TEL NO: 64523938 (6 LINES) FAX NO: 64527936

A/C DEPT: 64590882

Business Reg & GST NO: 201512120M



TAX INVOICE

REPRINT

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,

#01-45/46

SINGAPORE 408716

REMARK: SKM5207P WENDY 9

DELIVER TO:

199B

INV NO : 1215879

DATE : 14/02/2019

A/C NO : 006949

TERM : 30

: 1 OF 1 PAGE

ISSUE : TTH

Printed on 15/02/2019 5:21:33

ITE	M PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE TOT	TAL AMT.
1	246 826 0391MB	REAR BOOT LAMP SPONGE LH	DC	1	PC	15.00ζ	15.00/-
2	246 826 0491MB	REAR BOOT LAMP SPONGE LH	DC	1	PC	15.00 ς	15.00/-
3	246 740 0901 9H6	8 PANELING CLOSING HANDLE	DC	1	PCS	44.00	44.00/-

RECEIVED BY

PICKED BY: 88839

SUB-TOTAL : S\$

ADD 7% GST : S\$

74.00 5.18

TOTAL

: S\$

79.18

Goods sold are not returnable except Repairs/Serviced at authorized workshop.



BLK 32 SIN MING DRIVE #01-325 S(575706) TEL NO: 64523938 (6 LINES) FAX NO: 64527936

A/C DEPT: 64590882

Business Reg & GST NO: 201512120M



D218455

TAX INVOICE

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,

#01-45/46

REPRINT

SINGAPORE 408716

REMARK: SKM5207P WEDNY

DELIVER TO:

TP 5383

INV NO : 1218455

DATE : 01/03/2019 A/C NO : 006949

TERM: 30

PAGE : 1 OF 1

ISSUE : TTH

Printed on 01/03/2019 5:24:30

ITE	M PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	246 860 2969 9051	SEA BELT BUCKLE LH	DC	1	PC	135.00	135.00/~
2	246 860 3069 9051	SEA BELT BUCKLE RH	DC	1	PC	135.00	135.00 /-

RECEIVED BY

PICKED BY: 5477

SUB-TOTAL

: S\$ 270.00

ADD 7% GST : S\$

18.90

TOTAL

: S\$

288.90

Goods sold are not returnable except Repairs/Serviced at authorized workshop.



BLK 32 SIN MING DRIVE #01-325 S(575706) TEL NO: 64523938 (6 LINES) FAX NO: 64527936

A/C DEPT: 64590882

Business Reg & GST NO: 201512120M



TAX INVOICE

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,

#01-45/46

SINGAPORE 408716

REMARK: SKM5207P WENDY

DELIVER TO:

INV NO: 1219005

DATE : 05/03/2019 A/C NO : 006949

TERM : 30

: 1 OF 1 PAGE

ISSUE : TTH

Printed on 05/03/2019 2:59:43

ITEN	A PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	246 860 2685	9C94 FRT SAFETY BELT RH	DC	1	PC	335.00/	335.00/~

SUB-TOTAL : S\$ PICKED BY: 5477

ADD 7% GST : S\$

TOTAL : S\$ 358.45

335.00

23.45

Goods old are not returnable except Repairs/Serviced at authorized workshop.

Hsiao Tong (LKKAuto)

Tisiao Tolig (Ekitotato)	
From: Sent: To: Cc: Subject:	Janice Goh <janice.goh@eqinsurance.com.sg> Wednesday, 18 March 2020 9:44 AM Hsiao Tong (LKKAuto) Admin A RE: DM19HO00295/JT: <seek mandate="">EQ ref: TBA *LKK ref: CC4/EQI19002132/R1pb3q2 [ACCIDENT INVOLVING GBE2324C(EQ-OI) & SKM5207P(TP) ON 28/01/2019]</seek></janice.goh@eqinsurance.com.sg>
Hi Hsiao Tong	
Please proceed to offer upto \$13	3,493.49.
Thank you.	
Janice Goh Executive Claims	
×	
EQ Insurance Company Limited 5 Maxwell Road #17-00 Tower Block MN did 65 6496 9032 tel 65 6223 9433 ext 0 www.eqinsurance.com.sg	032 fax 65 6223 4190
Privileged/Confidential information may be o	contained in this message. If you are not the intended recipient, please notify the sender immediately and delete
From: Hsiao Tong (LKKAuto) [ma Sent: Monday, March 16, 2020 2 To: Janice Goh <janice.goh@eqi Cc: Admin A <admin-a@lkkauto Subject: RE: DM19HO00295/JT: INVOLVING GBE2324C(EQ-OI) & Dear Sirs/Mdm,</admin-a@lkkauto </janice.goh@eqi 	12:14 PM insurance.com.sg>

For LOR, third party rejected our offer at 11days and counter propose 36days due to waiting spare parts.

Attached herewith are the supporting parts order documents as follows:-

- Parts Requisition Order dated 01/02/2019
- 1st batch Factory Parts invoice /DO showing parts received on 01/02/2019
- 2nd batch Factory Parts invoice /DO showing parts received on 11/02/2019
- 3rd batch Factory Parts invoice /DO showing pants received on 14/02/2019
- 4th batch Factory Parts invoice /DO showing parts received on 01/03/2019
- Last batch Factory Parts invoice /DO showing parts received on 05/03/2019

We would like to seek your mandate to revise offer at \$13,493.49(all-in). Summary is a s follows: -

	3 rd party proposed	Revised Amount
1. Cost of Repair (w/GST)	\$10,091.49	\$ 10,091.49
2. Loss of Rental (36days)	\$ 3,700.00	\$ 3,400.00 (34days x \$100.00)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
	\$ 13,793.49	\$ 13,493.49

Kindly let us have your further mandate/instruction.

Thank you.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan < ianet.tan@eqinsurance.com.sg> Sent: Monday, 30 September 2019 8:43 AM To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: DM19HO00295/JT: <Seek Mandate>EQ ref : TBA *LKK ref : CC4/EQI19002132/R1pb3q2 [ACCIDENT

INVOLVING GBE2324C(EQ-OI) & SKM5207P(TP) ON 28/01/2019]

Dear Hsiao Tong

Please proceed to offer up to \$11,193.49.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, September 30, 2019 8:25 AM To: Janet Tan < janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: <Seek Mandate>EQ ref: TBA *LKK ref: CC4/EQI19002132/R1pb3q2 [ACCIDENT INVOLVING GBE2324C(EQ-

OI) & SKM5207P(TP) ON 28/01/2019]

EQ ref: TBA

LKK ref: CC4/EQI19002132/R1pb3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE2324C(EQ-OI) & SKM5207P(TP) ON 28/01/2019

We refer to the above matter.

It is a head-to-rear collision. Liability is down against our insured driver.

We seek your approval to offer Third Party repairer "PROGRESSIVE CAR CARE PTE LTD" at \$ (all-in).

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 16,673.28	\$10,091.49
2. Loss of Rental (36days)	\$ 3,700.00	\$ 1,100.00 (11days x \$100.00)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
	\$ 20,375.28	\$11,193.49

Surveyor recommended 6 days for repair + 2Sunday + 2PH + 1PRS = 11days.

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)