

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD, #17-00
 TOWER BLOCK MND COMPLEX
 SINGAPORE 069110

TEL: 62239433

FAX: 62243903

ATTN: Motor Claim Department

Your Ref No: TP 0119-5383

Claim Type: Third Party

Accident Date: 28/01/2019

TP Veh Reg No: GBE 2324 C

Estimate No: EST1504509

Date: 28 Jan 2019

Policy No: A27849501QMY

Veh Reg No: **SKM5207P**

Make/Model: MERCEDES BEN B180
 (R17 BI)

Chassis No: WDD2462422J230232

Engine No: 27091030323135

Reg. Date: 12/03/2014

Estimate Repair Cost to Vehicle No : SKM5207P

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Special Net				
1 REAR BOOT GLASS V-COOL	400.00	1 PC	400.00 300	
2 REAR NUMBER PLATE WITH CASING	35.00	1 SET	35.00	435.00
Spare Parts				
3 REAR BUMPER DE	730.00	1 PC	730.00	
4 REAR BUMPER SIDE HOLDER - LH ne	8.00	1 PC	8.00	
5 REAR BUMPER SIDE HOLDER - RH ne	8.00	1 PC	8.00	
6 REAR BUMPER CLIPS ne	2.80	10 PC	28.00	
7 REAR BUMPER REINFORCEMENT ?	240.00	1 PC	240.00	
8 REAR BUMPER FOAM - LH, RH, CENTRE ?	57.00	1 PC	57.00	
9 REAR BUMPER LOWER GARNISH DE	65.00	1 PC	65.00	
10 REAR BUMPER LOWER CHROME - LH ne	73.00	1 PC	73.00	
11 REAR BUMPER LOWER CHROME - RH ne	73.00	1 PC	73.00	
12 REAR BUMPER SENSOR ne	140.00	6 PC 2 pcs	840.00	
13 REAR BUMPER SENSOR WIRE ?	50.00	1 PC	50.00	
14 REAR BUMPER TOWING COVER - RH ms	36.00	1 PC	36.00	
15 REAR BUMPER TOP CHROME ne	82.00	1 PC	82.00	
16 REAR BOOT PA	1,100.00	1 PC	1,100.00	
17 REAR BOOT GLASS W/MOULDING Buo	1,150.00	1 PC	1,150.00	
18 REAR BOOT TOP LOCK ?	114.00	1 PC	114.00	
19 REAR BOOT BOTTOM LOCK ?	20.00	1 PC	20.00	
20 REAR BOOT MER LOGO ne	27.00	1 PC	27.00	
21 REAR BOOT B180 WORDING ne	45.00	1 PC	45.00	
22 REAR BOOT OUTER CHROME sur	138.00	1 PC	138.00	
23 REAR BOOT RUBBER ne	93.00	1 PC	93.00	
24 REAR BOOT REFLECTOR - LH ?	220.00	1 PC	220.00	
25 REAR BOOT REFLECTOR - RH cas	220.00	1 PC	220.00	
26 REAR BOOT INNER TRIM - BIG ne	0.00	1 PC	0.00	
27 REAR BOOT INNER TRIM - LH ?	78.00	1 PC	78.00	
28 REAR BOOT INNER TRIM - RH ?	0.00	1 PC	0.00	
29 REAR SPARE PANEL FLOOR PANEL W/TOP INSULATOR ?	450.00	1 PC	450.00	
30 REAR PANEL ?	520.00	1 PC	520.00	
31 REAR PANEL TOP GARNISH ?	45.00	1 PC	45.00	
32 REAR EXHAUST PIPE CHROME - LH X	155.00	1 PC	155.00	
33 REAR EXHAUST PIPE CHROME - RH sur	155.00	1 PC	155.00	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : EQ INSURANCE COMPANY LIMITED
 5 MAXWELL ROAD, #17-00
 TOWER BLOCK MND COMPLEX
 SINGAPORE 069110
 TEL: 62239433 FAX: 62243903
 ATTN: Motor Claim Department

Your Ref No: TP 0119-5383
 Claim Type: Third Party
 Accident Date: 28/01/2019
 TP Veh Reg No: GBE 2324 C

Estimate No: EST1504509
 Date: 28 Jan 2019
 Policy No: A27849501QMY
 Veh Reg No: **SKM5207P**
 Make/Model: MERCEDES BEN B180
 (R17 BI)
 Chassis No: WDD2462422J230232
 Engine No: 27091030323135
 Reg. Date: 12/03/2014

Estimate Repair Cost to Vehicle No : SKM5207P

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
34 TAIL LAMP - LH X	230.00	1 PC	230.00	
35 TAIL LAMP - RH ?	230.00	1 PCS	230.00	
36 REAR SAFETY BELT - LH 425	220.00	1 PC	220.00	
37 REAR SAFETY BELT - RH 425	220.00	1 PCS	220.00	
38 FRONT SAFETY BELT - RH ?	355.00	1 PCS	355.00	
39 FRONT SAFETY BELT BUCKLE W/SENSOR - RH ?	135.00	1 PCS	135.00	
40 REAR SAFETY BELT BUCKLE W/SENSOR - LH 345	135.00	1 PCS	135.00	
41 REAR SAFETY BELT BUCKLE W/SENSOR - RH 345	135.00	1 PCS	135.00	
42 L/R FENDER INNER TOP TRIM cut	110.00	1 PCS	110.00	
43 CONTROL OIL FURL PUMP X	250.00	1 PCS	250.00	
			8,840.00	
	Add 15%		1,326.00	10,166.00

Labour

44 TO KNOCK OUT DENTS ON REAR PANEL, REAR SPARE TYRE FLOOR PANEL, REAR BOOT, CUT/WELD & REPLACE ACCIDENT PARTS	1,200.00	1 JOB	1,200.00	spare tyre - 1000 600
45 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,200.00	1 JOB	1,200.00	600 / 1000?
46 TO CHECK WIRING	50.00	1 JOB	50.00	30
47 TO REMOVE, REFIX END PANEL GARNISH TO FACILITATE REPAIRS	80.00	1 JOB	80.00	60
48 TO REMOVE, REPLACE REAR BUMPER SENSOR	100.00	1 JOB	100.00	80
49 TO REMOVE, REPLACE FRONT HEADREST - LH, RH	300.00	1 JOB	300.00	X
50 TO RESET ECU	200.00	1 JOB	200.00	X
51 TO TUFF-KOTE	120.00	1 JOB	120.00	80
52 TO REMOVE, REPLACE REAR BOOT GLASS	150.00	1 JOB	150.00	120
53 TO REMOVE, REPLACE REAR EXHAUST PIPE	150.00	1 JOB	150.00	100
54 TO REMOVE, REPLACE REAR R/F SAFETY BELTS - LH, RH & BUCKLES	500.00	1 JOB	500.00	400
55 TO REMOVE, REFIT REAR SEAT, GARNISH & RELATED PARTS	300.00	1 JOB	300.00	200
56 TO REPROGRAM PRESAFE FUNCTIONS TROUBLE CODE	600.00	1 JOB	600.00	?

4,950.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD, #17-00
TOWER BLOCK MND COMPLEX
SINGAPORE 069110
TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Your Ref No: TP 0119-5383
Claim Type: Third Party
Accident Date: 28/01/2019
TP Veh Reg No: GBE 2324 C

Estimate No: EST1504509
Date: 28 Jan 2019
Policy No: A27849501QMY
Veh Reg No: **SKM5207P**
Make/Model: MERCEDES BEN B180
(R17 BI)
Chassis No: WDD2462422J230232
Engine No: 27091030323135
Reg. Date: 12/03/2014

Estimate Repair Cost to Vehicle No : SKM5207P

Total	S\$ 15,551.00
Add GST @ 7%	1,088.57
Total Amount payable	S\$ 16,639.57

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND SIX HUNDRED THIRTY NINE AND CENTS FIFTY SEVEN ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ram
Hp 90010068
6 days
9/1
31/01/19
Resurvey be part