

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL 6741 5336 FAX 6741 7208 Email claims@procarcare.com.sg
GST 201006949C RCB NO 201006949C

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD, #17-00
TOWER BLOCK MND COMPLEX
SINGAPORE 069110

TEL: 62239433 FAX: 62243903

ATTN: Motor Claim Department

Estimate No: **EST1504509**

Date: 28 Jan 2019

Policy No: A27849501QMY

Veh Reg No: SKM5207P

Make/Model: MERCEDES BEN B180
(R17 BI)

Chassis No: WDD2462422J230232

Engine No: 27091030323135

Reg. Date: 12/03/2014

Your Ref No: TP 0119-5383

Claim Type: Third Party

Accident Date: 28/01/2019

TP Veh Reg No: GBE 2324 C

Estimate Repair Cost to Vehicle No : SKM5207P

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Special Net				
1 REAR BOOT GLASS V-COOL	400.00	1 PC	400.00	300 -
2 REAR NUMBER PLATE WITH CASING	35.00	1 SET	35.00	35 -
				435.00
Spare Parts				
3 REAR BUMPER DE	730.00	1 PC	730.00	✓
4 REAR BUMPER SIDE HOLDER - LH	8.00	1 PC	8.00	X
5 REAR BUMPER SIDE HOLDER - RH	8.00	1 PC	8.00	X
6 REAR BUMPER CLIPS	2.80	10 PC	28.00	✓
7 REAR BUMPER REINFORCEMENT	240.00	1 PC	240.00	✓
8 REAR BUMPER FOAM - LH, RH, CENTRI	57.00	1 PC	57.00	X
9 REAR BUMPER LOWER GARNISH	65.00	1 PC	65.00	✓
10 REAR BUMPER LOWER CHROME - LH	73.00	1 PC	73.00	✓
11 REAR BUMPER LOWER CHROME - RH	73.00	1 PC	73.00	✓
12 REAR BUMPER SENSOR	140.00	1 PC	140.00	280 -
13 REAR BUMPER SENSOR WIRE	50.00	1 PC	50.00	X
14 REAR BUMPER TOWING COVER - RH	36.00	1 PC	36.00	✓
15 REAR BUMPER TOP CHROME	82.00	1 PC	82.00	✓
16 REAR BOOT	1,100.00	1 PC	1,100.00	✓
17 REAR BOOT GLASS V-MOULDING	1,150.00	1 PC	1,150.00	✓
18 REAR BOOT TOP LOCK	114.00	1 PC	114.00	✓
19 REAR BOOT BOTTOM LOCK	20.00	1 PC	20.00	X
20 REAR BOOT MIER LOGO	27.00	1 PC	27.00	✓
21 REAR BOOT B180 WORDING	45.00	1 PC	45.00	✓
22 REAR BOOT OUTER CHROME	138.00	1 PC	138.00	✓
23 REAR BOOT RUBBER	93.00	1 PC	93.00	X
24 REAR BOOT REFLECTOR - LH	220.00	1 PC	220.00	X
25 REAR BOOT REFLECTOR - RH	220.00	1 PC	220.00	✓
26 REAR BOOT INNER TRIM - BIG	0.00	1 PC	0.00	87 -
27 REAR BOOT INNER TRIM - LH	78.00	1 PC	78.00	X
28 REAR BOOT INNER TRIM - RH	0.00	1 PC	0.00	X
29 REAR SPARE PANEL FLOOR PANEL W/ TOP INSULATOR	450.00	1 PC	450.00	X
30 REAR PANEL	520.00	1 PC	520.00	X
31 REAR PANEL TOP GARNISH	45.00	1 PC	45.00	44 -
32 REAR EXHAUST PIPE CHROME - LH	155.00	1 PC	155.00	X
33 REAR EXHAUST PIPE CHROME - RH	155.00	1 PC	155.00	✓

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST 201006949C RCB NO 201006949C

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD, #17-00
TOWER BLOCK MND COMPLEX
SINGAPORE 069110
TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Estimate No: **EST1504509**
Date: 28 Jan 2019
Policy No: A27849501QMY
Veh Reg No: **SKM5207P**
Make/Model: MERCEDES BEN B180
(R17 BI)
Chassis No: WDD2462422J230232
Engine No: 27091030323135
Reg. Date: 12/03/2014

Your Ref No: TP 0119-5383
Claim Type: Third Party
Accident Date: 28/01/2019
TP Veh Reg No: GBE 2324 C

Estimate Repair Cost to Vehicle No : SKM5207P

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
34 TAIL LAMP - LH <i>X'm</i>	230.00	1 PC	230.00	X
35 TAIL LAMP - RH <i>? X'suc</i>	230.00	1 PCS	230.00	X
36 REAR SAFETY BELT - LH <i>as /</i>	220.00	1 PC	220.00	—
37 REAR SAFETY BELT - RH <i>as /</i>	220.00	1 PCS	220.00	—
38 FRONT SAFETY BELT - RH <i>? belt</i>	355.00	1 PCS	355.00	<i>335</i>
39 FRONT SAFETY BELT BUCKLE W/SENSOR - RH <i>? X'suc</i>	135.00	1 PCS	135.00	X
40 REAR SAFETY BELT BUCKLE W/SENSOR - LH <i>as /</i>	135.00	1 PCS	135.00	—
41 REAR SAFETY BELT BUCKLE W/SENSOR - RH <i>as /</i>	135.00	1 PCS	135.00	—
42 L R FENDER INNER TOP TRIM <i>as X'suc</i>	110.00	1 PCS	110.00	X
43 CONTROL OIL FUEL PUMP <i>X'm</i>	250.00	1 PCS	250.00	X
			8,840.00	
	Add 15%		1,326.00	10,166.00

Labour

44 TO KNOCK OUT DENTS ON REAR PANEL, REAR SPARE TYRE FLOOR PANEL, REAR BOOT, CUL WELD & REPLACE ACCIDENT PARTS	1,200.00	1 JOB	1,200.00	<i>space type - 1000 X</i> <i>600 -</i>
45 TO RE SPRAY PAINT ON ACCIDENT PORTIONS	1,200.00	1 JOB	1,200.00	<i>600 / 1000 X?</i>
46 TO CHECK WIRING	50.00	1 JOB	50.00	<i>30 -</i>
47 TO REMOVE, REFIX END PANEL GARNISH TO FACT HATE REPAIRS	80.00	1 JOB	80.00	<i>60 -</i>
48 TO REMOVE, REPLACE REAR BUMPER SENSOR	100.00	1 JOB	100.00	<i>80 -</i>
49 TO REMOVE, REPLACE FRONT HEADREST - LH, RH	300.00	1 JOB	300.00	<i>X'm -</i>
50 TO RESET ECU	200.00	1 JOB	200.00	<i>80 -</i>
51 TO HUE-KOTE	120.00	1 JOB	120.00	<i>120 -</i>
52 TO REMOVE, REPLACE REAR BOOT GLASS	150.00	1 JOB	150.00	<i>100 -</i>
53 TO REMOVE, REPLACE REAR EXHAUST PIPE	150.00	1 JOB	150.00	<i>400 -</i>
54 TO REMOVE, REPLACE REAR R/T SAFETY BELTS - LH, RH & BUCKLES	500.00	1 JOB	500.00	<i>200 -</i>
55 TO REMOVE, REFIX REAR SEAL GARNISH & RELATED PARTS	300.00	1 JOB	300.00	<i>? X</i>
56 TO REPROGRAM PRESAFE FUNCTIONS TROUBLE CODE	600.00	1 JOB	600.00	
				4,950.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST 201006949C' RCB NO 201006949C'

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD, #17-00
TOWER BLOCK MND COMPLEX
SINGAPORE 069110
TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Your Ref No: TP 0119-5383
Claim Type: Third Party
Accident Date: 28/01/2019
TP Veh Reg No: GBE 2324 C

Estimate No: EST1504509
Date: 28 Jan 2019
Policy No: A27849501QMY
Veh Reg No: SKM5207P
Make/Model: MERCEDES BEN B180
(R17 BI)
Chassis No: WDD2462422J230232
Engine No: 27091030323135
Reg. Date: 12/03/2014

Estimate Repair Cost to Vehicle No : SKM5207P

Total	S\$ 15,551.00
Add GST @ 7%	1,088.57
Total Amount payable	S\$ 16,639.57

TOTAL SINGAPORE DOLLAR SIXTEEN THOUSAND SIX HUNDRED THIRTY NINE AND CENTS FIFTY SEVEN ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LRK to be submitted; hence notify the Repairer of the following:

- To reserve all rights of payment
- To display damaged part(s) during repairs
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No legal implication is allowed

Signature: _____

Ram
Hp 90010068
6 days
9/1
31/01/19
Reby by part

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S: EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD, #17-00
TOWER BLOCK MND COMPLEX
SINGAPORE 069110

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Your Ref No: TP 0119-5383
Claim Type: Third Party
Accident Date: 28/01/2019
TP Veh Reg No: GBE 2324 C

Estimate No: EST1504509
Date: 28 Jan 2019
Policy No: A27849501QMY
Veh Reg No: SKM5207P
Make/Model: MERCEDES BEN B180
(R17 BI)
Chassis No: WDD2462422J230232
Engine No: 27091030323135
Reg. Date: 12/03/2014

Estimate Repair Cost to Vehicle No : SKM5207P

Description	U/Price	Quantity	Cost S\$	Amount S\$
Special Net				
1 REAR BOOT GLASS V-COOL	400.00	1 PC	100.00	300 ✓
2 REAR NUMBER PLATE WITH CASING	35.00	1 SET	35.00	104 ✓
				435.00 325
Spare Parts				
3 REAR BUMPER DE ✓	730.00	1 PC	730.00	✓
4 REAR BUMPER SIDE HOLDER - LH ✓	8.00	1 PC	8.00	✓
5 REAR BUMPER SIDE HOLDER - RH ✓	8.00	1 PC	8.00	✓
6 REAR BUMPER CLIPS ✓	2.80	10 PC	28.00	✓
7 REAR BUMPER REINFORCEMENT ? ✓	240.00	1 PC	240.00	✓
X8 REAR BUMPER FOAM - LH, RH CENTRE ? NNX	57.00	1 PC	57.00	✓
9 REAR BUMPER LOWER GARNISH DE ✓	65.00	1 PC	65.00	✓
10 REAR BUMPER LOWER CHROME - LH ✓	73.00	1 PC	73.00	✓
11 REAR BUMPER LOWER CHROME - RH ✓	73.00	1 PC	73.00	✓
12 REAR BUMPER SENSOR ✓	140.00	6 PC 2 PCS	840.00	280 ✓
X13 REAR BUMPER SENSOR WIRE ? NNX	50.00	1 PC	50.00	✓
14 REAR BUMPER TOWING COVER - RH ✓	36.00	1 PC	36.00	✓
15 REAR BUMPER TOP CHROME ✓	82.00	1 PC	82.00	✓
16 REAR BOOT ✓	1,100.00	1 PC	1,100.00	✓
17 REAR BOOT GLASS W/MOULDING ✓	1,150.00	1 PC	1,150.00	✓
X18 REAR BOOT TOP LOCK ? ✓	114.00	1 PC	114.00	✓
X19 REAR BOOT BOTTOM LOCK ? NNX	20.00	1 PC	20.00	✓
20 REAR BOOT MER LOGO ✓	27.00	1 PC	27.00	✓
21 REAR BOOT B180 WORDING ✓	45.00	1 PC	45.00	✓
22 REAR BOOT OUTER CHROME ✓	138.00	1 PC	138.00	✓
X23 REAR BOOT RUBBER ✓	93.00	1 PC	93.00	✓
24 REAR BOOT REFLECTOR - LH ? NNX	220.00	1 PC	220.00	✓
✓25 REAR BOOT REFLECTOR - RH ✓	220.00	1 PC	220.00	✓
✓26 REAR BOOT INNER TRIM - BIG ✓	0.00 87.00	1 PC	0.00 87.00	✓
X27 REAR BOOT INNER TRIM - LH ? NNX	78.00	1 PC	78.00	✓
X28 REAR BOOT INNER TRIM - RH ? NNX	0.00	1 PC	0.00	✓
X29 REAR SPARE PANEL FLOOR PANEL W/TOP INSULATOR ? NNX	450.00	1 PC	450.00	✓
X30 REAR PANEL ? NNX	520.00	1 PC	520.00	✓
✓31 REAR PANEL TOP GARNISH ? ✓	45.00	1 PC	45.00	44 ✓
32 REAR EXHAUST PIPE CHROME - LH ✓	155.00	1 PC	155.00	✓
33 REAR EXHAUST PIPE CHROME - RH ✓	155.00	1 PC	155.00	✓

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S: EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD, #17-00
TOWER BLOCK MND COMPLEX
SINGAPORE 069110

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

Your Ref No: TP 0119-5383
Claim Type: Third Party
Accident Date: 28/01/2019
TP Veh Reg No: GBE 2324 C

Estimate No: EST1504509
Date: 28 Jan 2019
Policy No: A27849501QMY
Veh Reg No: SKM5207P
Make/Model: MERCEDES BEN B180
(R17 BI)
Chassis No: WDD2462422J230232
Engine No: 27091030323135
Reg. Date: 12/03/2014

Estimate Repair Cost to Vehicle No : SKM5207P

Description	U/Price	Quantity	Cost S\$	Amount S\$
34 TAIL LAMP - LH X	230.00	1 PC	230.00	
✓ 35 TAIL LAMP - RH ? N N X	230.00	1 PCS	230.00	
36 REAR SAFETY BELT - LH act ✓	220.00	1 PC	220.00 ✓	
37 REAR SAFETY BELT - RH act ✓	220.00	1 PCS	220.00 ✓	
✓ 38 FRONT SAFETY BELT - RH ? ✓	355.00	1 PCS	355.00 335	
✓ 39 FRONT SAFETY BELT BUCKLE W/SENSOR - RH ? ✓	135.00	1 PCS	135.00	
40 REAR SAFETY BELT BUCKLE W/SENSOR - LH act ✓	135.00	1 PCS	135.00 ✓	
41 REAR SAFETY BELT BUCKLE W/SENSOR - RH act ✓	135.00	1 PCS	135.00 ✓	
42 L/R FENDER INNER TOP TRIM act ✓	110.00	1 PCS	110.00	
43 CONTROL OIL FURL PUMP X	250.00	1 PCS	250.00	
			8,840.00 5732	
	Add 15%		1,326.00	10,166.00 6591.8
Labour				
44 TO KNOCK OUT DENTS ON REAR PANEL, REAR SPARE TYRE FLOOR PANEL, REAR BOOT, CUT/WELD & REPLACE ACCIDENT PARTS	1,200.00	1 JOB	1,200.00 600 ✓	
45 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,200.00	1 JOB	1,200.00 600 ✓	
46 TO CHECK WIRING	50.00	1 JOB	50.00 30 ✓	
47 TO REMOVE, REFIX END PANEL GARNISH TO FACILITATE REPAIRS	80.00	1 JOB	80.00 60 ✓	
48 TO REMOVE, REPLACE REAR BUMPER SENSOR	100.00	1 JOB	100.00 80 ✓	
49 TO REMOVE, REPLACE FRONT HEADREST - LH, RH	300.00	1 JOB	300.00	
50 TO RESET ECU	200.00	1 JOB	200.00 NEC ✓	
51 TO TUFF-KOTE	120.00	1 JOB	120.00 80 ✓	
52 TO REMOVE, REPLACE REAR BOOT GLASS	150.00	1 JOB	150.00 120 ✓	
53 TO REMOVE, REPLACE REAR EXHAUST PIPE	150.00	1 JOB	150.00 100 ✓	
54 TO REMOVE, REPLACE REAR R/F SAFETY BELTS - LH, RH & BUCKLES	500.00	1 JOB	500.00 400 ✓	
55 TO REMOVE, REFIT REAR SEAT, GARNISH & RELATED PARTS	300.00	1 JOB	300.00 200 ✓	
56 TO REPROGRAM PRESAFE FUNCTIONS TROUBLE CODE	600.00	1 JOB	600.00 470 ✓	
				4,950.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD, #17-00

TOWER BLOCK MND COMPLEX

SINGAPORE 069110

TEL: 62239433

FAX: 62243903

ATTN: Motor Claim Department

Your Ref No: TP 0119-5383

Claim Type: Third Party

Accident Date: 28/01/2019

TP Veh Reg No: GBE 2324 C

Estimate No: EST1504509

Date: 06 Mar 2019

Policy No: A27849501QMY

Veh Reg No: SKM5207P

Make/Model: MERCEDES BEN B180
(R17 BI)

Chassis No: WDD2462422J230232

Engine No: 27091030323135

Reg. Date: 12/03/2014

Estimate Repair Cost to Vehicle No : SKM5207P

Description	U/Price	Quantity	Cost S\$	Amount S\$
Supplementary Parts to Repair				
Spare Parts				
1 REAR BOOT LAMP SPONGE - LH	15.00	1 PC	15.00	} NE c ✓ ✓
2 REAR BOOT LAMP SPONGE - RH	15.00	1 PC	15.00	
			30.00	
	Add 15%		4.50	34.50
Total				S\$ 34.50
GST Amount				S\$ 2.42
Total Amount payable				S\$ 36.92

6/3/19
6/20/19

97361577

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

SUPP 34.50

PARTS. 6591.80

SN 335.00

LAB. 2470.00

9431.30



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D215879

REPRINT

TAX INVOICE

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,

#01-45/46

SINGAPORE 408716

REMARK : SKM5207P WENDY

DELIVER TO :

TP 5383

INV NO : I215879

DATE : 14/02/2019

A/C NO : 006949

TERM : 30

PAGE : 1 OF 1

ISSUE : TTH

Printed on 15/02/2019 5:21:33

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	246 826 0391MB	REAR BOOT LAMP SPONGE LH	DC	1	PC	15.00	15.00/-
2	246 826 0491MB	REAR BOOT LAMP SPONGE LH	DC	1	PC	15.00	15.00/-
3	246 740 0901 9H68	PANELING CLOSING HANDLE	DC	1	PCS	44.00	44.00/-

RECEIVED BY

PICKED BY: 88839

SUB-TOTAL : S\$ 74.00

ADD 7% GST : S\$ 5.18

TOTAL : S\$ 79.18

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
 TEL NO : 64523938 (6 LINES) FAX NO : 64527936
 A/C DEPT : 64590882
 Business Reg & GST NO : 201512120M



D214816

REPRINT

TAX INVOICE

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,

#01-45/46

SINGAPORE 408716

REMARK : SKM5207P WENDY

DELIVER TO :

TP 9383

INV NO : I214816

DATE : 01/02/2019

A/C NO : 006949

TERM : 30

PAGE : 1 OF 1

ISSUE : TTH

Printed on 12/02/2019 12:00:34

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	246 880 3340 9999	RR BUMPER	3W2D18	1	PCS	730.00	730.00/-
2	003 990 9497MB	REAR BUMPER CLIP	SS2A30	10	PCS	2.80	28.00/-
3	246 885 0921MB	REAR BUMPER LOWER CHROME LH	SS2Q04	1	PCS	73.00	73.00/-
4	246 885 1021MB	REAR BUMPER LOWER CHROME RH	SS2Q04	1	PCS	73.00	73.00/-
5	000 905 0242MB	REAR BUMPER SENSOR	SS2B17	2	PCS	140.00	280.00/-
6	246 885 1022 9999	RR BUMPER TOWING COVER	SS2C07	1	PC	36.00	36.00/-
7	246 885 0011MB	RR BUMPER TOP CHROME	SS2Q04	1	PC	82.00	82.00/-
8	246 740 0101MB	REAR BOOT	DC	1	PCS	1,100.0	1,100.00/-
9	246 740 2500MB	REAR BOOT GLASS	DC	1	PC	1,150.0	1,150.00/-
10	246 817 0016MB	BOOT MER LOGO	SS2D06	1	PCS	27.00	27.00/-
11	246 817 0915MB	MODEL PLATE B180	SS2D05	1	PC	45.00	45.00/-
12	246 740 1293MB	REAR BOOT OUTER CHROME	DC	1	PC	138.00	138.00/-
13	246 906 6400MB	REAR BOOT REFLECTOR RH	SS3D07	1	PC	220.00	220.00/-
14	246 490 0027MB	EXHAUST CHORME PIPE RH	DC	1	PC	155.00	155.00/-
15	246 860 0000 9C94	REAR SAFETY BELT LEFT	DC	1	PCS	220.00	220.00/-
16	246 860 0100 9C94	REAR SAFETY BELT RH	DC	1	PCS	220.00	220.00/-
17	246 740 0701 9H68	TAIL GATE INN TRIM	DC	1	PC	87.00	87.00/-

RECEIVED BY

PICKED BY: 8839

SUB-TOTAL : S\$ 4,664.00

ADD 7% GST : S\$ 326.48

TOTAL : S\$ 4,990.48

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D215155

TAX INVOICE

REPRINT

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,

#01-45/46

SINGAPORE 408716

REMARK : SKM5207P WENDY

DELIVER TO :

tp 5383

INV NO : I215155

DATE : 11/02/2019

A/C NO : 006949

TERM : 30

PAGE : 1 OF 1

ISSUE : TTH

Printed on 12/02/2019 4:49:44

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	246 610 1100MB	REAR REINDORCEMENT	3W2F03	1	PCS	240.00	240.00
2	246 885 3425MB	LOWER GARNISH	DC	1	PC	65.00	65.00
3	246 740 1301MB	REAR BOOT TOP LOCK	DC	1	PC	114.00	114.00

RECEIVED BY

PICKED BY: MIC

SUB-TOTAL : S\$ 419.00

ADD 7% GST : S\$ 29.33

TOTAL : S\$ 448.33

Goods sold are not returnable except Repairs/Service at authorized workshop.

5083



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D219005

TAX INVOICE

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,

#01-45/46

SINGAPORE 408716

REMARK : SKM5207P WENDY

DELIVER TO :

TP 5383

INV NO : I219005

DATE : 05/03/2019

A/C NO : 006949

TERM : 30

PAGE : 1 OF 1

ISSUE : TTH

Printed on 05/03/2019 2:59:43

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	246 860 2685 9C94	FRT SAFETY BELT RH	DC	1	PC	335.00	335.00

RECEIVED BY

PICKED BY: 5477

SUB-TOTAL : S\$ 335.00

ADD 7% GST : S\$ 23.45


TOTAL : S\$ 358.45

Goods sold are not returnable except Repairs/Service at authorized workshop.



PAS AUTO PTE LTD

BLK 32 SIN MING DRIVE #01-325 S(575706)
TEL NO : 64523938 (6 LINES) FAX NO : 64527936
A/C DEPT : 64590882
Business Reg & GST NO : 201512120M



D218455

REPRINT

TAX INVOICE

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1,
#01-45/46

SINGAPORE 408716

REMARK : SKM5207P WEDNY

DELIVER TO :

TP 5383

INV NO : I218455

DATE : 01/03/2019

A/C NO : 006949

TERM : 30

PAGE : 1 OF 1

ISSUE : TTH

Printed on 01/03/2019 5:24:30

ITEM	PART NO	DESCRIPTION	LOCATION	QTY	UNIT	PRICE	TOTAL AMT.
1	246 860 2969 9051	SEA BELT BUCKLE LH	DC	1	PC	135.00	135.00 ✓
2	246 860 3069 9051	SEA BELT BUCKLE RH	DC	1	PC	135.00	135.00 ✓

RECEIVED BY

PICKED BY: 5477

SUB-TOTAL : S\$ 270.00

ADD 7% GST : S\$ 18.90

TOTAL : S\$ 288.90

Goods sold are not returnable except Repairs/Service at authorized workshop.