



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLB4230Z
Date of Accident : 30 January 2019

Messrs Eng Soon Auto Pte Ltd

Date : 14 February 2019

Estimate To Repair SLT800K - B.M.W 530I SE AUTO
Chassis No : WBAJA520X0G885470

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper <i>deep cut</i>	\$ 1,503.70 ✓
02	10 ps	rear bumper clip @ \$3.90 <i>rel</i>	\$ 39.00 ✓
03	1 pc	rear bumper side retainer RH <i>11x</i>	\$ 98.50 X
04	1 pc	rear door RH <i>10/12/19</i>	\$ 1,863.50 ✓
05	1 pc	rear door outer moulding RH <i>11x</i>	\$ 124.40 X
Less 10 %			\$ 3,629.10
			\$ 362.91
			\$ 3,266.19
<u>SPECIAL NETT ITEMS</u>			
06	1 pc	rear tyre <i>suc</i>	\$ 450.00 X
			\$ 450.00
<u>LABOUR & MISC. CHARGES</u>			
01		To transfer of tyre, rim and on wheel balancing.	\$ -80.00 X
02		To check steering geometry and computer wheel alignment.	\$ -80.00 X
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00 A00 400
04		Putty and spray painting of rear bumper, rear fender RH, rear door RH and front door RH.	\$ 1,200.00 800 800
			\$ 2,260.00
Total			\$ 5,976.19
<i>parts - \$3406.20</i> <i>- 10%</i> <i>\$ 3065.58</i> <i>\$ 1200.00</i> <i>\$ 4265.58</i>			<i>P-33089</i> <i>102</i> <i>2978.01</i> <i>4178.01</i> <i>3342.</i>

LKK Auto Centre, Singapore, to notify the Repaired of the following:

- To insure by the insurer's policy covering
- To display damaged vehicle during survey
- Parts and services are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- The repairer must obtain the approval of the insurer
- Supplementary item(s) must be approved by the insurer
- is subject to final approval from insurer's company

Acknowledged by Repaired
Signature:
Date: