

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291 Email: support@hkllimmotorsport.com.sg

Website: www.hkllimmotorsport.com.sg

FN6130Z

1 LAMPSTAY	\$150.00 bt
2 METER ASSY	\$950.00 ?
3 FRONT FORK ASSY LH / RH	\$1,800.0066
4 FRONT FORK UNDER BRACKET	\$450.00 66
5 STEERING CONE BEARING	\$120.00 14
6 FRONT FORK TOP CRAM	\$180.00 3t
7 BODY FRAME ALIGNMENT	\$650.00 380
8 FRONT FENDER	\$220.00
9 FRONT WHEEL RIM	\$680.00 7
10 FRONT WHEEL SHALF	\$120.00 ?
11 FRONT WHEEL BEARING 2PCS	\$50.00?
12 FRONT WHEEL BEARING OIL SEAL 2PCS	\$30.00 7
13 FRONT BRAKE DISC LH / RH	\$1,200.00 7
14 HEAD COWLING + SPRAY	\$180.00 au
15 FRONT SIGNALS LH / RH	\$160.00 x
16 IU UNIT	\$170.00 ×
17 IU UNIT BRACKET	\$30.00 ×
18 HANDLE BAR	\$185.0066
19 HANDLE BAR GRIP	\$20.00 ₭
20 HANDLE BAR BALANCER (MOTOVATION)	\$120.00 cit
21 BRAKE LEVER	\$45.00 66-
22 HEADLIGHT ASSY	\$350.00 21
23 HEADLIGHT BRACKET LH / RH	\$160.00 ?
24 BRAKE PEDAL	\$120.00Ry
25 REAR FOOT REST RH	\$70.00 brow
26 REAR FOOT REST BRACKET RH	\$250.00 RY
27 EXHAUST HEADER + GASKET	\$850.00 4
28 EXHAUST MUFFLER (YOSHIMURA TITANIUM BLUE)	\$1,200.00 dd
29 EXHAUST INSPECTION	\$82.00 ?
30 FRAME GUARD	\$150.00 dd-
31 TOP BOX	\$550.00 Cra
32 TOP BOX BRACKET	\$160.00 ?
33 RADIATOR	\$720.00 66-
34 RADIATOR GUARD	\$120.00 %
35 COOLANT WATER	\$45.00 16/
36 SIDE PANEL LH/RH	\$120.00 <
37 TOWING	\$40.00 ✓
38 LABOUR	\$750.00 450.

1/2/196415/2 Composition of repair serve (Weardo var 6 days.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: