

CIC CASE OWNER:

RA 1004, ASM 1900 737, RI fab

LCK:

B-1:

96834

Surveyor:

MRB

DOC:

ASSIGNMENT

15/2/19

Date/Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLL8300B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Stuttgart.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

12/2
cpr

SLL8300B - X; SMF 2338C - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 14/2/19

After call ltr to OI: 14/2/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Rasm.

Repair Cost:

RIP

SS 2901.51

(4 days)

Reduction:

4494.21 % 79

Email

Call

FINAL SETTLEMENT

Date/Time:

24/8/19/10am

Confirm with:

Jen

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

Nil

If NO or B 28, Ass. Lia:

Repair Cost:

(WIGST)

SS 4181.04

Loss of Rental (LOR):

SS 573.60

(3 days)

x \$171.20

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/Independent)

Legal Cost

SS

-

Total:

SS

4694.64

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1

SS

4694.64

Name 1:

Stuttgart Auto Pte Ltd

Payee 2 (Strike if N.A.)

SS

Name 2:

Payee 3 (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

\$350/-

Faru

REF: ASM(CAXA)

23714(F)

31232

ASSIGNMENT

Date: 15/2/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

For Insured Vehicle No

SLL 8300B
Trans Eurokars
27A Tanjung Penjun

at Workshop no

of

Insured

Policy No

Claim No

Sum Insured

Excess


(Client's Record)

Make of Veh

4pm @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value

378K

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repair

4

days

Res: Yes or No

Lump Sum

100%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date

Person Contacted

Veh No

SLL 8300 B

Vt Page

2016 RMA

Type: ☒ Car / ☐ Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make

Porsche Cayman GT4 cc 3800

Color

Black

AG

Insured / Std / NI / NA

Sp Reading

74459

IRadio

Insured / Std / NI / NA

Eng No

C No

WP0ZZ2982GK189608

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / STD / STD A/Rim or

Tyre Size

F:

295/302R 20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A

26/01/19

D.O.I

15/02/19

Survey held at

Trans Eurokars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P 43907.51

(Red = \$14946.21 / 79%)

Date/Time, File Pass to?

☐

Prefi. Report

By

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Techn. Ins (\$

☐

Weekend (\$

Report Format:

Lump Sum / LB (\$)

Photo

Other

Other

Other



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

PORSCHE

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN.: MOTOR CLAIM DEPT. FAX: 68804838 / 68804739		NAME: Mr Leon Liu Zun ADDRESS: 2 Phoenix Garden Singapore 668270 TEL:		WIP: 42362 EXCESS: DATE: 01.02.2019	
VEH NO:	SLL8300B	DATE IN:		CONTACT PERSON:	EVA 63310683
CHASSIS NO:	WP0ZZZ98ZGK189608	MILEAGE:		TYPE OF CLAIM:	TP
MODEL:	Cayman GT4	DATE REG.:	01.08.2016	POLICY NO.:	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	REAR BUMPER <i>repar</i>	1		\$ 2,109.10
2	BUMPER PROTECTIVE FILM LH <i>re</i>	1		\$ 16.29 18.10
3	BUMPER PROTECTIVE FILM RH <i>re</i>	1		\$ 16.29 18.10
4	BUMPER LOWER RETAINING FRAME <i>x su</i>	1		\$ 459.40
5	U-CLAMP <i>x su</i>	10		\$ 12.00
6	BUMPER LOWER GARNISH LH <i>x su</i>	1		\$ 151.70
7	BUMPER LOWER GARNISH RH <i>x su</i>	1		\$ 151.70
8	TAIL PIPE GARNISH <i>x su</i>	1		\$ 162.70
9	LOGO "PORSCHE" BLACK <i>re</i>	1		\$ 198.92 198.80
10	LOGO "GT4" BLACK <i>re</i>	1		\$ 116.01 128.90
11	MAIN EXHAUST MUFFLER RH <i>? x su</i>	1		\$ 3,521.80
12	MAIN EXHAUST MUFFLER LH <i>? x su</i>	1		\$ 3,521.80
13	TAIL PIPE <i>? x su</i>	1		\$ 1,584.10
14	EXHAUST MUFFLER CLAMP <i>? x su</i>	1		\$ 92.60
15	HEXAGON NUT (WF57) <i>? x su</i>	4		\$ 21.20
16	EXHAUST GASKET <i>? x su</i>	2		\$ 18.80
TOTAL PARTS				\$ 12,170.80
LESS 10%				\$ 1,217.08
TOTAL PARTS COST				\$ 10,953.72

Labour Description			
1	TO REPLACE REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560	\$ 3,120.00
2	TO RESPRAY REAR BUMPER.	1300	\$ 1,560.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY. <i>x su</i>	NETT	\$? 1,560.00
4	TO INSTALL THE REAR BUMPER STICKER. (2 WORKING DAYS) AS PER QUOTATION. <i>invoice ? re</i>	NETT <i>x su</i>	\$ 800.00
5	TO SUPPLY 1 PC REAR NUMBER PLATE. <i>x su</i>	NETT	\$ 70.00

6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 150 200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 480 600.00
8	SUNDRIES.	NETT	\$ 20 50.00

TOTAL LABOUR	\$ -	\$ 7,900.00
TOTAL PARTS	\$ -	\$ 10,953.72
TOTAL	\$ -	\$ 18,853.72
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

\$3,580.00

parts \$ 327.51
labour \$ 3,580.00
p/p: \$ 3,907.51

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Rasul
Hp 90010068
(4) 5 days
15/02/19 @ 1630
Resurvey after repair
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



PORSCHE

AXA INSURANCE PTE LTD		NAME :	Mr Leon Liu Zun	WIP :	42362
8 SHENTON WAY		ADDRESS :	2 Phoenix Garden	EXCESS :	
#24-01 AXA TOWER			Singapore 668270	DATE :	01.02.2019
SINGAPORE 068811		TEL :			
ATTN. :	MOTOR CLAIM DEPT				
FAX :	68804838 / 68804739				
VEH NO :	SLL8300B	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ98ZGK189608	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Cayman GT4	DATE REG.:	01.08.2016	POLICY NO. :	

NATURE OF WORKS

S/NO	<u>Parts Description</u>		QTY		REVISED	PRICES
1	REAR BUMPER		1	P981-505-991-80-	\$ -	\$ 2,109.10
2	BUMPER PROTECTIVE FILM LH		1	P981-505-691-00-	\$ 18.10	\$ 18.10
3	BUMPER PROTECTIVE FILM RH		1	P981-505-692-00-	\$ 18.10	\$ 18.10
4	BUMPER LOWER RETAINING FRAME		1	P981-505-853-80-1E0	\$ -	\$ 459.40
5	U-CLAMP		10	P999-507-696-00-	\$ -	\$ 12.00
6	BUMPER LOWER GARNISH LH		1	P981-505-511-80-1E0	\$ -	\$ 151.70
7	BUMPER LOWER GARNISH RH		1	P981-505-512-80-1E0	\$ -	\$ 151.70
8	TAIL PIPE GARNISH		1	P981-505-811-80-1E0	\$ -	\$ 162.70
9	LOGO "PORSCHE" BLACK		1	P991-559-235-90-	\$ 198.80	\$ 198.80
10	LOGO "GT4" BLACK		1	P981-559-251-80-	\$ 128.90	\$ 128.90
11	MAIN EXHAUST MUFFLER RH		1	P981-111-922-06-	\$ -	\$ 3,521.80
12	MAIN EXHAUST MUFFLER LH		1	P981-111-921-06-	\$ -	\$ 3,521.80
13	TAIL PIPE		1	P981-111-361-61-	\$ -	\$ 1,584.10
14	EXHAUST MUFFLER CLAMP		1	P981-111-280-00-	\$ -	\$ 92.60
15	HEXAGON NUT (WF57)		4	P900-910-003-03-	\$ -	\$ 21.20
16	EXHAUST GASKET		2	P982-251-263- -	\$ -	\$ 18.80
TOTAL PARTS					\$ 363.90	\$ 12,170.80
LESS 10%					\$ 36.39	\$ 1,217.08
TOTAL PARTS COST					\$ 327.51	\$ 10,953.72

Labour Description

1	TO REPLACE REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,560.00	\$ 3,120.00
2	TO RESPRAY REAR BUMPER.	\$ 1,300.00	\$ 1,500.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	\$ -	\$ 1,560.00
4	TO INSTALL THE REAR BUMPER STICKER. (2 WORKING DAYS) AS PER QUOTATION	\$ -	\$ 800.00
5	TO SUPPLY 1 PC REAR NUMBER PLATE.	\$ 70.00	\$ 70.00

6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 480.00	\$ 600.00
8	SUNDRIES.	\$ 20.00	\$ 50.00
TOTAL LABOUR		\$ 3,580.00	\$ 7,900.00
TOTAL PARTS		\$ 327.51	\$ 10,953.72
TOTAL		\$ 3,907.51	\$ 18,853.72
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ 3,907.51	
GST 7%		\$ 273.53	\$ -
GRAND TOTAL		\$ 4,181.04	\$ -

NUMBER OF DAYS: 4 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : MOTOR CLAIM DEPT FAX : 68804838 / 68804739		NAME : Mr Leon Liu Zun ADDRESS : 2 Phoenix Garden Singapore 668270 TEL :		WIP : 42362 EXCESS : DATE: 01.02.2019	
VEH NO :	SLL8300B	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ98ZGK189608	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Cayman GT4	DATE REG.:	01.08.2016	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	REAR BUMPER <i>repar</i>	1	P981-505-991-80-		\$ 2,109.10
2	BUMPER PROTECTIVE FILM LH <i>repar</i>	1	P981-505-691-00-		\$ 18.10
3	BUMPER PROTECTIVE FILM RH <i>repar</i>	1	P981-505-692-00-		\$ 18.10
4	BUMPER LOWER RETAINING FRAME <i>X</i>	1	P981-505-853-80-1E0		\$ 459.40
5	U-CLAMP <i>X</i>	10	P999-507-696-00-		\$ 12.00
6	BUMPER LOWER GARNISH LH <i>X</i>	1	P981-505-511-80-1E0		\$ 151.70
7	BUMPER LOWER GARNISH RH <i>X</i>	1	P981-505-512-80-1E0		\$ 151.70
8	TAIL PIPE GARNISH <i>X</i>	1	P981-505-811-80-1E0		\$ 162.70
9	LOGO "PORSCHE" BLACK <i>repar</i>	1	P991-559-235-90-		\$ 198.80
10	LOGO "GT4" BLACK <i>repar</i>	1	P981-559-251-80-		\$ 128.90
11	MAIN EXHAUST MUFFLER RH <i>?</i>	1	P981-111-922-06-		\$ 3,521.80
12	MAIN EXHAUST MUFFLER LH <i>?</i>	1	P981-111-921-06-		\$ 3,521.80
13	TAIL PIPE <i>?</i>	1	P981-111-361-61-		\$ 1,584.10
14	EXHAUST MUFFLER CLAMP <i>?</i>	1	P981-111-280-00-		\$ 92.60
15	HEXAGON NUT (WF57) <i>?</i>	4	P900-910-003-03-		\$ 21.20
16	EXHAUST GASKET <i>?</i>	2	P982-251-263- -		\$ 18.80
TOTAL PARTS					\$ 12,170.80
LESS 10%					\$ 1,217.08
TOTAL PARTS COST					\$ 10,953.72
Labour Description					
1	TO REPLACE REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			1560	\$ 3,120.00
2	TO RESPRAY REAR BUMPER.			1300	\$ 1,560.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.			NETT	\$? 1,560.00
4	TO INSTALL THE REAR BUMPER STICKER. (2 WORKING DAYS) AS PER QUOTATION <i>invoice ? re</i>			NETT	\$ 800.00
5	TO SUPPLY 1 PC REAR NUMBER PLATE. <i>X</i>			NETT	\$ 70.00

6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 150 200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 480 600.00
8	SUNDRIES.	NETT	\$ 20 50.00
		TOTAL LABOUR	\$ - \$ 7,900.00
		TOTAL PARTS	\$ - \$ 10,953.72
		TOTAL	\$ - \$ 18,853.72
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ - \$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Rasul
Hp 90010068
4-5 days
15/02/19 @ 1630
Resumy after repair



PORSCHE

DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned
Repairers my / our vehicle No: SH 8300 B which has been
repaired to my satisfaction and I/we admit that the payment for such repairs
by **Stuttgart Auto Pte Ltd** is in full and final discharge of my claim under
policy number: _____ in respect of damage
caused to the said vehicle as a result of an accident that occurred on
26/01/2019 at machap PP Johore.

Danice Syu 

Witnessed by Repairers

29/03/2019

Date:

Leni

Signature by Insured

29/03/2019

Date:

LETTER OF AUTHORIZATION

To: Name: Stuttgart Auto Pte Ltd
From: Name: Leon Liu Zun
Address: 2 Phoenix Garden
S(668270)

In the matter of an accident involving motor vehicles SL 8300B & SMF 2338C on
26/01/2019 at machap PR Johore

I/we Leon Liu Zun the owner of vehicle registration no: SL 8300B
hereby authorize you to commence repairs to my above-mentioned vehicle.

I/We confirm that you are hereby authorized to handle the repair and /or to negotiate and settle
any claims relating to the above accident which I/we may have against other third party /parties or
Insurers and /or to instruct lawyer on my /our behalf to facilitate the third party claim for me /us.

You are hereby authorized as my attorney to execute and /or sign any documents /discharge
vouchers /discharge agreement regarding my /our claim for my convenience.

I confirm that in the event of an unsuccessful claim against the negligent party and /or my own
Insurer for the damages caused to my vehicle, I agree to pay for all repair cost and /or any incidental
expenses incurred by you.

Dated the 26 day of 03 20 19

Leon Liu Zun
Owner (name /signature)
NRIC No. S1F33123E

Janice Syn
Witness (name /signature)
NRIC No. _____



[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0636C
Vehicle Details	
Vehicle No.:	SLL3052A
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	PE20841163
Chassis No.:	JM6GL1071H0105807
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$20,233.00
Original Registration Date:	21 Feb 2017
First Registration Date:	21 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$20,327.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Feb 2027
PARF Rebate Amount:	\$15,245.00
Intended COE Rebate Details	
COE Expiry Date:	20 Feb 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,209.00
COE Rebate Amount:	\$36,716.00
Total Rebate Amount:	\$51,961.00

The information contained herein is correct as at 09 Jul 2019

OK

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 14 February 2019 4:23 PM
To: eva.kok@eurokars.com.sg
Cc: janice.syn@porsche.com.sg; rickteo@eurokars.com.sg;
jobithomas@eurokars.com.sg; Admin A; assignments
Subject: RE: TP CLAIMS- SLL8300B & SMF2338C DOA 26/1/2019 *** LKK REF:
CC4/ASM19002137/fa3

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC4/ASM18002137/fa3
Your Ref: SLL 8300B

Dear Eva,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, kindly arrange TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

English (default) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾



SERVICE REQUESTS

MESSAGES

CLAIMS

<< TP Mandate IA < S9M01CDU >

Type

Question

Message

Dear Richard, Liability: Insured vehicle roll forward and collided into the rear of third party vehicle, Liability is down against our insured. We did clarify with OI (Mr Tan) the nature of the accident, he is agree to settle, aware that NCD (if any) is affected. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "Stuttgart Auto Pte Ltd" is as follows: - 1) COR(w/gst): \$4,181.04 + 2) Loss of Rental (3 days x \$120.00+7%gst): \$385.20 = Total: \$4,566.24. **4days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please.
PohKin- LKK- 09/07/2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 9/7/2019

Survey Details:

Date of loss	26-Jan-19
Date of appointment	1-Feb-19
Date of survey	15-Feb-19
Location of survey	STUTTGART AUTO PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLL8300B
Make and Model	PORSCHE CAYMAN GT4 (981) - 3800cc
Date of registration	1-Aug-16
Parf Rebate	
Market Value	\$ 378,000.00
Parf Rebate	\$ 164,332.00
Nett Loss	\$ 213,668.00

Repair details:

Initial Estimate	18,853.72
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 327.51
Check items (estimate)	\$ -
Labour	\$ 3,580.00
Total	\$ 3,907.51
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>4 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Liability: Insured vehicle roll forward and collided into the rear of third party vehicle, Liability is down against our insured. We did clarify with OI (Mr Tan) the nature of the accident, he is agree to settle, aware that NCD (if any) is affected.

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	4,181.04 (\$3,907.51 +7%gst)
Loss of use	\$	-
Loss of rental	\$	385.20 (3 days x \$120.00 +7%gst)
Loss of income	\$	-
LTA search fees	\$	-
Others	\$	-
Proposed Total	\$	4,566.24



Re:TP Mandate IA < S9M01CDU >

Type

🔗 Question

Message

Hi, pls proceed as per mandate. TY>

Reply



Re:RE: Re:TP Mandate IA < S9M01CDU >

Type

🔗 Question

Message

Hi, we agree for LOR at \$160/- per day. TY.

Reply



PORSCHE

AXA INSURANCE PTE LTD
8 Shenton Way
#24-01 AXA Tower
Singapore 068811
Attn : Motor Claims Department

DATE : 03/07/2019

Your Ref : **SMF2338C**

Car Regn No: **SLL8300B**

Accident involving SLL8300B & SMF2338C on 26/01/2019

Direct Settlement Claim

Dear Sirs

The repairs have been completed for **SLL8300B**. We submit the following documents for your perusal :

1) Invoice No: 13205139	\$ 4,181.04
2) Car Rental Invoice No 18285	\$ 577.80
3) PRI (\$180.00 x 2 days)	\$ 360.00
4) Letter of Authority	
5) Discharge voucher signed by client	

TOTAL \$ **5,118.84**

Please pay **Stuttgart Auto Pte Ltd** the sum of **\$5,118.84** as soon as possible and mail your cheque to **12 Sungei Kadut Avenue Singapore 729648**.

Yours faithfully,

Tommy Woon
Assistant Manager - Body & Paint Division
DID : 63310693
FAX: 63310690
e-mail : tommywoon@eurokars.com.sg

Eurokars Centre

12 Sungei Kadut Avenue
Singapore 729648
Telephone: (65) 6363 0911
Fax: (65) 6363 3911



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002137/R1ga3s2

8 SHENTON WAY #24-01

AXA TOWERSINGAPORE 068811

Date : 02-09-2019



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMF 2338C	Veh. Inspected	SLL 8300B
Policy No.	GA402605/1	Coverage (\$)	0.00
Claim No.	S9M01CDU	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	01/02/2019

2. Vehicle Particulars & Condition

Make & Model	PORSCHE CAYMAN GT4	c.c	3800
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WP0ZZZ98ZGK189608	Colour	BLACK
Odometer	74459	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/30ZR20	MICHELIN	6 mm
L/H Front Tyre	295/30ZR20	MICHELIN	6 mm
R/H Rear Tyre	295/30ZR20	MICHELIN	6 mm
L/H Rear Tyre	295/30ZR20	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/01/2019	Inspection Date	15/02/2019
Survey held at	27A TANJONG PENJURU		
Repairer	STUTTGART AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 8300B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	2,109.10	-
1	BUMPER PROTECTIVE FILM LH (CONSISTENT)	NECESSARY	18.10	18.10
1	BUMPER PROTECTIVE FILM RH (CONSISTENT)	NECESSARY	18.10	18.10
1	BUMPER LOWER RETAINER FRAME (CONSISTENT)	SERVICEABLE	459.40	-
10	U-CLAMP (CONSISTENT)	SERVICEABLE	12.00	-
1	BUMPER LOWER GARNISH LH (CONSISTENT)	SERVICEABLE	151.70	-
1	BUMPER LOWER GARNISH RH (CONSISTENT)	SERVICEABLE	151.70	-
1	TAIL PIPE GARNISH (CONSISTENT)	SERVICEABLE	162.70	-
1	LOGO "PORSCHE" BLACK (CONSISTENT)	NECESSARY	198.80	198.80
1	LOGO "GT4" BLACK (CONSISTENT)	NECESSARY	128.90	128.90
1	MAIN ENTRANCE MUFFLER RH (CONSISTENT)	SERVICEABLE	3,521.80	-
1	MAIN ENTRANCE MUFFLER LH (CONSISTENT)	SERVICEABLE	3,521.80	-
1	TAIL PIPE (CONSISTENT)	SERVICEABLE	1,584.10	-
1	EXHAUST MUFFLER CLAMP (CONSISTENT)	SERVICEABLE	92.60	-
4	HEXAGON NUT (WF57) (CONSISTENT)	NOT NECESSARY	21.20	-
2	EXHAUST GASKET (CONSISTENT)	NOT NECESSARY	18.80	-
	LESS 10% DISCOUNT		-1,217.08	-36.39
			10,953.72	327.51
SPECIAL NETT ITEMS				
1	REAR BUMPER STICKER (SN) (CONSISTENT)	NOT NECESSARY	800.00	-
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NECESSARY	70.00	70.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			920.00	90.00
LABOUR				
	TO REPLACE REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT, INCLUSIVE OF THE REPAIR OF REAR BUMPER.		3,120.00	1,560.00
	TO RESPRAY REAR BUMPER.		1,500.00	1,300.00
	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NOT NECESSARY	1,560.00	-

Report Ref No. CC4/ASM19002137/R1ga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		200.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	480.00
			6,980.00	3,490.00
GRAND TOTAL			18,853.72	3,907.51
RECOMMENDED COST OF REPAIRS				3,907.51

Report Ref No. CC4/ASM19002137/R1ga3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.