



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: MOTOR CLAIM DEPT FAX: 68804838 / 68804739		NAME: Mr Leon Liu Zun ADDRESS: 2 Phoenix Garden Singapore 668270 TEL:		WIP: 42362 EXCESS: DATE: 01.02.2019	
VEH NO:	SLL8300B	DATE IN:		CONTACT PERSON:	EVA 63310683
CHASSIS NO:	WPQZZZ98ZGK189608	MILEAGE:		TYPE OF CLAIM:	TP
MODEL:	Cayman GT4	DATE REG:	01.08.2016	POLICY NO.:	

NATURE OF WORKS					
S/NO	Parts Description	QTY		REVISED	PRICES
1	REAR BUMPER <i>repa</i>	1	P981-505-991-80-		\$ 2,109.10
2	BUMPER PROTECTIVE FILM LH <i>re</i>	1	P981-505-691-00-		\$ 18.10
3	BUMPER PROTECTIVE FILM RH <i>re</i>	1	P981-505-692-00-		\$ 18.10
4	BUMPER LOWER RETAINING FRAME <i>X su</i>	1	P981-505-853-80-1E0		\$ 459.40
5	U-CLAMP <i>X su</i>	10	P999-507-696-00-		\$ 12.00
6	BUMPER LOWER GARNISH LH <i>X su</i>	1	P981-505-511-80-1E0		\$ 151.70
7	BUMPER LOWER GARNISH RH <i>X su</i>	1	P981-505-512-80-1E0		\$ 151.70
8	TAIL PIPE GARNISH <i>X su</i>	1	P981-505-811-80-1E0		\$ 162.70
9	LOGO "PORSCHE" BLACK <i>re</i>	1	P991-559-235-90-		\$ 198.80
10	LOGO "GT4" BLACK <i>re</i>	1	P981-559-251-80-		\$ 128.90
11	MAIN EXHAUST MUFFLER RH <i>? X su</i>	1	P981-111-922-06-		\$ 3,521.80
12	MAIN EXHAUST MUFFLER LH <i>? X su</i>	1	P981-111-921-06-		\$ 3,521.80
13	TAIL PIPE <i>? X su</i>	1	P981-111-361-61-		\$ 1,584.10
14	EXHAUST MUFFLER CLAMP <i>? X su</i>	1	P981-111-280-00-		\$ 92.60
15	HEXAGON NUT (WF57) <i>? X su</i>	4	P900-910-003-03-		\$ 21.20
16	EXHAUST GASKET <i>? X su</i>	2	P982-251-263-		\$ 18.80
TOTAL PARTS					\$ 12,170.80
LESS 10%					\$ 1,217.08
TOTAL PARTS COST					\$ 10,953.72

Labour Description		
1	TO REPLACE REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560 / \$ 3,120.00
2	TO RESPRAY REAR BUMPER.	1300 / \$ 1,300.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY. <i>X su</i>	NETT \$? 1,560.00
4	TO INSTALL THE REAR BUMPER STICKER. (2 WORKING DAYS) AS PER QUOTATION <i>invoice? re</i>	NETT <i>X su</i> \$ 800.00
5	TO SUPPLY 1 PC REAR NUMBER PLATE. <i>X su</i>	NETT \$ 70.00



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS

EUROKARS GROUP

AXA INSURANCE PTE LTD		NAME : Mr Leon Liu Zun	WIP : 42362
8 SHENTON WAY		ADDRESS : 2 Phoenix Garden	EXCESS :
#24-01 AXA TOWER		Singapore 668270	DATE : 01.02.2019
SINGAPORE 068811		TEL :	
ATTN. :	MOTOR CLAIM DEPT		
FAX :	68804838 / 68804739		

VEH NO :	SLL8300B	DATE IN :		CONTACT PERSON :	EVA	63310683
CHASSIS NO :	WPOZZZ98ZGK189608	MILEAGE :		TYPE OF CLAIM :	TP	
MODEL :	Cayman GT4	DATE REG.:	01.08.2016	POLICY NO. :		

NATURE OF WORKS
Parts Description

	QTY			REVISED	PRICES
1	REAR BUMPER	1	P981-505-991-80-	\$ -	\$ 2,109.10
2	BUMPER PROTECTIVE FILM LH	1	P981-505-691-00-	\$ 18.10	\$ 18.10
3	BUMPER PROTECTIVE FILM RH	1	P981-505-692-00-	\$ 18.10	\$ 18.10
4	BUMPER LOWER RETAINING FRAME	1	P981-505-853-80-1E0	\$ -	\$ 459.40
5	U-CLAMP	10	P999-507-696-00-	\$ -	\$ 12.00
6	BUMPER LOWER GARNISH LH	1	P981-505-511-80-1E0	\$ -	\$ 151.70
7	BUMPER LOWER GARNISH RH	1	P981-505-512-80-1E0	\$ -	\$ 151.70
8	TAIL PIPE GARNISH	1	P981-505-811-80-1E0	\$ -	\$ 162.70
9	LOGO "PORSCHE" BLACK	1	P991-559-235-90-	\$ 198.80	\$ 198.80
10	LOGO "GT4" BLACK	1	P981-559-251-80-	\$ 128.90	\$ 128.90
11	MAIN EXHAUST MUFFLER RH	1	P981-111-922-06-	\$ -	\$ 3,521.80
12	MAIN EXHAUST MUFFLER LH	1	P981-111-921-06-	\$ -	\$ 3,521.80
13	TAIL PIPE	1	P981-111-361-61-	\$ -	\$ 1,584.10
14	EXHAUST MUFFLER CLAMP	1	P981-111-280-00-	\$ -	\$ 92.60
15	HEXAGON NUT (WF57)	4	P900-910-003-03-	\$ -	\$ 21.20
16	EXHAUST GASKET	2	P982-251-263- -	\$ -	\$ 18.80

TOTAL PARTS	\$ 363.90	\$ 12,170.80
LESS 10%	\$ 36.39	\$ 1,217.08
TOTAL PARTS COST	\$ 327.51	\$ 10,953.72

Labour Description

1	TO REPLACE REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,560.00	\$ 3,120.00
2	TO RESPRAY REAR BUMPER.	\$ 1,300.00	\$ 1,500.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	\$ -	\$ 1,560.00
4	TO INSTALL THE REAR BUMPER STICKER. (2 WORKING DAYS) AS PER QUOTATION	\$ -	\$ 800.00
5	TO SUPPLY 1 PC REAR NUMBER PLATE.	\$ 70.00	\$ 70.00

6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 480.00	\$ 600.00
8	SUNDRIES.	\$ 20.00	\$ 50.00
TOTAL LABOUR		\$ 3,580.00	\$ 7,900.00
TOTAL PARTS		\$ 327.51	\$ 10,953.72
TOTAL		\$ 3,907.51	\$ 18,853.72
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ 3,907.51	
GST 7%		\$ 273.53	\$ -
GRAND TOTAL		\$ 4,181.04	\$ -

NUMBER OF DAYS: 4 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)

6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$ 150 200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 480 600.00
8	SUNDRIES.	NETT	\$ 20 50.00
		TOTAL LABOUR	\$ - \$ 7,900.00
		TOTAL PARTS	\$ - \$ 10,953.72
		TOTAL	\$ - \$ 18,853.72
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ - \$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Rasul
Hp 90010068
(4) 5 days
15/02/19 @ 1630
Resumy after repair
4 days