

Steve chen@lkkauto.com

Steve 8322 8813

hit

PP 5 hrs

Reg bfr 6 af spray

25/2/19 2:20pm

SERVICE ESTIMATE

89896 - C00001 SL: SERVICE SALES - PC

Mr Eu Chee Wei David

8 Vanda Drive

Singapore 287847

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Eu Chee Wei David

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 23/01/2019

WIP No. . : 50004

Veh.In/Out:

*Tel.No. . : Mobile: 82888835

Reg.No. . : EU3338L

Reg.date . : 29/05/2017

Mileage . : 0

Chassis No: YV1DZ40LDH2165426

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BOOT LID,REAR EMBLEM,REAR BUMPER,REAR SPOILER, REAR SKID PLATE,REAR SENSOR,REAR BEAM,REAR BRACKET,ETC	0	3200.00	0	3,200.00 S	1600	
-----	---	---	---------	---	------------	------	--

800	TO PUTTY SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,REAR LOWER SPOILER,ETC	0	2800.00	0	2,800.00 S	2100	
-----	--	---	---------	---	------------	------	--

802	TO TRANSFER REAR BOOT LID PART	0	250.00	0	250.00 S	X	
802	TO REPLACE REAR WINDSCREEN	0	800.00	0	800.00 S	X	
89994	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0	280.00 S	X	
280	TO CHECK WIRING INCLUDE	0	450.00	0	450.00 S	/	

RESETTING OF ALL ELECTRICAL MODULES

BUMPER COVER REAR XC	1.0 EA	1454.80	1,454.80 S
PROTECT PLATE REAR X	1.0 EA	770.40	770.40 S
BUMPER SPOILER REAR	1.0 EA	434.30	434.30 S
BUMPER BRACKET LHR X	1.0 EA	66.10	66.10 S

SERVICE ESTIMATE

89896 - C00001 SL: SERVICE SALES - PC

Mr Eu Chee Wei David

8 Vanda Drive

Singapore 287847

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Eu Chee Wei David

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 23/01/2019

WIP No. . : 50004

Veh.In/Out:

*Tel.No. . : Mobile: 82888835

Reg.No. . : EU3338L

Reg.date. : 29/05/2017

Mileage . : 0

Chassis No: YV1DZ40LDH2165426

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET RHR X ?	1.0 EA	66.10			66.10	S
	BUMPER BRACKET REAR ?	1.0 EA	73.90			73.90	S
	BUMPER BRACKET REAR ?	1.0 EA	73.90			73.90	S
	BUMPER BRACKET REAR ?	1.0 EA	63.00			63.00	S
	SKID PLATE RIM LH XC	1.0 EA	249.30			249.30	S
	SKID PLATE RIM RH XC	1.0 EA	253.00			253.00	S
	BUMPER RAIL (BEAM) R	1.0 EA	1336.30			1,336.30	S
	BLIND RIVET 4.0*21 P / NEC	10.0 EA	3.00			30.00	S
	BUMPER CLIP 8x8,5 / NEC	10.0 EA	5.40			54.00	S
	BUMPER INSTALLING MT / NEC	1.0 EA	83.40			83.40	S
	ADHESIVE TUBE CHEMIC / NEC	4.0 EA	75.80			303.20	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- No supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature by Repairer

Sign Date:

Date:

Gross Total. 13,091.70

Net..... 13,091.70

GST @ 7.0% 916.42

Total..... 14,008.10

Paid..... 0.00

Please Pay.. 14,008.10