Mei Kwan (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Wednesday, 20 February, 2019 4:22 PM

To: Mei Kwan (LKKAuto)
Cc: Vic (LKKAuto); Joel Goh

Subject: FW: Direct Settlement - Accident Involving GBG3280C (DM19HO00310/JG:) AND

SHC4756R (TP: LKK REF - CC3/EQI19002143/Jha3) on 28/01/2019

Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf; TP GIA REPORT.pdf;

SAS2544120.PDF

Dear Mei Kwan

OI report as attached.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Wednesday, February 20, 2019 11:55 AM **To:** EQI PRS < EQIPRS@eqinsurance.com.sg>

Cc: Joel Goh <joel.goh@eqinsurance.com.sg>; Janet Tan <janet.tan@eqinsurance.com.sg>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>; Admin A <admin-a@lkkauto.com> **Subject:** Direct Settlement - Accident Involving GBG3280C (OI: EQI - TBA) AND SHC4756R (TP: LKK REF -

CC3/EQI19002143/Jha3) on 28/01/2019

<u>'WITHOUT PREJUDICE'</u> SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 4756R at M/s SMRT Automotive Services Pte Ltd (Woodlands) on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: <u>MeiKwan@lkkauto.com</u> | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)