

12/03/2002

ASS. REC. BY:

REF: CS/FCI19002156/Upd3ⁿ²

Special Instruction:

Surveyor:

Marius

ASSIGNMENT (Office)

From (Person):

Mary chua

of

FCI

Date/Time: 3:15pm @ 1/2/19

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 7796X

Insured:

SHD 4880J

at Workshop m/s

Trans Eurokars

Tel:

81289802

of

Subi close

Policy No:

Claim No:

D19000770MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/01/2019

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 4:25pm @ 1/2/19

Person Contacted:

Jess -

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 7796S - x

SHD 4880J - CS/FCI18010616/Dtd3e2

DUA: 7/6/18

12/19 @ 4:32pm revised preli advise via email.

REF: FCI

ASSIGNMENT

Date: 11/02/2019

Estimated Cost

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

SLJ 7796X

at Workshop no

Trans Eurokars

of

5 ubi close

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh

4pm owner waiting

Jess

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value:

88

ACC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: 54J7796X

Reg: 12 16

Type: ☒ M / Car / M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Mercedes BIANTE

C.G

1998

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp. Reading

26726

T/Radio

Insured / Std / NI / NA

Eng/No

C/No

JM6CC107190110077

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

7

mm

R/Bal:

7

mm

L/Bal:

7

mm

L/Bal:

7

mm

D.O.A.

26/1/19

D.O.I.

11/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Req.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 60413

30/4/19 conf. and final by P 7317.98 with Catherine.
Cred to 4491.15 (38%)

RECEIVED 30 APR 2019

Date/Time: File Pass to?

☐

Preli. Report

30/4 typing

☐

Final Report

Date/Time: File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Inv (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

Food & Bev (\$)

Photos

Other

TOTAL

Report Format:

TP

Lump Sum / L.B.T. (\$)

7317.99

170+15

50

50

37

322



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000770MFSH

Date: 12/2/2019

Our Ref: CS/FCI19002156/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 7796X

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/2/2019 at the premises of M/s Trans Eurokars have the following to report: -

Workshop Estimate Amount	: S\$ <u>11,8094.14</u>
Revised Estimate Amount	: S\$ <u>7,317.99</u>
"Check" Items Amount	: S\$ <u>414.90</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-01-2019	Our Ref No. D19000770MFSH
Accident Date	26-01-2019	Claim Type. Third Party
Insured Vehicle	SHD4880J	Third Party Vehicle. SLJ7796X
Survey Location	5 UBI CLOSE	
Contact Person.	JESS FRANCIS CARLOS	
Contact No.	81289802/ 81289802	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUOKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 12 February 2019 4:32 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000770MFSH/1
Attachments: PRELI ADVISED SLJ 7796X.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLJ 7796X**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 1 February 2019 4:51 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000770MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes Benz E63S , 16 Jan 2014, \$232888.



Rare Top Of The Line E63 S
AMG, Hellacious V8 Bassy Note,
Wolf In Sheep's Cloth!
ACM Automobiles - StarAd



Browse by Category

Sort by Date Posted

Advanced Search

3 vehicles

Mazda Bianté

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
	Mazda Bianté		Any	Any	2016	Any	Any	
	Mazda Bianté	Mazda Bianté 2.0A	\$88,000	\$11,300 /yr	14-Jan-2016	1,998 cc	14,000 km	
Very Well Taken Care Of And In Excellent Condition For Both The Interior And Exterior. A Nicely Dependable MPV To Drive Along. Viewir By Appointment Only. No Dealers Or Consignment Agent ...								
Posted: 02-Feb-2019			Tags: 2016 Mazda Bianté, 2016 mazda bianté, Mazda Bianté, mazda bianté, Mazda, Bianté, bianté, Used Mazda					
	Mazda Bianté	Mazda Bianté 2.0A	\$92,000	\$10,380 /yr	28-Oct-2016	1,998 cc	40,500 km	
One Of The Most Spacious MPVs In The Market At A Lowest Depreciation Of Its Class. Agent High Option Unit. Comes With Warranty Ar Complementary Servicing. Auto Sliding Doors And Electric Tail ...								
Posted: 28-Jan-2019			Tags: 2016 Mazda Bianté, 2016 mazda bianté, Mazda Bianté, mazda bianté, Mazda, Bianté, bianté, Used Mazda					
	Mazda Bianté	Mazda Bianté 2.0A	\$88,000	\$10,530 /yr	16-Jun-2016	1,998 cc	50,000 km	
Come Own One Of The Most Spacious MPVs In The Market At A Competitive \$10k Depreciation! Well Taken Care Of Unit With Regular S Pirelli Tyres, In-Car Dash Cam, DVD Player With Local Chann...								
Car Buyers Automotive Pte Ltd			Posted: 15-Dec-2018					
			Tags: 2016 Mazda Bianté, 2016 mazda bianté, Mazda Bianté, mazda bianté, Mazda, Bianté, bianté, Used Mazda					

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage V

For old advertisements, view **Expired ads**

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resour

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, truc cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage car insurance. Find buy used Mazda Bianté, Mazda Bianté Singapore, used Mazda Bianté Singapore, used Mazda Bianté, used vehicles Singapore or even buy used f new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle

All prices

played on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliat accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accur

Compare

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0913H
Vehicle Details	
Vehicle No.:	SLJ7796X
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	MAZDA
Vehicle Model:	BIANTE 5-DOOR WAGON 2.0L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	PE30923144
Chassis No.:	JM6CC1071G0110077
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$21,017.00
Original Registration Date:	27 Dec 2016
First Registration Date:	27 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$21,424.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Dec 2026
PARF Rebate Amount:	\$16,068.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,340.00
COE Rebate Amount:	\$44,345.00
Total Rebate Amount:	\$60,413.00

The information contained herein is correct as at 12 Feb 2019

OK

Owner IC & LIC



gsiml@gmail.com





Contact us at
Hotline: (65) 6532 2888
E-mail: CustomerService@DirectAsia.com

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act")
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore)
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)


This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No.	: MT/00439111/01
Type of Coverage / Driver Plan	: Car Comprehensive (Value Plus Plan)
1) Vehicle Registration No.	: SLJ7796X
Chassis No.	: JM6CC1071G0110077
2) Name of Policy Holder	: LIM SAY SIONG
3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	: 27/12/2018 00:00
4) Date/Time of Expiry of Insurance	: 26/12/2019 23:59
5) Persons or Classes of Persons Entitled to Drive	
(a) Any named person under the policy who is driving on the Policyholder's permission.	
(b) Any authorised person, provided such person is aged 30 and above and holds a valid driving licence of 2 years or more, who is driving on the Policyholder's permission	
The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.	
6) Limitations as to use*	
Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business.	
*Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.	
Sum Insured	: Market Value
Own Damage Excess	: S\$ 500.00 (before any applicable GST)
Windscreen Excess	: S\$ 100.00 (before any applicable GST)
Choice of workshop	: My Workshop/ My Authorised Distributor Workshop
Finance company / Hire Purchase	: HONG LEONG FINANCE
Main driver	: LIM SAY SIONG
Named driver	: None
Important Note: This policy does not cover the Policyholder/drivers below the age of 30 and Policyholder/drivers who hold a valid driving licence of less than 2 years with the exception of the main/named drivers above.	



I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Direct Asia Insurance (Singapore) Pte. Ltd.

Issued on: 28/11/2018


Edip Okur
Chief Underwriting Officer

Direct Asia Insurance (Singapore) Pte Ltd
20 Anson Road #08-01 Twenty Anson Singapore 079912
www.DirectAsia.com





TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

Not Authorized

FIRST CAPITAL INS

36 ROBINSON ROAD

CITY HOUSE, #16-01

ATTN: (068877) MOTOR CLAIMS

FAX :

NAME : Mr Lim Say Siong

ADDRESS : Blk 240 Lorong 1 Toa Payoh

#08-116

Singapore 310240

TEL : 93801742

WIP : 42025

EXCESS :

DATE: 28-Jan-19

6 by.

HLK Marcus 11/2/19

Take photo before painting

VEH NO :	SLJ7796X	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6CC1071G0110077	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	BIANTE	DATE REG.:	27-Dec-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER <i>2/pe</i> 1	MC275-50-221FBB	\$ 1,114.70
2	STRIPE LHS, REAR BUMPER <i>neu</i> 1	MC467-50-888	\$ 81.90
3	STRIPE CENTER, REAR BUMPER <i>neu</i> 1	MC467-50-879	\$ 123.90
4	STRIPE RHS, REAR BUMPER <i>neu</i> 1	MC467-50-878	\$ 81.90
5	GROMMET, REAR BUMPER <i>neu</i> 2	MB01W-51-142B	\$ 6.00
6	GROMMET, REAR BUMPER <i>neu</i> 2	MBP4K-50-ES1	\$ 8.80
7	PIN LOCATOR, REAR BUMPER <i>neu</i> 2	MGJ6B-50-1K5	\$ 8.00
8	RIVET, REAR BUMPER <i>neu</i> 2	MA001-50-7C1	\$ 7.20
9	FASTENER, REAR BUMPER <i>neu</i> 2	MGD7A-50-EA1	\$ 6.00
10	REAR END PANEL <i>1</i> 1	MC273-70-750B	\$ 288.70
11	TRIM, END PANEL <i>1 1</i> 1	MC273-68-89XA56	\$ 116.40
12	FASTENER, TRIM <i>1 1</i> 2	MB467-68-AC3 02	\$ 7.40
13	TAILGATE <i>Body</i> 1	MC2Y3-62-02XF	\$ 1,618.70
14	WEATHERSTRIP, TAILGATE <i>1 1</i> 1	MC273-62-761B	\$ 207.90
15	FASTENER, TRIM <i>neu</i> 3	MB467-68-AC3 02	\$ 11.10
16	FASTENER, TRIM <i>neu</i> 3	MB467-68-AC3 34	\$ 15.90
17	SPACER, REAR WINDSCREEN <i>neu</i> 5	MGJ6A-50-897	\$ 60.50
18	FASTENER, REAR WINDSCREEN <i>neu</i> 2	MC273-50-896	\$ 15.60
19	PIN STUD, REAR WINDSCREEN <i>neu</i> 1	MG21E-63-938B	\$ 10.50
20	FASTENER, REAR WINDSCREEN <i>neu</i> 4	MD204-50-896A	\$ 10.40
21	ANTENNA, KEYLESS <i>1 1</i> 1	MC277-67-6N0	\$ 253.10
TOTAL PARTS			\$ 4,054.60
LESS 10%			\$ 405.46
TOTAL PARTS COST			\$ 3,649.14

Labour Description

1	TO REPLACE REAR BUMPER, REAR END PANEL AND TAILGATE. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	990	\$ 1,980.00
---	--	-----	-------------

TOTAL LABOUR	\$ -	\$ 8,160.00
TOTAL PARTS	\$ -	\$ 3,649.14
TOTAL	\$ -	\$ 11,809.14
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

- Third party survey is off a "Without Prejudice" basis
- No design modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

Not Authorized

FIRST CAPITAL INS.
36 ROBINSON ROAD,
CITY HOUSE, #16-01
SL064877

NAME: Mr Lim Say Siong
ADDRESS: Blk 240 Lorong 1 Toa Payoh
#08-116
Singapore 310240
TEL: 93801742

WIP: 42025
EXCESS:
DATE: 28-Jan-19
6 by.
HKK marcus 11/2/19
take photo before painting

ATTN: MOTOR CLAIMS
FAX:

VEH NO:	SLJ7796X	DATE IN:		CONTACT PERSON:	Jess 63957874
CHASSIS NO:	JM6CC1071G0110077	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	BIANTE	DATE REG.:	27-Dec-16	POLICY NO.:	


NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER	MC275-50-221F8B	\$ 1,114.70
2	STRIPE LHS, REAR BUMPER	MC467-50-888	\$ 81.90
3	STRIPE CENTER, REAR BUMPER	MC467-50-879	\$ 123.90
4	STRIPE RHS, REAR BUMPER	MC467-50-878	\$ 81.90
5	GROMMET, REAR BUMPER	MB01W-51-142B	\$ 6.00
6	GROMMET, REAR BUMPER	MBP4K-50-ES1	\$ 8.80
7	PIN LOCATOR, REAR BUMPER	MGJ6B-50-1K5	\$ 8.00
8	RIVET, REAR BUMPER	MA001-50-7C1	\$ 7.20
9	FASTENER, REAR BUMPER	MGD7A-50-EA1	\$ 6.00
10	REAR END PANEL	MC273-70-750B	\$ 288.70
11	TRIM, END PANEL	MC273-68-89XA56	\$ 116.40
12	FASTENER, TRIM	MB467-68-AC3 02	\$ 7.40
13	TAILGATE	MC2Y3-62-02XF	\$ 1,618.70
14	WEATHERSTRIP, TAILGATE	MC273-62-761B	\$ 207.90
15	FASTENER, TRIM	MB467-68-AC3 02	\$ 11.10
16	FASTENER, TRIM	MB467-68-AC3 34	\$ 15.90
17	SPACER, REAR WINDSCREEN	MGJ6A-50-897	\$ 60.50
18	FASTENER, REAR WINDSCREEN	MC273-50-896	\$ 15.60
19	PIN STUD, REAR WINDSCREEN	MG21E-63-9388	\$ 10.50
20	FASTENER, REAR WINDSCREEN	MD204-50-896A	\$ 10.40
21	ANTENNA, KEYLESS	MC277-67-6N0	\$ 253.10
TOTAL PARTS			\$ 4,054.60
LESS 10%			\$ 405.46
TOTAL PARTS COST			\$ 3,649.14

Labour Description

1	TO REPLACE REAR BUMPER, REAR END PANEL AND TAILGATE. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	990	\$ 1,980.00
---	--	-----	-------------



FIRST CAPITAL INSURANCE LTD		NAME : Mr Lim Say Siong		WIP : 42025	
		ADDRESS : Blk 240 Lorong 1 Toa Payoh		EXCESS :	
		#08-116		DATE: 28-Jan-19	
		Singapore 310240			
ATTN : MOTOR CLAIMS		TEL : 93801742			
FAX :					
VEH NO :	SLJ7796X	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6CC1071G0110077	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	BIANTE	DATE REG.:	27-Dec-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MC275-50-221FBB	\$ 1,114.70	\$ 1,114.70
2	STRIPE LHS, REAR BUMPER	1	MC467-50-888	\$ 81.90	\$ 81.90
3	STRIPE CENTER, REAR BUMPER	1	MC467-50-879	\$ 123.90	\$ 123.90
4	STRIPE RHS, REAR BUMPER	1	MC467-50-878	\$ 81.90	\$ 81.90
5	GROMMET, REAR BUMPER	2	MB01W-51-142B	\$ 6.00	\$ 6.00
6	GROMMET, REAR BUMPER	2	MBP4K-50-ES1	\$ 8.80	\$ 8.80
7	PIN LOCATOR, REAR BUMPER	2	MGJ6B-50-1K5	\$ 8.00	\$ 8.00
8	RIVET, REAR BUMPER	2	MA001-50-7C1	\$ 7.20	\$ 7.20
9	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	\$ 6.00	\$ 6.00
10	REAR END PANEL	1	MC273-70-750B		\$ 288.70
11	TRIM, END PANEL	1	MC273-68-89XA56		\$ 116.40
12	FASTENER, TRIM	2	MB467-68-AC3 02		\$ 7.40
13	TAILGATE	1	MC2Y3-62-02XF	\$ 1,618.70	\$ 1,618.70
14	WEATHERSTRIP, TAILGATE	1	MC273-62-761B		\$ 207.90
15	FASTENER, TRIM	3	MB467-68-AC3 02	\$ 11.10	\$ 11.10
16	FASTENER, TRIM	3	MB467-68-AC3 34	\$ 15.90	\$ 15.90
17	SPACER, REAR WINDSCREEN	5	MGJ6A-50-897	\$ 60.50	\$ 60.50
18	FASTENER, REAR WINDSCREEN	2	MC273-50-896	\$ 15.60	\$ 15.60
19	PIN STUD, REAR WINDSCREEN	1	MG21E-63-938B	\$ 10.50	\$ 10.50
20	FASTENER, REAR WINDSCREEN	4	MD204-50-896A	\$ 10.40	\$ 10.40
21	ANTENNA, KEYLESS	1	MC277-67-6N0		\$ 253.10
TOTAL PARTS				\$ 3,181.10	\$ 4,054.60
LESS 10%				\$ 318.11	\$ 405.46
TOTAL PARTS COST				\$ 2,862.99	\$ 3,649.14
Labour Description					
1	TO REPLACE REAR BUMPER AND TAILGATE. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 990.00	\$ 1,980.00

2		TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE.	\$ 1,575.00	\$ 1,890.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$ 560.00	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	\$ 120.00	\$ 120.00
5	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	\$ 250.00	\$ 660.00
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ 330.00	\$ 660.00
7	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 330.00	\$ 990.00
8	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ 350.00
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
12	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
TOTAL LABOUR			\$ 4,455.00	\$ 8,160.00
TOTAL PARTS			\$ 2,862.99	\$ 3,649.14
TOTAL			\$ 7,317.99	\$ 11,809.14
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 7,317.99	
GST 7%			\$ 512.26	\$ -
GRAND TOTAL			\$ 7,830.25	\$ -

REMARKS:

7 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002156/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4880J	Veh. Inspected	SLJ 7796X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000770MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	01/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA BIANTE (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6CC1071G0110077	Colour	BLUE	
Odometer	26726	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	DUNLOP	7 mm	
L/H Front Tyre	205/60 R16	DUNLOP	7 mm	
R/H Rear Tyre	205/60 R16	DUNLOP	7 mm	
L/H Rear Tyre	205/60 R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/01/2019	Inspection Date	11/02/2019	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 7796X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED / DEFORMED	1,114.70	1,114.70
1	STRIPE LHS, REAR BUMPER	NECESSARY	81.90	81.90
1	STRIPE CENTER, REAR BUMPER	NECESSARY	123.90	123.90
1	STRIPE RHS, REAR BUMPER	NECESSARY	81.90	81.90
2	GROMMET, REAR BUMPER	NECESSARY	6.00	6.00
2	GROMMET, REAR BUMPER	NECESSARY	8.80	8.80
2	PIN LOCATOR, REAR BUMPER	NECESSARY	8.00	8.00
2	RIVET, REAR BUMPER	NECESSARY	7.20	7.20
2	FASTENER, REAR BUMPER	NECESSARY	6.00	6.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	288.70	-
1	TRIM, END PANEL	NOT NECESSARY	116.40	-
1	FASTENER, TRIM	NOT NECESSARY	7.40	-
1	TAILGATE	BADLY DENTED	1,618.70	1,618.70
1	WEATHERSTRIP, TAILGATE	NOT NECESSARY	207.90	-
3	FASTENER, TRIM	NECESSARY	11.10	11.10
3	FASTENER, TRIM	NECESSARY	15.90	15.90
5	SPACER, REAR WINDSCREEN	NECESSARY	60.50	60.50
2	FASTENER, REAR WINDSCREEN	NECESSARY	15.60	15.60
1	PIN STUD, REAR WINDSCREEN	NECESSARY	10.50	10.50
4	FASTENER, REAR WINDSCREEN	NECESSARY	10.40	10.40
1	ANTENNA, KEYLESS	NOT NECESSARY	253.10	-
	LESS 10% DISCOUNT		-405.46	-318.11
			3,649.14	2,862.99
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			100.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE REAR BUMPER, REAR END PANEL AND TAILGATE. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,980.00	990.00
	TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE.		1,890.00	1,575.00
	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		560.00	560.00
	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		120.00	120.00
	TO TRANSFER REVERSE SENSOR. (WITH REVERSE SENSOR)		660.00	250.00
	TO TRANSFER REVERSE CAMERA.		660.00	330.00
	TO REMOVE & REFIT CARPET& TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		990.00	330.00
	TO SUPPLY SPRAY TEROSTAT SELANT ON THE CUTTING.	NOT NECESSARY	350.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			8,060.00	4,425.00
	GRAND TOTAL		11,809.14	7,317.99
RECOMMENDED COST OF REPAIRS				7,317.99

Report Ref No. CS/FCI19002156/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.