

ASS. REC. BY:

REF

CS/SMA19002205/ Atd3ⁿ²

Special Instruction:

SURVEYOR
Menmen

Adrian

ASSIGNMENT (Office)

From (Person): chen shu hui agnes

of SMO

Date/Time: 7/2/19 2:50pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No:

SJP 38404

Insured:

FBH 3875G

at Workshop m/s

TK Motor Workshop

Tel:

9627 3323

of

1 kaki Bkt Ave 6 # 02-56 Autobay

Policy No:

D18MTMCO1004769

Claim No:

CMTD1900713

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/02/2019

CA / REV / REP. / REV 24 HRS ^{1 up}

H.O.D. Endorsement:

Date/Time: 3:46pm @ 7/2/19

Person Contacted:

Kenny

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	SJP 38404-X
	FBH 3875G-X
8/2/19-	VNI Repairer call Adrian call him on 11/2/19
11/2/19-	called Kenny No answer, Kenny called back to he said will arrange with Adrian.
13/2-	Revised via menmen pending Estiment

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

23/03/09.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SJP3840U Yr Regn: 2009 MarchType: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish. c.c. 1794Colour: White A/C: Insured / Std / NI / NASp. Reading: 184599 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDER12W903002976Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 12/02/15Survey held at T.K.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 50mpo
Already Analise

Pending COE Renewal.

Lump Sum \$38007 Ured: 5612.50 (59%)

mv:

PV: 9.3k

Nett:

RECEIVED 15 JUL 2019

Date/Time, File Pass to?

1) 15th Typist

3)

5)

Prel. Report:

Final Report:

Date/Time, File Return to?

2)

4)

6)

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

25011261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2019		07 Feb 2019 14:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SHEIK MUHAMMAD KASHMEER BIN MOHD YUSOFF, ID: S9512272H		
Main Claimant:	TK MOTOR WORKSHOP, Co. Reg. No.: 53049097L		
Vehicle Reg. No.:	SJP3840U	Date of Loss:	01/02/2019 10:00 - :59
Claim Type:	TP / CMTD1900713	Policy/Cover Note No.:	D18MTMC01004769 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	FBH3875G	Policy No. (Claimant):	
		Excess:	
Repairer:	Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt, 417883 Kaki Bukit - Tel: 67466896		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/02/2019]		
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Teo, Grace

From: Kuru & Co <kurulegal@yahoo.com.sg>
Sent: Thursday, February 07, 2019 2:45 PM
To: Teo, Grace
Cc: Chan, Shu Hui Agnes; Ye, Yong Kang Melvin
Subject: Re: CMTD1900713/AGC \ Yr Ref: L19.0140.AT - PRI/ FBH3875G & SJP3840U ACC ON 01.02.19

Dear Sirs

Our client is agreeable to the following surveyor as the SJE: **LKK Auto Consultants Pte Ltd**

Please arrange for your surveyor to survey our client's vehicle at the following address:

TK MOTOR WORKSHOP
1 Kaki Bukit Ave 6
#02-56 AutoBay@Kaki Bukit
Singapore 417883
Contact: 9627 3323

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Anne

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

From: "Teo, Grace" <grace.teo@sompo.com.sg>
To: Kuru & Co <kurulegal@yahoo.com.sg>
Cc: "Chan, Shu Hui Agnes" <agnes.chan@sompo.com.sg>; "Ye, Yong Kang Melvin" <melvin.ye@sompo.com.sg>
Sent: Thursday, 7 February 2019, 13:35
Subject: CMTD1900713/AGC \ Yr Ref: L.19.0140.AT - PRI/ FBH3875G & SJP3840U ACC ON 01.02.19

Our Reference : CMTD1900713/AGC
Your Reference: L.19.0140.AT

Date: 07/02/2019

Without Prejudice
EMAIL ONLY

Attention:
M/S KURU & CO

Dear Anne,

ACCIDENT INVOLVING FBH3875G & SJP3840U ON 01.02.2019

We refer to your Notice of Accident dated 07/02/2019.

Please be informed that **Ms. Agnes Chan** is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Thursday, February 07, 2019 9:40 AM
To: Claims - Motor Survey
Subject: Our Ref: L.19.0140.AT//Your Ref: FBH 3875G//PRS

Dear Sirs

ACCIDENT INVOLVING SJP 3840U & FBH 3875G ON 01.02.2019

ALONG BEDOK RESERVOIR VIEW

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **T K Motor Workshop**, whose vehicle registration number **SJP 3840U** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards
Anne
Kuru & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

View Sent Message

This mail is associated with :

***SJP3840U (CMTD1900713)
[FBH3875G]**

TP

TK MOTOR WORKSHOP

Feb 1 2019 10:00AM

[SHEIK MUHAMMAD KASHMEER BIN MOHD YUSOFF]

Tk Motor Workshop

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 13/02/2019 14:11 PM.

To agnes.chan@sompo.com.sg

Subject *SJP3840U (CMTD1900713) [FBH3875G]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJP 3840U on 12/02/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9097L
Vehicle Details	
Vehicle No.:	SJP3840U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1ZZ3239066
Chassis No.:	JTDER12W903002976
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,662.00
Original Registration Date:	23 Mar 2009
First Registration Date:	23 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$18,662.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2019
PARF Rebate Amount:	\$9,331.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$3,000.00
COE Rebate Amount:	\$7.00
Total Rebate Amount:	\$9,338.00

The information contained herein is correct as at 13 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2019 19:47
Date Of Accident	01/02/2019 10:00
Exact Location Of Accident	BEDOK RESERVOIR VIEW
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP3840U
Insured/Policyholder	
Name Of Registered Owner	TK MOTOR WORKSHOP
Co Reg No	53049097L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96273323
Alternative Phone No	OFFICE-96273323

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 AUTO
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094647396
Cover Note Number	

Driver

Name of Driver	LOH LIN HIONG RICHARD
NRIC No	S6941057Z
Date Of Birth	28/11/1969
Occupation	OUTDOOR
Date Of Driving Pass	23/06/2014
Driving Experience	4 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97269882
Fax Number	
Contact Number	OTHERS-97269882
EMail Address	NOEMAIL

Address	BLK 114 PUNGGOL WALK #02-29
Postcode	828767
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20190202/7001

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBH3875G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	SHEIK MUHAMMAD KASHMEER BIN MOHD YUSOFF
NRIC/Passport Number	S9512272H
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LOH LIN HIONG RICHARD

Approximate Age

Injuries Sustain SLIGHT

Injured person in which vehicle? SJP3840U

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

Address


Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

TK Motor Workshop

Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

7/2/2019
Witnessed by Reporting Centre Personnel

Sketch Plan

Bedok Reservoir View	
	
(A) SJP 3840 U	
(B) FBH 3875 G	The clean water codo.

Sketch Plan #2

Describe Circumstances of the Accident

* Refer To Police Report NO: T/20190202/7001

Declaration

We declare the foregoing particulars are true in every respect.

TK Motor Workshop
[Signature]

Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature] 7/2/2019
Witnessed by Reporting Centre Personnel

Police Report



**SINGAPORE
POLICE FORCE**



T/20190202/7001

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190202/7001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/02/2019 00:24	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: LOH LIN HIONG RICHARD			Address: APT BLK 114 PUNGGOL WALK #02-29 SINGAPORE 828767		
ID Type / ID No.: NRIC NO / S6941057Z			Contact No.: Home/Office: Mobile: 97269882		
Nationality: SINGAPORE CITIZEN			Email: richardmpthree@gmail.com		
Sex: Male	Age: 49	Date of Birth: 28/11/1969	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: Date of Expiry:		

General information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/02/2019 10:00	Type of Location: Straight Road
Location: BEDOK RESERVOIR VIEW				
Weather: Sunny		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBH3875G	Motorcycle			Black	Slightly Damaged	0
SJP3840U	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20190202/7001

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190202/7001

CONTINUATION OF REPORT

Rider			
Name	SHEIK MUHAMMAD KASHMEER BIN MOHD YUSOFF		ID No. S9512272H
Related Vehicle	FBH3875G (Motorcycle)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	LOH LIN HIONG RICHARD		ID No. S6941057Z
Related Vehicle	SJP3840U (Car)		Contact No. 97269882
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

At about 1000 hours, I was driving my vehicle (SJP3840U) along Bedok Reservoir View, which was stationary, waiting to turn right into the condo (The Clearwater). Suddenly, I felt an impact hit onto the rear of my vehicle. I had gotten down to find that, I had been hit by a motorcycle (FBH3875G). At the point of accident, the rider said that his stomach was pain. I wanted to call the ambulance immediately but the rider refused and insisted that he would settle it on his own. After which, we had exchanged particulars. I had continued my work. After a few hours, I had experienced back and neck pains. I had then proceeded to Mount Alvernia Hospital, and was given 5 days of medical certification.

Police Report



**SINGAPORE
POLICE FORCE**



T/20190202/7001

3 of 3

Report No. T/20190202/7001

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
02/02/2019 00:24

Classification Of Case:

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 96273323 FAX: 68442641
CO. REG NO : 53049097 L

LKK · Adrian.

DATE: 27/02/2019

TK MOTOR WORKSHOP
BLK 114 PUNGGOL WALK #02-29
SINGAPORE 828767

TP Sampo Denise

JTDFR12WS03002576

DEAR SIR

ACCIDENT DATE: 01/02/2019

ESTIMATE COST OF REPAIRS BILL TO TOYOTA WISH 1.8 AUTO CAR NO: SJP3840U

1	PC REAR BOOTLID	Dented	S\$	1277.20	1277.20	✓
1	PC REAR BOOTLID EMBLEM	new		58.50	58.50	-
1	PC REAR BOOTLID CHROME MOULDING	He new		297.10	297.10	+
1	PC REAR BOOTLID LOCK	new		349.40	349.40	x
1	PC REAR BOOTLID RUBBER	new		159.40	159.40	x
2	PC REAR BOOTLID ASBORBER	new		357.80	357.80	+
1	PC REAR END PANEL	Dented		578.40	578.40	✓
1	PC REAR END PANEL GARNISH	Behind		178.40	178.40	✓
1	PC REAR BUMPER	Behind		1,077.20	1,077.20	545.20
1	PC REAR BUMPER REFLECTOR	crushed		75.60	75.60	✓
2	PC REAR BUMPER BRACKET	LH Dented		149.80	149.80	74.80
2	PC REAR BUMPER SIDE RETAINER	new		157.20	157.20	✓
8	PC REAR BUMPER CLIP	new		30.40	30.40	✓
2	PC REAR BUMPER SIDE CLIP	new		25.60	25.60	✓
1	SET REAR BUMPER REVERSE SENSOR	Dented		200.00	200.00	S/NETT ✓
1	PC REAR L/H TAILLAMP	crushed		509.40	509.40	408
1	PC REAR L/H TAILLAMP BRACKET	Dented		28.40	28.40	✓
1	PC REAR REVERSE CAMERA	new		380.00	380.00	S/NETT x
1	PC REAR NO PLATE CIVER	new		15.00	15.00	S/NETT x
1	PC REAR WINDSCREEN MOULDING	new		86.70	86.70	✓
1	PC REAR WINDSCREEN SEALANT	new		45.00	45.00	S/NETT ✓
1	PC REAR WINDSCREEN INNER SEAL	new		26.00	26.00	S/NETT ✓

TO CHECK WIRING.
TO TOP-UP AIR-CON GAS.
TO SPRAY PAINTING.
TO WHEEL ALIGHTMENT.
TO REMOVE & REFIX FRONT UNDER CARRIAGE
TO CONDUCT CHASSIC ALIGHTMENT & MEASUREMENT.
TO CHECK AND TEST RADIATOR PRESSURE TEST.
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED
PANEL FOR RUST PROTECTION.

TO LABOUR CHARGES FOR PANEL BEATING, WELDING,
REMOVING ALL DAMAGED PARTS AND REPLACING OF
THE NEW PARTS ETC.

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL AMOUNT S\$

3.8k

9,412.50

total: 4729.37

L/s: 3.8k

06 Days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002205/ATD3N2

Date: 16/07/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTMC01004769
Claimant Vehicle No :	SJP3840U	Insured Vehicle No :	FBH3875G
Date of Loss:	01/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900713

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP3840U	Engine No:	1ZZ3239066
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12W903002976
Reg. Date:	23/03/2009 (Man. Year: 2009)	Odometer:	184599 km
Colour:	White		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,062.50	2,914.37	3,148.13	51.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,860.00	1,490.00	44.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,412.50	4,774.37	4,638.13	49.28
Approved Total (Overridden) (\$\$)		3,800.00		
Nett Amount (\$\$)	9,412.50	3,800.00	5,612.50	59.63

INSPECTION

Date of Assignment:	07/02/2019	
Date Inspected:	12/02/2019	Inspected At:
		Tk Motor Workshop (HQ)
		Blk 1 Kaki Bukit Ave 6 #02-56, Autobay
		@ Kaki Bt
		Singapore 417883

Estimated Period of Repair: 6.0 days**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP3840U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	1,277.20 F	*1,277.20 FL
2	1		*REAR BOOTLID EMBLEM	Necessary	58.50 F	*58.50 FL
3	1		*REAR BOOTLID CHROME MOULDING	Not Necessary	297.10 F	*- FL
4	1		*REAR BOOTLID LOCK	Not Necessary	349.40 F	*- FL
5	1		*REAR BOOTLID RUBBER	Not Necessary	159.40 F	*- FL
6	2		*REAR BOOTLID ABSORBER	Not Necessary	357.80 F	*- FL
7	1		*REAR END PANEL	Dented	578.40 F	*578.40 FL
8	1		*REAR END PANEL GARNISH	Deformed	178.40 F	*178.40 FL
9	1		*REAR BUMPER	Deformed	1,077.20 F	*545.20 FL
10	1		*REAR BUMPER REFLECTOR	Cracked	75.60 F	*75.60 FL
11	1		*REAR BUMPER BRACKET	N/s Dented	149.80 F	*74.90 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	157.20 F	*157.20 FL
13	8		*REAR BUMPER CLIP	Necessary	30.40 F	*30.40 FL
14	2		*REAR BUMPER SIDE CLIP	Necessary	25.60 F	*25.60 FL
15	1		*REAR L/H TAILLAMP	Cracked	509.40 F	*408.00 FL
16	1		*REAR L/H TAILLAMP BRACKET	Damaged	28.40 F	*28.40 FL
17	1		*REAR WINDSCREEN MOULDING	Necessary	86.70 F	*86.70 FL
18	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
19	1		*REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
20	1		*REAR NO PLATE CIVER	Not Necessary	15.00 FS	*- FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*45.00 FS
22	1		*REAR WINDSCREEN INNER SEAL	Necessary	26.00 FS	*26.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,062.50	3,795.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	881.13
Total Parts (\$\$)	6,062.50	2,914.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO TOP-UP AIR-CON GAS	New	100.00	0.00
3	TO SPRAY PAINTING	New	1,200.00	850.00
4	TO WHEEL ALIGHTMENT	New	60.00	0.00
5	TO REMOVE & REFIX FRONT UNDER CARRIAGE	New	380.00	0.00
6	TO CONDUCT CHASSIS ALIGHTMENT & MEASUREMENT	New	280.00	0.00
7	TO CHECK AND TEST RADIATOR PRESSURE TEST	New	100.00	0.00
8	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	New	180.00	80.00
9	TO LABOUR CHARGE FOR PANEL BEATING,WELDING,REMOVING ALL DAMAGED PARTS AND REPLACING OF THE NEW PARTS ETC	New	1,000.00	900.00
Gross Labour Cost (\$\$)			3,350.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >