

REF: SMO

7154F

Date 7/2/2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

SLV 163E

at Work Shop no

Performance Motor
303 Alexandra Road

Insured

Policy No

Client's No

Sum Insured

Excess:

78A \$600/

(Client's Record)

Make of Veh

Joseph @ 91165199

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value

146k

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs

days

Res: Yes or No

Est. Sum

%

3 Val: Yes or No

CA (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date

Person Contacted

Veh No SLV 163E

Yr Regn 2017 Jun

Type M/Cat / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make B.M.W X5

cc 1998

Colour WHITE

A/C Insured / Std / Nil / NA

Sp Reading 32653

T/Radio Insured / Std / Nil / NA

Eng No

C/No WBALS020300U16402

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mork: Nil / S/Rim / STD A/Rim or

Tyre Size F:

285/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal 6 mm

R/Bal 6 mm

L/Bal 6 mm

L/Bal 6 mm

D.O.A. 02/02/19

D.O.I. 07/02/19

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

18/03/19 @ 10:57 a.m. received IA to
 @ 6 days with Result.
 (\$ 3,245.40 Red. 16%)

Confirmed P/P \$ 17,583.45

18/3/2019

RECEIVED 8 MAR 2019

Date/Time File Pass to

20/03/19

Type

Date/Time File Return to



Preli. Report



Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee

Transportation

T. S. & P. S.

J. H. & S.

V. H. & S.

J. S. & P. S.

Total

Add Fee:



Site Insp \$



Intervew \$



Tech. Insp \$



Workshop \$

Report Format

Lump Sum / L.B.F. \$

17,583.45 P/P

450

10

460