

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 11 Feb 2019

**Preliminary Advice**

Insured Vehicle No	: SLU2711R	Accident Date	: 04/02/2019
TP Vehicle No	: SDS3338J	Assignment Date	: 08/02/2019
Make	: BMW 528I	Est. Duration of Repair	: 7-9.00
Date of Inspection	: 08/02/2019		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,078.10
Revised Amount	:S\$	15,077.70
Check Items (Estimated)	:S\$	13,114.35
Total	:S\$	28,192.05

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :The above survey was conducted on a 'Without Prejudice' basis.